

# MAPPED SITES SUMMARY

Target Property Address:  
LEY CREEK LAND  
SYRACUSE, NY 13206

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
<a href="#">LM2338</a>	CELLCO - JAMES STREE	989 JAMES STREET SYR	ICIS, FINDS, ECHO	Higher	11082, 2.099, SSW
<a href="#">LQ2339</a>	BILL RAPP PONTIAC	3449 BARNET AVE	US AIRS	Higher	11085, 2.099, SE
<a href="#">2340</a>	MILLION AIR HANGAR	442 COLONEL EILEEN C	FINDS	Higher	11096, 2.102, NNW
<a href="#">LN2341</a>	337 RIEGEL AVE.	337 RIEGEL AVE	NY LTANKS	Higher	11101, 2.102, South
<a href="#">LN2342</a>	MC'S + FIELDS TOWING	337 RIEGEL STREET	NY SWF/LF, NY Spills	Higher	11101, 2.102, South
<a href="#">LM2343</a>	WTVH-TV	980 JAMES ST	FTTS, HIST FTTS	Higher	11111, 2.104, SSW
<a href="#">LM2344</a>	WTVH-TV	980 JAMES ST	FINDS	Higher	11111, 2.104, SSW
<a href="#">LV2345</a>	COOPER-CROUSE-HINDS	WOLF & SEVENTH NORTH	NY AIRS	Higher	11119, 2.106, West
<a href="#">LV2346</a>	COOPER CROUSE-HINDS	WOLF & 7TH NORTH ST	NY TANKS, NY MANIFEST, NY SPDES	Higher	11119, 2.106, West
<a href="#">LI2347</a>	CLARK CONCRETE TRUCK	1400 BURNETT AVE	NY Spills	Higher	11122, 2.106, South
<a href="#">LW2348</a>	NATIONAL CAR RENTAL	SYRACUSE AIRPORT	NY LTANKS	Higher	11153, 2.112, North
<a href="#">LW2349</a>	HERTZ RENT-A-CAR	SYRACUSE HANCOCK AIR	NY Spills	Higher	11153, 2.112, North
<a href="#">LX2350</a>	5000 CAMPUS WOOD PL	5000 CAMPUS WOOD PL	NY Spills	Higher	11161, 2.114, East
<a href="#">LX2351</a>		5000 CAMPUSWOOD DR	NY COOLING TOWERS	Higher	11161, 2.114, East
<a href="#">LY2352</a>	SUNOCO ROUTE 11	ROUTE 11	NY Spills	Higher	11165, 2.115, NW
<a href="#">LZ2353</a>	GERACE GULF SERVICE	422 KINNE ST	EDR Hist Auto	Higher	11167, 2.115, ESE
<a href="#">LZ2354</a>	JOHN'S SERVICE	422 KINNE STREET	NY UST, NY AST, NY Spills	Higher	11167, 2.115, ESE
<a href="#">MA2355</a>	KOCHANЕК ROBERT J	219 GRAVES ST	RCRA NonGen / NLR, FINDS, ECHO	Higher	11184, 2.118, SW
<a href="#">MB2356</a>	MIDLER CROSSINGS	107-115-119 131 SIMO	FINDS, ECHO	Higher	11189, 2.119, SSE
<a href="#">MB2357</a>	DPW	MIDLER AND CANAL ST	NY Spills	Higher	11190, 2.119, SSE
<a href="#">2358</a>	NUT SHELL	303 W MOLLOY RD	EDR Hist Auto	Higher	11192, 2.120, WNW
<a href="#">2359</a>	BRISTOL LABS - LEY C	LEY CREEK AT BRISTOL	NY Spills	Higher	11193, 2.120, SE
<a href="#">2360</a>	VILLAGE DECORATION L	CORPORATE CIR	FINDS, ECHO	Higher	11194, 2.120, NE
<a href="#">MB2361</a>	LOWES - #2380 SYRACU	131 SIMON DRIVE	PA MANIFEST	Higher	11194, 2.120, SSE
<a href="#">MB2362</a>	LOWES HOME IMPROVEME	131 SIMON DR	NY Spills	Higher	11194, 2.120, SSE
<a href="#">MB2363</a>	PARKING LOT	131 SIMON DRIVE	NY Spills	Higher	11194, 2.120, SSE
<a href="#">MB2364</a>	LOWES OF SYRACUSE NY	131 SIMON DR	RCRA-SQG, FINDS, ECHO, NY MANIFEST	Higher	11194, 2.120, SSE
<a href="#">MB2365</a>	LOWES STORE 2380	131 SIMON DRIVE	NY Spills	Higher	11194, 2.120, SSE
<a href="#">MB2366</a>	LOWE'S OF SYRACUSE N	131 SIMON DR	NY AST	Higher	11194, 2.120, SSE
<a href="#">LX2367</a>	CARRIER CORP.-CARLYL	CARLYLE-COMPRESSOR	NY Spills	Higher	11195, 2.120, East
<a href="#">LX2368</a>	APEX STRIPING INC	NEW VENTURE GEAR DR	NY SHWS, NY SWF/LF, NY ENG CONTROLS, NY INST...	Higher	11195, 2.120, East
<a href="#">LX2369</a>	UNITED TECHNOLOGIES	6500 CHRYSLER DRIVE	NY MANIFEST	Higher	11195, 2.120, East
<a href="#">LX2370</a>	CARRIER-CARLYLE COMP	6500 NEW VENTURE GEA	NY RGA HWS	Higher	11195, 2.120, East
<a href="#">LX2371</a>	FASTRAC MARKETS LLC	6500 NEW VENTURE GEA	EDR Hist Auto	Higher	11195, 2.120, East
<a href="#">LX2372</a>	CARLYLE COMPRESSOR C	6500 CHRYSLER DR	RCRA NonGen / NLR, FTTS, HIST FTTS	Higher	11195, 2.120, East
<a href="#">LX2373</a>	CARRIER CIRCLE BUSIN	6500 NEW VENTURE GEA	NY UST	Higher	11195, 2.120, East
<a href="#">LX2374</a>	CARRIER CORP	6500 CHRYSLER DR	NY LTANKS, NY Spills	Higher	11195, 2.120, East
<a href="#">LX2375</a>	CARRIER CORP. CARLYL	6500 CHRYSLER DR	FINDS	Higher	11195, 2.120, East
<a href="#">LX2376</a>	CARRIER-CARLYLE COMP	6500 NEW VENTURE GEA	NY VAPOR REOPENED	Higher	11195, 2.120, East

# MAPPED SITES SUMMARY

Target Property Address:  
LEY CREEK LAND  
SYRACUSE, NY 13206

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
<a href="#">LX2377</a>	FASTRAC PROPERTIES I	6500 NEW VNTR GR DR	EDR Hist Auto	Higher	11195, 2.120, East
<a href="#">LX2378</a>	CARLYLE COMPRESSOR C	6500 CHRYSLER DR	NY AIRS	Higher	11195, 2.120, East
<a href="#">LX2379</a>	CARRIER CORP	6500 NEW VENTURE GEA	NY Spills	Higher	11195, 2.120, East
<a href="#">LX2380</a>	CARRIER CIRCLE BUSIN	6500 NEW VENTURE GEA	NY AST	Higher	11195, 2.120, East
<a href="#">LX2381</a>	CARRIER CORP CARLYLE	6500 CHRYSLER DR	FINDS, ECHO	Higher	11195, 2.120, East
<a href="#">LX2382</a>	ADVANCED MOTORS & DR	6500 NEW VENTURE DEA	FINDS, ECHO	Higher	11195, 2.120, East
<a href="#">LX2383</a>	SULLIVAN, BAZINET, B	6500 NEW VENTURE GEA	FINDS	Higher	11195, 2.120, East
<a href="#">MC2384</a>	VERIZON WIRELESS MSC	132 CREEK CIRCLE	NY TANKS	Higher	11210, 2.123, East
<a href="#">MD2385</a>		6000 THOMPSON RD	ERNS	Higher	11217, 2.124, SE
<a href="#">MD2386</a>	BRISTOL-MYERS SQUIBB	6000 THOMPSON RD	FINDS	Higher	11217, 2.124, SE
<a href="#">MD2387</a>		6000 THOMPSON ROAD	ERNS	Higher	11217, 2.124, SE
<a href="#">MD2388</a>	BRISTOL-MYERS SQUIBB	THOMPSON RD	NY Spills, NY MANIFEST	Higher	11217, 2.124, SE
<a href="#">MD2389</a>		6000 THOMPSON RD	NY COOLING TOWERS	Higher	11217, 2.124, SE
<a href="#">MD2390</a>		6000 THOMPSON ROAD	ERNS	Higher	11217, 2.124, SE
<a href="#">MD2391</a>		6000 THOMPSON RD.	ERNS	Higher	11217, 2.124, SE
<a href="#">MD2392</a>	BRISTOL-MYERS SQUIBB	6000 THOMPSON ROAD	ICIS	Higher	11217, 2.124, SE
<a href="#">MD2393</a>		6000 THOMPSON RD	ERNS	Higher	11217, 2.124, SE
<a href="#">MD2394</a>		6000 THOMPSON RD	ERNS	Higher	11217, 2.124, SE
<a href="#">MD2395</a>		6000 THOMPSON RD	NY COOLING TOWERS	Higher	11217, 2.124, SE
<a href="#">MD2396</a>		6000 THOMPSON RD	NY COOLING TOWERS	Higher	11217, 2.124, SE
<a href="#">MD2397</a>	BMS SYRACUSE NORTH C	6000 THOMPSON ROAD	NY LTANKS, NY CBS, NY BROWNFIELDS, NY Spills, NY...	Higher	11217, 2.124, SE
<a href="#">MD2398</a>		6000 THOMPSON RD	NY COOLING TOWERS	Higher	11217, 2.124, SE
<a href="#">MD2399</a>		6000 THOMPSON RD	NY COOLING TOWERS	Higher	11217, 2.124, SE
<a href="#">MD2400</a>		6000 THOMPSON RD	NY COOLING TOWERS	Higher	11217, 2.124, SE
<a href="#">MD2401</a>		6000 THOMPSON RD	NY COOLING TOWERS	Higher	11217, 2.124, SE
<a href="#">MD2402</a>	BRISTOL-MYERS SQUIBB	6000 THOMPSON RD	TRIS	Higher	11217, 2.124, SE
<a href="#">MD2403</a>	BRISTOL-MYERS SQUIBB	6000 THOMPSON ROAD	NY CBS UST, NY CBS AST	Higher	11217, 2.124, SE
<a href="#">MD2404</a>		6000 THOMPSON RD	NY COOLING TOWERS	Higher	11217, 2.124, SE
<a href="#">MD2405</a>	BRISTOL LABS	6000 THOMPSON ROAD (	NY RGA HWS	Higher	11217, 2.124, SE
<a href="#">MD2406</a>	BRISTOL-MYERS SQUIBB	6000 THOMPSON ROAD	RMP, FINDS, ECHO	Higher	11217, 2.124, SE
<a href="#">MD2407</a>		6000 THOMPSON RD	ERNS	Higher	11217, 2.124, SE
<a href="#">MD2408</a>		6000 THOMPSON RD	NY COOLING TOWERS	Higher	11217, 2.124, SE
<a href="#">MD2409</a>		6000 THOMPSON RD	NY COOLING TOWERS	Higher	11217, 2.124, SE
<a href="#">MD2410</a>		6000 THOMPSON RD	NY COOLING TOWERS	Higher	11217, 2.124, SE
<a href="#">MD2411</a>		6000 THOMPSON RD	NY COOLING TOWERS	Higher	11217, 2.124, SE
<a href="#">MD2412</a>	BRISTOL-MYERS SQUIBB	6000 THOMPSON ROAD	NY UST	Higher	11217, 2.124, SE
<a href="#">MD2413</a>	SOUTH LEY CREEK	6000 THOMPSON ROAD	NY Spills	Higher	11217, 2.124, SE
<a href="#">MD2414</a>	BRISTOL MYERS	THOMPSON RD	SEMS-ARCHIVE, RCRA-LQG, NY LTANKS, ICIS, US AIRS,...	Higher	11217, 2.124, SE
<a href="#">MD2415</a>		6000 THOMPSON RD	NY COOLING TOWERS	Higher	11217, 2.124, SE

# MAPPED SITES SUMMARY

Target Property Address:  
LEY CREEK LAND  
SYRACUSE, NY 13206

Click on Map ID to see full detail.

MAP ID	SITE NAME	ADDRESS	DATABASE ACRONYMS	RELATIVE ELEVATION	DIST (ft. & mi.) DIRECTION
<a href="#">LY2455</a>	CROSBY DAIRY PRODUCT	OLEAN-HINSDALE HGWY	NY UST	Higher	11314, 2.143, NW
<a href="#">MI2456</a>	US AIR FUEL STORAGE	HANCOCK INTERNATIONAL	NY MOSF AST	Higher	11323, 2.145, NNW
<a href="#">MI2457</a>	USAIR MAINTENANCE	HANCOCK AIRPORT	NY LTANKS, RCRA NonGen / NLR, NY MANIFEST	Higher	11323, 2.145, NNW
<a href="#">MJ2458</a>	I/A/O 210 JOHN ST	I/A/O 210 JOHN ST	NY Spills	Higher	11333, 2.146, SW
<a href="#">MK2459</a>	RICHELIEU AMERICA LT	1216 CANAL ST	NY MANIFEST	Higher	11339, 2.148, South
<a href="#">MK2460</a>	WOODLAND SPECIALTIES	1216 CANAL	NY Spills	Higher	11339, 2.148, South
<a href="#">MK2461</a>	RICHELIEU AMERICA LT	1216 CANAL ST	RCRA-LQG, FINDS, ECHO	Higher	11339, 2.148, South
<a href="#">ML2462</a>	CARRIER CORP	THOMPSON ROAD	NY AST, NY Spills	Higher	11340, 2.148, East
<a href="#">ML2463</a>	CARRIER CORP TCE	BLDG 10R19 CARRIER C	NY Spills	Higher	11340, 2.148, East
<a href="#">ML2464</a>	CARRIER	CARRIER PARKWAY	NY Spills	Higher	11340, 2.148, East
<a href="#">ML2465</a>	CARRIER CORP	BUILDING TR 20	NY Spills	Higher	11340, 2.148, East
<a href="#">ML2466</a>	CARRIER CORPORATION	CARRIER PARKWAY	NY Spills	Higher	11340, 2.148, East
<a href="#">ML2467</a>	CARRIER CORP	PO BOX 4808	NY Spills	Higher	11340, 2.148, East
<a href="#">ML2468</a>	CARRIER CORP.	THOMPSON RD.	NY Spills	Higher	11340, 2.148, East
<a href="#">ML2469</a>	CARRIER CORPORATION	CHRYSLER DRIVE LAB	NY Spills	Higher	11340, 2.148, East
<a href="#">ML2470</a>	TR2	CARRIER PARKWAY	NY Spills	Higher	11340, 2.148, East
<a href="#">ML2471</a>	BRISTOL MYERS	THOMPSON ROAD	NY Spills	Higher	11340, 2.148, East
<a href="#">ML2472</a>	CARRIER CIRCLE SUNOC	THOMPSON ROAD/CARRIE	NY Spills	Higher	11340, 2.148, East
<a href="#">ML2473</a>	CARLISLE COMPRESSOR	CHRYSLER DRIVE	NY Spills	Higher	11340, 2.148, East
<a href="#">ML2474</a>	TR2 PLANT CARRIER	THOMPSON ROAD	NY Spills	Higher	11340, 2.148, East
<a href="#">ML2475</a>	CARRIER CORPORATION	THOMPSON ROAD	NY Spills	Higher	11340, 2.148, East
<a href="#">ML2476</a>	OUTSIDE CARRIER PLAN	CARRIER PARKWAY	NY Spills	Higher	11340, 2.148, East
<a href="#">ML2477</a>	CARRIER CORP	CARRIER PARKWAY	NY Spills	Higher	11340, 2.148, East
<a href="#">ML2478</a>	CARLYLE COMP PLANT	6500 NEW PROCESS GEA	NY Spills	Higher	11340, 2.148, East
<a href="#">ML2479</a>	CARRIER CORP	CARRIER PARKWAY	NY Spills	Higher	11340, 2.148, East
<a href="#">ML2480</a>	SOUTH OF BLDG TR-3	THOMPSON ROAD	NY Spills	Higher	11340, 2.148, East
<a href="#">ML2481</a>	CARRIER CORP.	BEHIND TR1 & TR2	NY Spills	Higher	11340, 2.148, East
<a href="#">ML2482</a>	CARRIER PLANT	CARRIER PARKWAY	NY Spills	Higher	11340, 2.148, East
<a href="#">ML2483</a>	THOMPSON ROAD	BY THE CARRIER CORPO	NY Spills	Higher	11340, 2.148, East
<a href="#">ML2484</a>	CARRIER CORP	NEW VENTURE GEAR DR	NY Spills	Higher	11340, 2.148, East
<a href="#">ML2485</a>	SAUNDERS CREEK	CHRYSLER DR - CARLIS	NY Spills	Higher	11340, 2.148, East
<a href="#">ML2486</a>	CARRIER CORP. TANKS	KINNE ST	NY Spills	Higher	11340, 2.148, East
<a href="#">ML2487</a>	CARRIER CORP.	CARRIOR CORP.	NY Spills	Higher	11340, 2.148, East
<a href="#">ML2488</a>	CARRIER CORP.	CARRIER CORP	NY Spills	Higher	11340, 2.148, East
<a href="#">ML2489</a>	CARRIER CORPORATION	CARRIER PARKWAY	NY Spills	Higher	11340, 2.148, East
<a href="#">ML2490</a>	THOMPSON RD FACILITY	CARRIER PARKWAY	NY Spills	Higher	11340, 2.148, East
<a href="#">ML2491</a>	CARRIER CORP.	TR-4 WEST SIDE	NY Spills	Higher	11340, 2.148, East
<a href="#">ML2492</a>	CARRIER CORP	CARRIER CORP	NY Spills	Higher	11340, 2.148, East
<a href="#">ML2493</a>	CARRIER CAMPUS	CARRIER PARKWAY	NY Spills	Higher	11340, 2.148, East

## EXECUTIVE SUMMARY

Spill Number/Closed Date: 8606616 / 1987-09-11				
MIDLER INDUSTRIAL PA	MIDLER INDUSTRIAL PA	SSE >2 (2.003 mi.)	2152	512
Site ID: 145157				
Spill Number/Closed Date: 9408171 / 1994-09-21				
BOB FETHERLY'S GARAG	701 WEST MANLIUS ST	SE >2 (2.026 mi.)	KF2193	522
Site ID: 131987				
Spill Number/Closed Date: 0109432 / 2003-10-23				
NATIONAL CAR RENTAL	NORTH ACCESS ROAD	N >2 (2.031 mi.)	LE2217	527
Site ID: 201845				
Spill Number/Closed Date: 9909479 / 2002-12-02				
HERTZ RENTAL AT SYRA	168 CONSTELLATION	N >2 (2.052 mi.)	LE2269	539
Site ID: 503051				
Spill Number/Closed Date: 1409431 / 2015-03-02				
SYRACUSE RIGGING	PEAT STREET/GREENWAY	S >2 (2.086 mi.)	LR2321	550
Site ID: 330594				
Spill Number/Closed Date: 9413575 / 1995-01-12				
337 RIEGEL AVE.	337 RIEGEL AVE	S >2 (2.102 mi.)	LN2341	555
Site ID: 134623				
Spill Number/Closed Date: 9211478 / 1993-07-28				
NATIONAL CAR RENTAL	SYRACUSE AIRPORT	N >2 (2.112 mi.)	LW2348	556
Site ID: 231773				
Spill Number/Closed Date: 9600538 / 1996-05-06				
<b>CARRIER CORP</b>	<b>6500 CHRYSLER DR</b>	<b>E &gt;2 (2.120 mi.)</b>	<b>LX2374</b>	<b>562</b>
Site ID: 211667				
Spill Number/Closed Date: 9700279 / 1997-06-30				
<b>BMS SYRACUSE NORTH C</b>	<b>6000 THOMPSON ROAD</b>	<b>SE &gt;2 (2.124 mi.)</b>	<b>MD2397</b>	<b>567</b>
Site ID: 160461				
Site ID: 286677				
Site ID: 286684				
Spill Number/Closed Date: 9415717 / 1995-03-06				
Spill Number/Closed Date: 0013038 / 2001-04-20				
Spill Number/Closed Date: 0400187 / 2004-12-28				
<b>BRISTOL MYERS</b>	<b>THOMPSON RD</b>	<b>SE &gt;2 (2.124 mi.)</b>	<b>MD2414</b>	<b>572</b>
Site ID: 188958				
Spill Number/Closed Date: 8904167 / 1989-07-26				
<b>CONRAIL MAINT SHOP</b>	<b>342 PEAT STREET</b>	<b>S &gt;2 (2.141 mi.)</b>	<b>MH2438</b>	<b>578</b>
Site ID: 239107				
Spill Number/Closed Date: 9107749 / 1991-11-04				
<b>SYRACUSE DPW DIESEL</b>	<b>1200 CANAL ST EXT</b>	<b>S &gt;2 (2.142 mi.)</b>	<b>MH2447</b>	<b>580</b>
Site ID: 441903				
Site ID: 301626				
Site ID: 193574				
Spill Number/Closed Date: 1008412 / 2011-01-03				
Spill Number/Closed Date: 9711008 / 1998-01-05				
Spill Number/Closed Date: 0111943 / 2003-10-31				
<b>USAIR MAINTENANCE</b>	<b>HANCOCK AIRPORT</b>	<b>NNW &gt;2 (2.145 mi.)</b>	<b>MI2457</b>	<b>582</b>
Site ID: 186247				
Spill Number/Closed Date: 8500850 / 1991-04-15				
BRISTOL LABS	BRISTOL LABS	SE >2 (2.160 mi.)	MD2525	599
Site ID: 104484				

## EXECUTIVE SUMMARY

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
KEITH'S PETROLEUM Database: UST, Date of Government Version: 02/11/2019	101 DEPOT ST	WSW 1 - 2 (1.902 mi.)	JG1966	469
CARRIER INTERNATIONAL Database: UST, Date of Government Version: 02/11/2019	6666 KINNE STREET	ENE 1 - 2 (1.904 mi.)	IX1970	470
ELEANOR B. HAYMAN Database: UST, Date of Government Version: 02/11/2019	2510-12 BURNET AVE	SSE 1 - 2 (1.927 mi.)	JP1992	475
THOMPSON RD MOVING & Database: UST, Date of Government Version: 02/11/2019	310 THOMPSON RD	SE 1 - 2 (1.938 mi.)	JU2019	482
NYNEX ENTERPRISES Database: UST, Date of Government Version: 02/11/2019	320 THOMPSON ROAD	SE 1 - 2 (1.948 mi.)	JU2035	486
18 CORPORATE CIRCLE Database: UST, Date of Government Version: 02/11/2019	18 CORPORATE CIRCLE	NE 1 - 2 (1.967 mi.)	JJ2051	489
BANK OF NEW YORK MEL Database: UST, Date of Government Version: 02/11/2019	111 SANDERS CREEK PA	E 1 - 2 (1.972 mi.)	KH2062	492
<b>FEDERAL AVIATION ADM</b> Database: UST, Date of Government Version: 02/11/2019	<b>HANCOCK AIRPORT</b>	<b>N 1 - 2 (1.972 mi.)</b>	<b>JZ2064</b>	<b>492</b>
<b>ADVANCED AUTOMOTIVE</b> Database: UST, Date of Government Version: 02/11/2019	<b>2616 BREWERTON RD</b>	<b>NW 1 - 2 (1.973 mi.)</b>	<b>KI2065</b>	<b>492</b>
KILIAN MANUFACTURING Database: UST, Date of Government Version: 02/11/2019	1728 BURNET AVE	S 1 - 2 (1.975 mi.)	KA2072	494
ST ANTHONY CONVENT Database: UST, Date of Government Version: 02/11/2019	1024 COURT ST	WSW 1 - 2 (1.992 mi.)	KB2123	505
HANCOCK AIRPORT Database: UST, Date of Government Version: 02/11/2019	1099 AIRPORT BLVD	N >2 (2.020 mi.)	KQ2179	518
CARMEN'S AUTOMOTIVE Database: UST, Date of Government Version: 02/11/2019	1224 WOLF ST	W >2 (2.029 mi.)	KN2205	524
SPEEDWAY #9947 Database: UST, Date of Government Version: 02/11/2019	6396 EAST MOLLOY RD	ENE >2 (2.030 mi.)	LC2206	524
NATIONAL CAR RENTAL Database: UST, Date of Government Version: 02/11/2019	137 CONSTELLATION WA	N >2 (2.036 mi.)	LE2221	528
FORMER VALVOLINE INS Database: UST, Date of Government Version: 02/11/2019	2700 BREWERTON RD	NW >2 (2.038 mi.)	LF2234	531
AVIS RENT A CAR SYST Database: UST, Date of Government Version: 02/11/2019	146 CONSTELLATION WA	N >2 (2.042 mi.)	LE2249	534
HERTZ RENT-A-CAR (17 Database: UST, Date of Government Version: 02/11/2019	168 CONSTELLATION WA	N >2 (2.052 mi.)	LE2268	539
SPEEDWAY #9934 Database: UST, Date of Government Version: 02/11/2019	2723 BREWERTON RD	NW >2 (2.086 mi.)	LF2315	549
BEST BUY AUTO Database: UST, Date of Government Version: 02/11/2019	6410 COLLAMER RD	ENE >2 (2.086 mi.)	LO2323	550
BILL RAPP INC Database: UST, Date of Government Version: 02/11/2019	3449 BURNET AVE	SE >2 (2.098 mi.)	LQ2336	554
<b>JOHN'S SERVICE</b> Database: UST, Date of Government Version: 02/11/2019	<b>422 KINNE STREET</b>	<b>ESE &gt;2 (2.115 mi.)</b>	<b>LZ2354</b>	<b>558</b>
CARRIER CIRCLE BUSIN Database: UST, Date of Government Version: 02/11/2019	6500 NEW VENTURE GEA	E >2 (2.120 mi.)	LX2373	562

## EXECUTIVE SUMMARY

Facility Id: 7-459348				
BANK OF NEW YORK MEL	111 SANDERS CREEK PA	E 1 - 2 (1.972 mi.)	KH2061	492
Database: AST, Date of Government Version: 02/11/2019				
Facility Id: 7-600869				
<b>FEDERAL AVIATION ADM</b>	<b>HANCOCK AIRPORT</b>	<b>N 1 - 2 (1.972 mi.)</b>	<b>JZ2064</b>	<b>492</b>
Database: AST, Date of Government Version: 02/11/2019				
Facility Id: 7-101109				
KILIAN MANUFACTURING	1728 BURNET AVE	S 1 - 2 (1.975 mi.)	KA2078	496
Database: AST, Date of Government Version: 02/11/2019				
Facility Id: 7-003131				
MIDLER CITY INDUSTRI	621 S. MIDLER AVE	SSE >2 (2.015 mi.)	KW2170	516
Database: AST, Date of Government Version: 02/11/2019				
Facility Id: 7-600874				
NATIONAL CAR RENTAL	137 CONSTELLATION WA	N >2 (2.036 mi.)	LE2223	528
Database: AST, Date of Government Version: 02/11/2019				
Facility Id: 7-077321				
FORMER VALVOLINE INS	2700 BREWERTON RD	NW >2 (2.038 mi.)	LF2235	531
Database: AST, Date of Government Version: 02/11/2019				
Facility Id: 7-600389				
PASCARELLA'S TOWING	1504 BURNET AVE	S >2 (2.040 mi.)	KY2246	534
Database: AST, Date of Government Version: 02/11/2019				
Facility Id: 7-601202				
AVIS RENT A CAR SYST	146 CONSTELLATION WA	N >2 (2.042 mi.)	LE2248	534
Database: AST, Date of Government Version: 02/11/2019				
Facility Id: 7-140031				
CENTURYLINK - SYRACU	1214 WOLF ST	W >2 (2.046 mi.)	KT2256	536
Database: AST, Date of Government Version: 02/11/2019				
Facility Id: 7-600825				
HERTZ RENT-A-CAR (17	168 CONSTELLATION WA	N >2 (2.052 mi.)	LE2270	539
Database: AST, Date of Government Version: 02/11/2019				
Facility Id: 7-459232				
COURTESY FORD, INC.	2724 BREWERTON RD	NW >2 (2.070 mi.)	LF2290	543
Database: AST, Date of Government Version: 02/11/2019				
Facility Id: 7-600915				
SPEEDWAY #9934	2723 BREWERTON RD	NW >2 (2.086 mi.)	LF2317	549
Database: AST, Date of Government Version: 02/11/2019				
Facility Id: 7-300926				
<b>BILL RAPP PONTIAC &amp;</b>	<b>3449 BURNET AVE</b>	<b>SE &gt;2 (2.098 mi.)</b>	<b>LQ2335</b>	<b>553</b>
Database: AST, Date of Government Version: 02/11/2019				
Facility Id: 7-491365				
<b>JOHN'S SERVICE</b>	<b>422 KINNE STREET</b>	<b>ESE &gt;2 (2.115 mi.)</b>	<b>LZ2354</b>	<b>558</b>
Database: AST, Date of Government Version: 02/11/2019				
Facility Id: 7-186066				
LOWE'S OF SYRACUSE N	131 SIMON DR	SSE >2 (2.120 mi.)	MB2366	560
Database: AST, Date of Government Version: 02/11/2019				
Facility Id: 7-601194				
CARRIER CIRCLE BUSIN	6500 NEW VENTURE GEA	E >2 (2.120 mi.)	LX2380	564
Database: AST, Date of Government Version: 02/11/2019				
Facility Id: 7-123927				
BRISTOL-MYERS SQUIBB	6000 THOMPSON ROAD	SE >2 (2.124 mi.)	MD2416	572
Database: AST, Date of Government Version: 02/11/2019				

## EXECUTIVE SUMMARY

Site ID: 365217 Spill Number/Closed Date: 0602677 / 2006-11-08				
POLE # 22-1	404 OAK ST	SSW >2 (2.092 mi.)	2330	552
Site ID: 437403 Spill Number/Closed Date: 1004144 / 2010-07-14				
RESIDENT	1420 BURNET AVENUE	S >2 (2.095 mi.)	LI2331	552
Site ID: 85619 Spill Number/Closed Date: 9960009 / 2002-06-03				
<b>BILL RAPP PONTIAC &amp;</b>	<b>3449 BURNET AVE</b>	<b>SE &gt;2 (2.098 mi.)</b>	<b>LQ2335</b>	<b>553</b>
Site ID: 101441 Spill Number/Closed Date: 0260055 / 2003-11-05				
<b>MC'S + FIELDS TOWING</b>	<b>337 RIEGEL STREET</b>	<b>S &gt;2 (2.102 mi.)</b>	<b>LN2342</b>	<b>555</b>
Site ID: 522289 Spill Number/Closed Date: 1510600 / 2016-02-01				
CLARK CONCRETE TRUCK	1400 BURNETT AVE	S >2 (2.106 mi.)	LI2347	556
Site ID: 303612 Spill Number/Closed Date: 9006663 / 1991-03-26				
HERTZ RENT-A-CAR	SYRACUSE HANCOCK AIR	N >2 (2.112 mi.)	LW2349	557
Site ID: 145633 Spill Number/Closed Date: 8601426 / 2018-04-30				
5000 CAMPUS WOOD PL	5000 CAMPUS WOOD PL	E >2 (2.114 mi.)	LX2350	557
Site ID: 280253 Spill Number/Closed Date: 0300483 / 2003-04-14				
SUNOCO ROUTE 11	ROUTE 11	NW >2 (2.115 mi.)	LY2352	557
Site ID: 82000 Spill Number/Closed Date: 8807090 / 1989-03-03				
<b>JOHN'S SERVICE</b>	<b>422 KINNE STREET</b>	<b>ESE &gt;2 (2.115 mi.)</b>	<b>LZ2354</b>	<b>558</b>
Site ID: 195568 Spill Number/Closed Date: 9608441 / 1996-10-31				
DPW	MIDLER AND CANAL ST	SSE >2 (2.119 mi.)	MB2357	558
Site ID: 228226 Spill Number/Closed Date: 9001945 / 1990-06-05				
BRISTOL LABS - LEY C	LEY CREEK AT BRISTOL	SE >2 (2.120 mi.)	2359	559
Site ID: 328125 Spill Number/Closed Date: 8700177 / 1987-04-07				
LOWES HOME IMPROVEME	131 SIMON DR	SSE >2 (2.120 mi.)	MB2362	559
Site ID: 482254 Spill Number/Closed Date: 1301845 / 2013-06-25				
PARKING LOT	131 SIMON DRIVE	SSE >2 (2.120 mi.)	MB2363	560
Site ID: 493649 Spill Number/Closed Date: 1400412 / 2014-04-13				
LOWES STORE 2380	131 SIMON DRIVE	SSE >2 (2.120 mi.)	MB2365	560
Site ID: 530987 Spill Number/Closed Date: 1604479 / 2016-08-03				
CARRIER CORP.-CARLYL	CARLYLE-COMPRESSOR	E >2 (2.120 mi.)	LX2367	561
Site ID: 155748 Spill Number/Closed Date: 8703556 / 1987-12-22				
<b>CARRIER CORP</b>	<b>6500 CHRYSLER DR</b>	<b>E &gt;2 (2.120 mi.)</b>	<b>LX2374</b>	<b>562</b>
Site ID: 331247				

## EXECUTIVE SUMMARY

Spill Number/Closed Date: 9902482 / 1999-07-02				
CARRIER CORP	6500 NEW VENTURE GEA	E >2 (2.120 mi.)	LX2379	563
Site ID: 129847				
Spill Number/Closed Date: 9911037 / 1999-12-20				
<b>BRISTOL-MYERS SQUIBB</b>	<b>THOMPSON RD</b>	<b>SE &gt;2 (2.124 mi.)</b>	<b>MD2388</b>	<b>565</b>
Site ID: 523386				
Spill Number/Closed Date: 1511620 / 2016-03-07				
<b>BMS SYRACUSE NORTH C</b>	<b>6000 THOMPSON ROAD</b>	<b>SE &gt;2 (2.124 mi.)</b>	<b>MD2397</b>	<b>567</b>
Site ID: 446894				
Site ID: 368217				
Site ID: 281141				
Site ID: 286673				
Site ID: 286674				
<i>*Additional key fields are available in the Map Findings section</i>				
Spill Number/Closed Date: 1012699 / 2011-03-21				
Spill Number/Closed Date: 0605112 / 2006-08-31				
Spill Number/Closed Date: 0007940 / 2000-10-18				
Spill Number/Closed Date: 0000854 / 2000-04-27				
Spill Number/Closed Date: 0010938 / 2001-01-30				
<i>*Additional key fields are available in the Map Findings section</i>				
SOUTH LEY CREEK	6000 THOMPSON ROAD	SE >2 (2.124 mi.)	MD2413	571
Site ID: 528708				
Spill Number/Closed Date: 1602307 / 2016-06-07				
EAST SYRACUSE YARD	RAILROAD ST	S >2 (2.126 mi.)	2421	573
Site ID: 171212				
Spill Number/Closed Date: 0100065 / 2001-04-20				
PAVEMENT SOIL	311 BURDOCK AVE	WSW >2 (2.134 mi.)	LP2428	575
Site ID: 577432				
Spill Number/Closed Date: 1806699 / 2018-11-08				
HIGH ASSOCIATION	201 GREENWAY AVE	S >2 (2.134 mi.)	2429	575
Site ID: 232060				
Spill Number/Closed Date: 9408780 / 1996-03-28				
WASHBURN DRIVE	222 WASBURN DRIVE	ESE >2 (2.136 mi.)	2430	575
Site ID: 348090				
Spill Number/Closed Date: 0503470 / 2005-08-08				
HINSDALE RD & BREWER	HINSDALE RD & BREWER	NW >2 (2.137 mi.)	LY2432	576
Site ID: 327351				
Spill Number/Closed Date: 9806724 / 1999-04-26				
NORTHERN LIGHTS MOBI	MOBIL	NW >2 (2.139 mi.)	LY2434	577
Site ID: 305393				
Spill Number/Closed Date: 9413944 / 1995-01-20				
DEWITT YARD	342 PEAT ST	S >2 (2.141 mi.)	MH2437	577
Site ID: 520697				
Site ID: 526382				
Spill Number/Closed Date: 1510046 / 2016-01-14				
Spill Number/Closed Date: 1601077 / 2016-06-28				
<b>CONRAIL MAINT SHOP</b>	<b>342 PEAT STREET</b>	<b>S &gt;2 (2.141 mi.)</b>	<b>MH2438</b>	<b>578</b>
Site ID: 104875				
Spill Number/Closed Date: 8906300 / 1991-06-07				
RAIL YARD	342 PEAT ST	S >2 (2.141 mi.)	MH2441	578



## EXECUTIVE SUMMARY

Site ID: 103306

Site ID: 103307

*\*Additional key fields are available in the Map Findings section*

Spill Number/Closed Date: 9612517 / 1997-01-23

Spill Number/Closed Date: 0002811 / 2000-06-07

Spill Number/Closed Date: 0004936 / 2000-07-31

Spill Number/Closed Date: 0107746 / 2001-11-01

Spill Number/Closed Date: 0202988 / 2002-06-25

*\*Additional key fields are available in the Map Findings section*

CARRIER CORP	BUILDING TR 20	E >2 (2.148 mi.)	ML2465	585
Site ID: 306635				
Spill Number/Closed Date: 9812223 / 1999-01-04				
CARRIER CORPORATION	CARRIER PARKWAY	E >2 (2.148 mi.)	ML2466	585
Site ID: 162028				
Spill Number/Closed Date: 0104020 / 2001-07-19				
CARRIER CORP	PO BOX 4808	E >2 (2.148 mi.)	ML2467	585
Site ID: 154182				
Spill Number/Closed Date: 9908929 / 2000-02-15				
CARRIER CORP.	THOMPSON RD.	E >2 (2.148 mi.)	ML2468	586
Site ID: 251258				
Spill Number/Closed Date: 8601037 / 1987-08-31				
CARRIER CORPORATION	CHRYSLER DRIVE LAB	E >2 (2.148 mi.)	ML2469	586
Site ID: 320440				
Spill Number/Closed Date: 9908891 / 1999-10-25				
TR2	CARRIER PARKWAY	E >2 (2.148 mi.)	ML2470	586
Site ID: 162027				
Spill Number/Closed Date: 0103956 / 2001-09-30				
BRISTOL MYERS	THOMPSON ROAD	E >2 (2.148 mi.)	ML2471	586
Site ID: 327847				
Site ID: 327851				
Site ID: 327854				
Site ID: 327857				
Site ID: 327868				
Spill Number/Closed Date: 0203471 / 2002-07-08				
Spill Number/Closed Date: 8802588 / 1988-06-22				
Spill Number/Closed Date: 8907175 / 1990-01-24				
Spill Number/Closed Date: 8911557 / 1990-04-19				
Spill Number/Closed Date: 9611457 / 1996-12-18				
CARRIER CIRCLE SUNOC	THOMPSON ROAD/CARRIE	E >2 (2.148 mi.)	ML2472	587
Site ID: 98385				
Site ID: 112423				
Spill Number/Closed Date: 8709937 / 1988-02-29				
Spill Number/Closed Date: 9813806 / 1999-02-12				
CARLISLE COMPRESSOR	CHRYSLER DRIVE	E >2 (2.148 mi.)	ML2473	587
Site ID: 273888				
Spill Number/Closed Date: 8804337 / 1988-08-17				
TR2 PLANT CARRIER	THOMPSON ROAD	E >2 (2.148 mi.)	ML2474	587
Site ID: 327880				
Spill Number/Closed Date: 9906843 / 2000-02-16				
CARRIER CORPORATION	THOMPSON ROAD	E >2 (2.148 mi.)	ML2475	587
Site ID: 112411				

## EXECUTIVE SUMMARY

Site ID: 112420 Spill Number/Closed Date: 0110720 / 2002-02-20 Spill Number/Closed Date: 9612775 / 1997-01-28				
OUTSIDE CARRIER PLAN	CARRIER PARKWAY	E >2 (2.148 mi.)	ML2476	588
Site ID: 103299 Spill Number/Closed Date: 0007365 / 2000-09-29				
CARRIER CORP	CARRIER PARKWAY	E >2 (2.148 mi.)	ML2477	588
Site ID: 103309 Spill Number/Closed Date: 0204895 / 2002-08-09				
CARLYLE COMP PLANT	6500 NEW PROCESS GEA	E >2 (2.148 mi.)	ML2478	588
Site ID: 265489 Spill Number/Closed Date: 9911092 / 1999-12-20				
CARRIER CORP	CARRIER PARKWAY	E >2 (2.148 mi.)	ML2479	588
Site ID: 103294 Site ID: 103295 Site ID: 103304 Site ID: 103314 Site ID: 103323 Spill Number/Closed Date: 0000424 / 2000-04-11 Spill Number/Closed Date: 0002752 / 2000-06-06 Spill Number/Closed Date: 0103595 / 2001-10-09 Spill Number/Closed Date: 8911626 / 1990-03-13 Spill Number/Closed Date: 9909816 / 1999-11-13				
SOUTH OF BLDG TR-3	THOMPSON ROAD	E >2 (2.148 mi.)	ML2480	589
Site ID: 112418 Spill Number/Closed Date: 9515340 / 1996-03-01				
CARRIER CORP.	BEHIND TR1 & TR2	E >2 (2.148 mi.)	ML2481	589
Site ID: 179590 Spill Number/Closed Date: 9310987 / 1993-12-10				
CARRIER PLANT	CARRIER PARKWAY	E >2 (2.148 mi.)	ML2482	589
Site ID: 103298 Spill Number/Closed Date: 0005013 / 2000-08-11				
THOMPSON ROAD	BY THE CARRIER CORPO	E >2 (2.148 mi.)	ML2483	589
Site ID: 237294 Spill Number/Closed Date: 9614118 / 1997-03-04				
CARRIER CORP	NEW VENTURE GEAR DR	E >2 (2.148 mi.)	ML2484	589
Site ID: 88219 Spill Number/Closed Date: 0000749 / 2000-05-18				
SAUNDERS CREEK	CHRYSLER DR - CARLIS	E >2 (2.148 mi.)	ML2485	590
Site ID: 75389 Spill Number/Closed Date: 8805672 / 1988-10-06				
CARRIER CORP. TANKS	KINNE ST	E >2 (2.148 mi.)	ML2486	590
Site ID: 129817 Spill Number/Closed Date: 8805910 / 1988-10-21				
CARRIER CORP.	CARRIOR CORP.	E >2 (2.148 mi.)	ML2487	590
Site ID: 77548 Spill Number/Closed Date: 8603172 / 1988-11-28				
CARRIER CORP.	CARRIER CORP	E >2 (2.148 mi.)	ML2488	590
Site ID: 133552 Spill Number/Closed Date: 9500771 / 1995-04-19				
CARRIER CORPORATION	CARRIER PARKWAY	E >2 (2.148 mi.)	ML2489	590

## EXECUTIVE SUMMARY

EPA ID:: NYR000083436				
NEW YORK STATE DEPT	1504 BURNET AVE	S >2 (2.040 mi.)	KY2240	532
EPA ID:: NYP000962779				
<b>VALVOLINE INSTANT OI</b>	<b>2700 BREWERTON RD &amp;</b>	<b>NW &gt;2 (2.040 mi.)</b>	<b>LF2247</b>	<b>534</b>
EPA ID:: NYD986990612				
<b>SEABOARD ATLANTIC GA</b>	<b>6810 KINNE ST</b>	<b>ENE &gt;2 (2.092 mi.)</b>	<b>2327</b>	<b>551</b>
EPA ID:: NYR000105825				
<b>KOCHANЕК ROBERT J</b>	<b>219 GRAVES ST</b>	<b>SW &gt;2 (2.118 mi.)</b>	<b>MA2355</b>	<b>558</b>
EPA ID:: NYR000064873				
<b>APEX STRIPING INC</b>	<b>NEW VENTURE GEAR DR</b>	<b>E &gt;2 (2.120 mi.)</b>	<b>LX2368</b>	<b>561</b>
EPA ID:: NYR000080622				
<b>CARLYLE COMPRESSOR C</b>	<b>6500 CHRYSLER DR</b>	<b>E &gt;2 (2.120 mi.)</b>	<b>LX2372</b>	<b>562</b>
EPA ID:: NYD000688796				
<b>PARE DAWN</b>	<b>906 1ST NORTH ST</b>	<b>WSW &gt;2 (2.130 mi.)</b>	<b>MG2424</b>	<b>574</b>
EPA ID:: NYR000083444				
<b>WOLLER STEVE A</b>	<b>601 HIGHLAND AVE</b>	<b>SW &gt;2 (2.136 mi.)</b>	<b>MA2431</b>	<b>576</b>
EPA ID:: NYR000093658				
<b>PEERLESS ENVIRONMENT</b>	<b>815 KIRKPATRICK ST</b>	<b>WSW &gt;2 (2.138 mi.)</b>	<b>MG2433</b>	<b>576</b>
EPA ID:: NYR000049700				
<b>CONVENIENT FAMILY HE</b>	<b>2804 BREWERTON RD</b>	<b>NW &gt;2 (2.141 mi.)</b>	<b>LY2436</b>	<b>577</b>
EPA ID:: NYD986971364				
<b>USAIR MAINTENANCE</b>	<b>HANCOCK AIRPORT</b>	<b>NNW &gt;2 (2.145 mi.)</b>	<b>MI2457</b>	<b>582</b>
EPA ID:: NYD986893303				
<b>CRISAFULLI ENVIRONME</b>	<b>1200 HAWLEY AVE</b>	<b>SSW &gt;2 (2.150 mi.)</b>	<b>MN2506</b>	<b>594</b>
EPA ID:: NYR000055079				
<b>NORTHERN LIGHTS MOBI</b>	<b>2801 BREWERTON RD</b>	<b>NW &gt;2 (2.153 mi.)</b>	<b>LY2513</b>	<b>596</b>
EPA ID:: NYD013284286				
<b>MOBIL OIL CORP SS #8</b>	<b>2801 BREWERTON RD</b>	<b>NW &gt;2 (2.153 mi.)</b>	<b>LY2514</b>	<b>596</b>
EPA ID:: NYD981564826				
<b>PENSKE AUTO CENTER</b>	<b>2803 BREWERTON RD -</b>	<b>NW &gt;2 (2.154 mi.)</b>	<b>LY2520</b>	<b>597</b>
EPA ID:: NYR000017715				
SAND RD SUBSTATION	SAND RD	NW >2 (2.176 mi.)	MT2549	604
EPA ID:: NYD980783070				
<b>MILLER HARDWARE ABAN</b>	<b>826 BUTTERNUT ST</b>	<b>SW &gt;2 (2.177 mi.)</b>	<b>ME2551</b>	<b>605</b>
EPA ID:: NY0000853572				
<b>ALIBRANDI JOHN G</b>	<b>125 THOMPSON RD</b>	<b>SE &gt;2 (2.178 mi.)</b>	<b>MD2554</b>	<b>605</b>
EPA ID:: NY0000708701				
HANCOCK SUB	E M OLLY RD	NW >2 (2.178 mi.)	MT2555	606
EPA ID:: NYD980782551				
<b>HARRINGTON GRACE</b>	<b>532 CARBON ST</b>	<b>SW &gt;2 (2.187 mi.)</b>	<b>2565</b>	<b>608</b>
EPA ID:: NYR000038307				
<b>PETERS &amp; SONS TAILOR</b>	<b>835 PARK ST</b>	<b>SW &gt;2 (2.188 mi.)</b>	<b>MJ2567</b>	<b>609</b>
EPA ID:: NYD013271549				
<b>A T &amp; T</b>	<b>641 THOMSON RD</b>	<b>SE &gt;2 (2.197 mi.)</b>	<b>MY2580</b>	<b>612</b>
EPA ID:: NYD986968568				
SUNOCO SERVICE STATI	ERIE BLVD E	SSE >2 (2.211 mi.)	NB2593	615

## EXECUTIVE SUMMARY

Docket Number:: T-02-2004-9279

Close Date:: / /

<b>WTVH-TV</b>	<b>980 JAMES ST</b>	<b>SSW &gt;2 (2.104 mi.)</b>	<b>LM2343</b>	<b>555</b>
Database: FTTS INSP, Date of Government Version: 04/09/2009				
<b>CARLYLE COMPRESSOR C</b>	<b>6500 CHRYSLER DR</b>	<b>E &gt;2 (2.120 mi.)</b>	<b>LX2372</b>	<b>562</b>
Database: FTTS INSP, Date of Government Version: 04/09/2009				
<b>CHESTNUT CROSSING</b>	<b>923 JAMES ST</b>	<b>SSW &gt;2 (2.230 mi.)</b>	<b>NJ2635</b>	<b>625</b>
Database: FTTS INSP, Date of Government Version: 04/09/2009				
<b>JAMES PARK EAST APAR</b>	<b>915 JAMES ST</b>	<b>SSW &gt;2 (2.248 mi.)</b>	<b>NJ2684</b>	<b>636</b>
Database: FTTS INSP, Date of Government Version: 04/09/2009				
<b>ALESSANDRO LISI AND</b>	<b>915 JAMES ST</b>	<b>SSW &gt;2 (2.248 mi.)</b>	<b>NJ2687</b>	<b>637</b>
Database: FTTS, Date of Government Version: 04/09/2009				
Docket Number:: T-02-2004-9281				
Close Date:: / /				
<b>THERMOPATCH CORP</b>	<b>2204 ERIE BLVD</b>	<b>S &gt;2 (2.253 mi.)</b>	<b>NN2690</b>	<b>638</b>
Database: FTTS INSP, Date of Government Version: 04/09/2009				
<b>BABBITT BEARINGS, IN</b>	<b>734 BURNET AVE</b>	<b>SSW &gt;2 (2.449 mi.)</b>	<b>QN3166</b>	<b>749</b>
Database: FTTS INSP, Date of Government Version: 04/09/2009				
<b>BABBITT BEARINGS, IN</b>	<b>734 BURNET AVE</b>	<b>SSW &gt;2 (2.449 mi.)</b>	<b>QN3168</b>	<b>750</b>
Database: FTTS INSP, Date of Government Version: 04/09/2009				
<b>BRIARCLIFF ESTATES</b>	<b>300 AUDUBON PARKWAY</b>	<b>SSE &gt;2 (2.459 mi.)</b>	<b>QT3634</b>	<b>833</b>
Database: FTTS INSP, Date of Government Version: 04/09/2009				
<b>CONIFER-COURTYARD AT</b>	<b>708 JAMES ST</b>	<b>SW &gt;2 (2.521 mi.)</b>	<b>RP3817</b>	<b>876</b>
Database: FTTS INSP, Date of Government Version: 04/09/2009				
<b>ROLLING GREEN ESTATE</b>	<b>2005 EAST FAYETTE ST</b>	<b>S &gt;2 (2.554 mi.)</b>	<b>RZ3928</b>	<b>898</b>
Database: FTTS INSP, Date of Government Version: 04/09/2009				
<b>ENSR CONSULTING</b>	<b>6601 KIRKVILLE RD</b>	<b>ESE &gt;2 (2.622 mi.)</b>	<b>TL4109</b>	<b>939</b>
Database: FTTS INSP, Date of Government Version: 04/09/2009				
<b>GALSON RESEARCH CORP</b>	<b>6601 KIRKVILLE RD</b>	<b>ESE &gt;2 (2.622 mi.)</b>	<b>TL4115</b>	<b>941</b>
Database: FTTS INSP, Date of Government Version: 04/09/2009				
Docket Number:: PCB-88-0235				
Close Date:: / /				
<b>TRIAD TECHNOLOGY</b>	<b>105 SPENCER ST</b>	<b>SW &gt;2 (2.667 mi.)</b>	<b>TT4242</b>	<b>970</b>
Database: FTTS INSP, Date of Government Version: 04/09/2009				
<b>TRIAD TECHNOLOGIES I</b>	<b>105 SPENCER ST</b>	<b>SW &gt;2 (2.667 mi.)</b>	<b>TT4246</b>	<b>971</b>
Database: FTTS, Date of Government Version: 04/09/2009				
Docket Number:: E-02-2004-4210				
Close Date:: / /				
<b>LEAD SAFE, LLC</b>	<b>466 SALINA ST</b>	<b>SW &gt;2 (2.686 mi.)</b>	<b>TN4304</b>	<b>984</b>
Database: FTTS INSP, Date of Government Version: 04/09/2009				
<b>LONGLEY JONES-SPRING</b>	<b>76 CATON DR, # 796</b>	<b>SSE &gt;2 (2.690 mi.)</b>	<b>UX4327</b>	<b>990</b>
Database: FTTS INSP, Date of Government Version: 04/09/2009				
<b>CRISAFULLI CONSTRUCT</b>	<b>320 SUNSET AVE</b>	<b>WSW &gt;2 (2.699 mi.)</b>	<b>TQ4360</b>	<b>998</b>
Database: FTTS INSP, Date of Government Version: 04/09/2009				
<b>CONIFER-MOSES DEWITT</b>	<b>212 WEST TOWNSEND</b>	<b>SW &gt;2 (2.700 mi.)</b>	<b>TZ4362</b>	<b>998</b>
Database: FTTS INSP, Date of Government Version: 04/09/2009				
<b>CNY ENVIRONMENTAL IN</b>	<b>466 N SALINA ST</b>	<b>SW &gt;2 (2.703 mi.)</b>	<b>VD4394</b>	<b>1008</b>
Database: FTTS INSP, Date of Government Version: 04/09/2009				
<b>LEAD SAFE LLC</b>	<b>466 N SALINA ST</b>	<b>SW &gt;2 (2.703 mi.)</b>	<b>VD4397</b>	<b>1008</b>
Database: FTTS INSP, Date of Government Version: 04/09/2009				

## EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
<b>CARLYLE COMPRESSOR C</b> Database: HIST FTTS INSP, Date of Government Version: 10/19/2006	<b>6500 CHRYSLER DR</b>	<b>E &gt;2 (2.120 mi.)</b>	<b>LX2372</b>	<b>562</b>
<b>CHESTNUT CROSSING</b> Database: HIST FTTS INSP, Date of Government Version: 10/19/2006	<b>923 JAMES ST</b>	<b>SSW &gt;2 (2.230 mi.)</b>	<b>NJ2635</b>	<b>625</b>
<b>JAMES PARK EAST APAR</b> Database: HIST FTTS INSP, Date of Government Version: 10/19/2006	<b>915 JAMES ST</b>	<b>SSW &gt;2 (2.248 mi.)</b>	<b>NJ2684</b>	<b>636</b>
<b>ALESSANDRO LISI AND</b> Database: HIST FTTS, Date of Government Version: 10/19/2006 Close Date:: / / Docket Number:: T-02-2004-9281	<b>915 JAMES ST</b>	<b>SSW &gt;2 (2.248 mi.)</b>	<b>NJ2687</b>	<b>637</b>
<b>THERMOPATCH CORP</b> Database: HIST FTTS INSP, Date of Government Version: 10/19/2006	<b>2204 ERIE BLVD</b>	<b>S &gt;2 (2.253 mi.)</b>	<b>NN2690</b>	<b>638</b>
<b>BABBITT BEARINGS, IN</b> Database: HIST FTTS INSP, Date of Government Version: 10/19/2006	<b>734 BURNET AVE</b>	<b>SSW &gt;2 (2.449 mi.)</b>	<b>QN3166</b>	<b>749</b>
<b>BABBITT BEARINGS, IN</b> Database: HIST FTTS INSP, Date of Government Version: 10/19/2006	<b>734 BURNET AVE</b>	<b>SSW &gt;2 (2.449 mi.)</b>	<b>QN3168</b>	<b>750</b>
<b>BRIARCLIFF ESTATES</b> Database: HIST FTTS INSP, Date of Government Version: 10/19/2006	<b>300 AUDUBON PARKWAY</b>	<b>SSE &gt;2 (2.459 mi.)</b>	<b>QT3634</b>	<b>833</b>
<b>CONIFER-COURTYARD AT</b> Database: HIST FTTS INSP, Date of Government Version: 10/19/2006	<b>708 JAMES ST</b>	<b>SW &gt;2 (2.521 mi.)</b>	<b>RP3817</b>	<b>876</b>
<b>ROLLING GREEN ESTATE</b> Database: HIST FTTS INSP, Date of Government Version: 10/19/2006	<b>2005 EAST FAYETTE ST</b>	<b>S &gt;2 (2.554 mi.)</b>	<b>RZ3928</b>	<b>898</b>
<b>ENSR CONSULTING</b> Database: HIST FTTS INSP, Date of Government Version: 10/19/2006	<b>6601 KIRKVILLE RD</b>	<b>ESE &gt;2 (2.622 mi.)</b>	<b>TL4109</b>	<b>939</b>
<b>GALSON RESEARCH CORP</b> Database: HIST FTTS INSP, Date of Government Version: 10/19/2006 Close Date:: / / Docket Number:: PCB-88-0235	<b>6601 KIRKVILLE RD</b>	<b>ESE &gt;2 (2.622 mi.)</b>	<b>TL4110</b>	<b>940</b>
<b>TRIAD TECHNOLOGY</b> Database: HIST FTTS INSP, Date of Government Version: 10/19/2006	<b>105 SPENCER ST</b>	<b>SW &gt;2 (2.667 mi.)</b>	<b>TT4242</b>	<b>970</b>
<b>TRIAD TECHNOLOGIES I</b> Database: HIST FTTS, Date of Government Version: 10/19/2006 Close Date:: / / Docket Number:: E-02-2004-4210	<b>105 SPENCER ST</b>	<b>SW &gt;2 (2.667 mi.)</b>	<b>TT4246</b>	<b>971</b>
<b>LEAD SAFE, LLC</b> Database: HIST FTTS INSP, Date of Government Version: 10/19/2006	<b>466 SALINA ST</b>	<b>SW &gt;2 (2.686 mi.)</b>	<b>TN4304</b>	<b>984</b>
<b>LONGLEY JONES-SPRING</b> Database: HIST FTTS INSP, Date of Government Version: 10/19/2006	<b>76 CATON DR, # 796</b>	<b>SSE &gt;2 (2.690 mi.)</b>	<b>UX4327</b>	<b>990</b>
<b>CONIFER-MOSES DEWITT</b> Database: HIST FTTS INSP, Date of Government Version: 10/19/2006	<b>212 WEST TOWNSEND</b>	<b>SW &gt;2 (2.700 mi.)</b>	<b>TZ4362</b>	<b>998</b>
<b>CNY ENVIRONMENTAL IN</b> Database: HIST FTTS INSP, Date of Government Version: 10/19/2006	<b>466 N SALINA ST</b>	<b>SW &gt;2 (2.703 mi.)</b>	<b>VD4394</b>	<b>1008</b>
<b>LEAD SAFE LLC</b> Database: HIST FTTS INSP, Date of Government Version: 10/19/2006	<b>466 N SALINA ST</b>	<b>SW &gt;2 (2.703 mi.)</b>	<b>VD4397</b>	<b>1008</b>
<b>CNY ENVIRONMENTAL IN</b> Database: HIST FTTS INSP, Date of Government Version: 10/19/2006	<b>309 BURNET AVE</b>	<b>SSW &gt;2 (2.704 mi.)</b>	<b>VF4405</b>	<b>1010</b>
<b>ANAREN MICROWAVE, IN</b> Database: HIST FTTS INSP, Date of Government Version: 10/19/2006	<b>6635 KIRKVILLE RD</b>	<b>ESE &gt;2 (2.724 mi.)</b>	<b>VS4496</b>	<b>1031</b>

## EXECUTIVE SUMMARY

Registry ID:: 110064676426				
MARK ANTHONY FOODS	1632 HAWLEY AVE	S >2 (2.063 mi.)	LI2285	542
Registry ID:: 110055492293				
Not reported	NEW PROCESS GEAR BLD	ENE >2 (2.066 mi.)	2286	543
Registry ID:: 110020936059				
<b>IMPERIAL GARDENS</b>	<b>989 JAMES STREET</b>	<b>SSW &gt;2 (2.084 mi.)</b>	<b>LM2307</b>	<b>547</b>
Registry ID:: 110015748887				
<b>SEABOARD ATLANTIC GA</b>	<b>6810 KINNE ST</b>	<b>ENE &gt;2 (2.092 mi.)</b>	<b>2327</b>	<b>551</b>
Registry ID:: 110012232574				
<b>APARTMENTS AT FRANKL</b>	<b>201 DEERFIELD RD</b>	<b>E &gt;2 (2.092 mi.)</b>	<b>LT2329</b>	<b>552</b>
Registry ID:: 110069283714				
<b>DBA RITE AID #10741</b>	<b>6430 KIRKVILLE RD</b>	<b>ESE &gt;2 (2.095 mi.)</b>	<b>LU2332</b>	<b>552</b>
Registry ID:: 110044988216				
<b>BILL RAPP PONTIAC &amp;</b>	<b>3449 BURNET AVE</b>	<b>SE &gt;2 (2.098 mi.)</b>	<b>LQ2335</b>	<b>553</b>
Registry ID:: 110004347804				
<b>NYSDOT BRIDGE BIN 10</b>	<b>I-690 OVER PEAT ST</b>	<b>S &gt;2 (2.098 mi.)</b>	<b>LR2337</b>	<b>554</b>
Registry ID:: 110008111514				
<b>CELLCO - JAMES STREE</b>	<b>989 JAMES STREET SYR</b>	<b>SSW &gt;2 (2.099 mi.)</b>	<b>LM2338</b>	<b>554</b>
Registry ID:: 110040426090				
MILLION AIR HANGAR	442 COLONEL EILEEN C	NNW >2 (2.102 mi.)	2340	555
Registry ID:: 110070128451				
WTVH-TV	980 JAMES ST	SSW >2 (2.104 mi.)	LM2344	555
Registry ID:: 110011543044				
<b>KOCHANЕК ROBERT J</b>	<b>219 GRAVES ST</b>	<b>SW &gt;2 (2.118 mi.)</b>	<b>MA2355</b>	<b>558</b>
Registry ID:: 110004549766				
<b>MIDLER CROSSINGS</b>	<b>107-115-119 131 SIMO</b>	<b>SSE &gt;2 (2.119 mi.)</b>	<b>MB2356</b>	<b>558</b>
Registry ID:: 110024425656				
<b>VILLAGE DECORATION L</b>	<b>CORPORATE CIR</b>	<b>NE &gt;2 (2.120 mi.)</b>	<b>2360</b>	<b>559</b>
Registry ID:: 110004567166				
<b>LOWES OF SYRACUSE NY</b>	<b>131 SIMON DR</b>	<b>SSE &gt;2 (2.120 mi.)</b>	<b>MB2364</b>	<b>560</b>
Registry ID:: 110037434746				
CARRIER CORP. CARLYL	6500 CHRYSLER DR	E >2 (2.120 mi.)	LX2375	563
Registry ID:: 110011779156				
<b>CARRIER CORP CARLYLE</b>	<b>6500 CHRYSLER DR</b>	<b>E &gt;2 (2.120 mi.)</b>	<b>LX2381</b>	<b>564</b>
Registry ID:: 110064315030				
Registry ID:: 110019426691				
<b>ADVANCED MOTORS &amp; DR</b>	<b>6500 NEW VENTURE DEA</b>	<b>E &gt;2 (2.120 mi.)</b>	<b>LX2382</b>	<b>564</b>
Registry ID:: 110055010232				
SULLIVAN, BAZINET, B	6500 NEW VENTURE GEA	E >2 (2.120 mi.)	LX2383	564
Registry ID:: 110070286668				
BRISTOL-MYERS SQUIBB	6000 THOMPSON RD	SE >2 (2.124 mi.)	MD2386	565
Registry ID:: 110070118347				
<b>BRISTOL-MYERS SQUIBB</b>	<b>6000 THOMPSON ROAD</b>	<b>SE &gt;2 (2.124 mi.)</b>	<b>MD2406</b>	<b>570</b>
Registry ID:: 110000325675				
<b>PARE DAWN</b>	<b>906 1ST NORTH ST</b>	<b>WSW &gt;2 (2.130 mi.)</b>	<b>MG2424</b>	<b>574</b>
Registry ID:: 110004560467				
<b>WOLLER STEVE A</b>	<b>601 HIGHLAND AVE</b>	<b>SW &gt;2 (2.136 mi.)</b>	<b>MA2431</b>	<b>576</b>

## EXECUTIVE SUMMARY

Registry ID: 110060157459				
<b>LONGLEY JONE MANAGEM</b>	<b>1010 JAMES ST</b>	<b>SSW &gt;2 (2.038 mi.)</b>	<b>KE2230</b>	<b>530</b>
Registry ID: 110010712586				
<b>FESTIVAL GARDENS</b>	<b>1010 JAMES STREET</b>	<b>SSW &gt;2 (2.038 mi.)</b>	<b>KE2231</b>	<b>530</b>
Registry ID: 110028153334				
<b>DEYS CENTENNIAL PLAZ</b>	<b>1010 JAMES ST</b>	<b>SSW &gt;2 (2.038 mi.)</b>	<b>KE2232</b>	<b>531</b>
Registry ID: 110035433670				
<b>KINGSBURY SHANE</b>	<b>810 HIGHLAND ST</b>	<b>SW &gt;2 (2.040 mi.)</b>	<b>2238</b>	<b>532</b>
Registry ID: 110004560458				
<b>NEW YORK STATE DEPT</b>	<b>1504 BURNET AVE</b>	<b>S &gt;2 (2.040 mi.)</b>	<b>KY2241</b>	<b>533</b>
Registry ID: 110042174161				
<b>VALVOLINE INSTANT OI</b>	<b>2700 BREWERTON RD &amp;</b>	<b>NW &gt;2 (2.040 mi.)</b>	<b>LF2247</b>	<b>534</b>
Registry ID: 110008071978				
<b>SALINA FREE LIBRARY</b>	<b>100 BELMONT STREET</b>	<b>WNW &gt;2 (2.045 mi.)</b>	<b>KZ2254</b>	<b>535</b>
Registry ID: 110014418530				
<b>FAA SYRACUSE SSC</b>	<b>200 N CONSTELLATION</b>	<b>N &gt;2 (2.050 mi.)</b>	<b>LJ2262</b>	<b>537</b>
Registry ID: 110038898841				
<b>COOPER CROUSE-HINDS</b>	<b>1201 WOLF ST</b>	<b>W &gt;2 (2.052 mi.)</b>	<b>LK2265</b>	<b>538</b>
Registry ID: 110030924971				
<b>PYRAMID SHERLYLE COM</b>	<b>1001 JAMES ST</b>	<b>SSW &gt;2 (2.058 mi.)</b>	<b>LM2276</b>	<b>541</b>
Registry ID: 110064676426				
<b>IMPERIAL GARDENS</b>	<b>989 JAMES STREET</b>	<b>SSW &gt;2 (2.084 mi.)</b>	<b>LM2307</b>	<b>547</b>
Registry ID: 110015748887				
<b>SEABOARD ATLANTIC GA</b>	<b>6810 KINNE ST</b>	<b>ENE &gt;2 (2.092 mi.)</b>	<b>2327</b>	<b>551</b>
Registry ID: 110012232574				
<b>APARTMENTS AT FRANKL</b>	<b>201 DEERFIELD RD</b>	<b>E &gt;2 (2.092 mi.)</b>	<b>LT2329</b>	<b>552</b>
Registry ID: 110069283714				
<b>DBA RITE AID #10741</b>	<b>6430 KIRKVILLE RD</b>	<b>ESE &gt;2 (2.095 mi.)</b>	<b>LU2332</b>	<b>552</b>
Registry ID: 110044988216				
<b>BILL RAPP PONTIAC &amp;</b>	<b>3449 BURNET AVE</b>	<b>SE &gt;2 (2.098 mi.)</b>	<b>LQ2335</b>	<b>553</b>
Registry ID: 110004347804				
<b>NYSDOT BRIDGE BIN 10</b>	<b>I-690 OVER PEAT ST</b>	<b>S &gt;2 (2.098 mi.)</b>	<b>LR2337</b>	<b>554</b>
Registry ID: 110008111514				
<b>CELLCO - JAMES STREE</b>	<b>989 JAMES STREET SYR</b>	<b>SSW &gt;2 (2.099 mi.)</b>	<b>LM2338</b>	<b>554</b>
Registry ID: 110040426090				
<b>KOCHANЕК ROBERT J</b>	<b>219 GRAVES ST</b>	<b>SW &gt;2 (2.118 mi.)</b>	<b>MA2355</b>	<b>558</b>
Registry ID: 110004549766				
<b>MIDLER CROSSINGS</b>	<b>107-115-119 131 SIMO</b>	<b>SSE &gt;2 (2.119 mi.)</b>	<b>MB2356</b>	<b>558</b>
Registry ID: 110024425656				
<b>VILLAGE DECORATION L</b>	<b>CORPORATE CIR</b>	<b>NE &gt;2 (2.120 mi.)</b>	<b>2360</b>	<b>559</b>
Registry ID: 110004567166				
<b>LOWES OF SYRACUSE NY</b>	<b>131 SIMON DR</b>	<b>SSE &gt;2 (2.120 mi.)</b>	<b>MB2364</b>	<b>560</b>
Registry ID: 110037434746				
<b>CARRIER CORP CARLYLE</b>	<b>6500 CHRYSLER DR</b>	<b>E &gt;2 (2.120 mi.)</b>	<b>LX2381</b>	<b>564</b>
Registry ID: 110019426691				
Registry ID: 110064315030				
<b>ADVANCED MOTORS &amp; DR</b>	<b>6500 NEW VENTURE DEA</b>	<b>E &gt;2 (2.120 mi.)</b>	<b>LX2382</b>	<b>564</b>

## EXECUTIVE SUMMARY

DEC Id: 7312600070				
SYRACUSE HAULERS WAS DEC Id: 7312600070	6223 THOMPSON RD - P	SE 1 - 2 (1.562 mi.)	GE1445	345
GLUNDAL COLORINC - 6 DEC Id: 7312600043	6800 JOY RD	ENE 1 - 2 (1.663 mi.)	GZ1623	389
GLUNDAL COLOR INC- 6 DEC Id: 7312600130	6700 JOY RD	ENE 1 - 2 (1.692 mi.)	GZ1642	393
ADVANCED D C MOTORS DEC Id: 7312600197	6268 EAST MOLLOY ROA	NE 1 - 2 (1.711 mi.)	HM1674	401
<b>NORTHERN CIRCUITS IN</b> DEC Id: 7312600157	<b>6 ADLER DR</b>	<b>ENE 1 - 2 (1.805 mi.)</b>	<b>IF1779</b>	<b>424</b>
MARSELLUS CASKET CO DEC Id: 7312600093	6666 KINNE STREET	ENE 1 - 2 (1.904 mi.)	IX1969	469
<b>6666 KINNE LLC</b> DEC Id: 7312600093	<b>6666 KINNE ST</b>	<b>ENE 1 - 2 (1.904 mi.)</b>	<b>IX1971</b>	<b>470</b>
MORSE MANUFACTURING DEC Id: 7312600294	727 W MANLIUS ST	SE 1 - 2 (1.929 mi.)	JC1999	477
PIEDMONT HAWTHORNE A DEC Id: 7314800107	SYRACUSE HANCOCK INT	NNW >2 (2.054 mi.)	LH2271	540
COOPER-CROUSE-HINDS DEC Id: 7314800002	WOLF & SEVENTH NORTH	W >2 (2.106 mi.)	LV2345	556
CARLYLE COMPRESSOR C DEC Id: 7312600017	6500 CHRYSLER DR	E >2 (2.120 mi.)	LX2378	563
BRISTOL-MYERS SQUIBB DEC Id: 7312600016	6000 THOMPSON RD	SE >2 (2.124 mi.)	MD2417	573
CITY OF SYRACUSE DEP DEC Id: 7311500249	1200 CANAL ST EXT	S >2 (2.142 mi.)	MH2448	580
EAGLE METALCRAFT DEC Id: 7312600030	3550 BURNET AVE	SE >2 (2.218 mi.)	MU2613	619
THERMOPATCH CORPORAT DEC Id: 7311500209	2204 ERIE BLVD EAST	S >2 (2.253 mi.)	NN2692	638
<b>CARR STREET GENERATI</b> DEC Id: 7312600127	<b>64 CARR ST</b>	<b>SE &gt;2 (2.289 mi.)</b>	<b>NQ2790</b>	<b>661</b>
CATHEDRAL CANDLE CO DEC Id: 7311500038	510 KIRKPATRICK ST	WSW >2 (2.371 mi.)	PM2988	707
THE RAYMOND CORPORAT DEC Id: 7312600362	6581 CHRYSLER LANE	E >2 (2.418 mi.)	PN3107	735
B G SULZLE INC DEC Id: 7314800001	1 NEEDLE LN	NW >2 (2.618 mi.)	SN4097	937
TRIAD TECHNOLOGIES I DEC Id: 7311500375	105 SPENCER ST	SW >2 (2.667 mi.)	TT4247	971
G A BRAUN INC DEC Id: 7312200528	79 GENERAL IRWIN BLV	NNE >2 (2.675 mi.)	TS4267	976
ICM CONTROLS CORPORA DEC Id: 7312200522	7313 WILLIAM BARRY B	N >2 (2.687 mi.)	UC4309	986
<b>ST JOSEPH'S HOSPITAL</b>	<b>301 PROSPECT AVE</b>	<b>SW &gt;2 (2.690 mi.)</b>	<b>UT4323</b>	<b>989</b>



## EXECUTIVE SUMMARY

EPA ID: NYR000226910				
<b>DBA RITE AID #10741</b>	<b>6430 KIRKVILLE RD</b>	<b>ESE &gt;2 (2.095 mi.)</b>	<b>LU2334</b>	<b>553</b>
EPA ID: NYR000191395				
<b>BILL RAPP PONTIAC &amp;</b>	<b>3449 BURNET AVE</b>	<b>SE &gt;2 (2.098 mi.)</b>	<b>LQ2335</b>	<b>553</b>
EPA ID: NYD013272976				
<b>COOPER CROUSE-HINDS</b>	<b>WOLF &amp; 7TH NORTH ST</b>	<b>W &gt;2 (2.106 mi.)</b>	<b>LV2346</b>	<b>556</b>
EPA ID: NYD002227973				
<b>LOWES OF SYRACUSE NY</b>	<b>131 SIMON DR</b>	<b>SSE &gt;2 (2.120 mi.)</b>	<b>MB2364</b>	<b>560</b>
EPA ID: NYR000157750				
<b>APEX STRIPING INC</b>	<b>NEW VENTURE GEAR DR</b>	<b>E &gt;2 (2.120 mi.)</b>	<b>LX2368</b>	<b>561</b>
EPA ID: NYR000080622				
<b>UNITED TECHNOLOGIES</b>	<b>6500 CHRYSLER DRIVE</b>	<b>E &gt;2 (2.120 mi.)</b>	<b>LX2369</b>	<b>561</b>
EPA ID: NYD000688796				
<b>BRISTOL-MYERS SQUIBB</b>	<b>THOMPSON RD</b>	<b>SE &gt;2 (2.124 mi.)</b>	<b>MD2388</b>	<b>565</b>
EPA ID: NYD002230902				
<b>PARE DAWN</b>	<b>906 1ST NORTH ST</b>	<b>WSW &gt;2 (2.130 mi.)</b>	<b>MG2424</b>	<b>574</b>
EPA ID: NYR000083444				
<b>PEERLESS ENVIRONMENT</b>	<b>815 KIRKPATRICK ST</b>	<b>WSW &gt;2 (2.138 mi.)</b>	<b>MG2433</b>	<b>576</b>
EPA ID: NYR000049700				
<b>CONVENIENT FAMILY HE</b>	<b>2804 BREWERTON RD</b>	<b>NW &gt;2 (2.141 mi.)</b>	<b>LY2436</b>	<b>577</b>
EPA ID: NYD986971364				
<b>CSX TRANSPORTATION I</b>	<b>342 PEAT ST</b>	<b>S &gt;2 (2.141 mi.)</b>	<b>MH2443</b>	<b>579</b>
EPA ID: NYR000223560				
<b>SYRACUSE DPW DIESEL</b>	<b>1200 CANAL ST EXT</b>	<b>S &gt;2 (2.142 mi.)</b>	<b>MH2447</b>	<b>580</b>
EPA ID: NYD982738221				
<b>USAIR MAINTENANCE</b>	<b>HANCOCK AIRPORT</b>	<b>NNW &gt;2 (2.145 mi.)</b>	<b>MI2457</b>	<b>582</b>
EPA ID: NYD986893303				
<b>RICHELIEU AMERICA LT</b>	<b>1216 CANAL ST</b>	<b>S &gt;2 (2.148 mi.)</b>	<b>MK2459</b>	<b>583</b>
EPA ID: NYR000219170				
<b>NORTHERN LIGHTS MOBI</b>	<b>2801 BREWERTON RD</b>	<b>NW &gt;2 (2.153 mi.)</b>	<b>LY2513</b>	<b>596</b>
EPA ID: NYD013284286				
<b>PENSKE AUTO CENTER</b>	<b>2803 BREWERTON RD -</b>	<b>NW &gt;2 (2.154 mi.)</b>	<b>LY2520</b>	<b>597</b>
EPA ID: NYR000017715				
<b>KMART CORPORATION #4</b>	<b>2803 BREWERTON RD</b>	<b>NW &gt;2 (2.154 mi.)</b>	<b>LY2521</b>	<b>598</b>
EPA ID: NYD986991677				
<b>SYRACUSE CUSTOM CARP</b>	<b>617 W MANLIUS ST</b>	<b>SE &gt;2 (2.164 mi.)</b>	<b>MO2533</b>	<b>601</b>
EPA ID: NY0000027979				
<b>MILLER HARDWARE ABAN</b>	<b>826 BUTTERNUT ST</b>	<b>SW &gt;2 (2.177 mi.)</b>	<b>ME2551</b>	<b>605</b>
EPA ID: NY0000853572				
<b>ALIBRANDI JOHN G</b>	<b>125 THOMPSON RD</b>	<b>SE &gt;2 (2.178 mi.)</b>	<b>MD2554</b>	<b>605</b>
EPA ID: NY0000708701				
<b>HARRINGTON GRACE</b>	<b>532 CARBON ST</b>	<b>SW &gt;2 (2.187 mi.)</b>	<b>2565</b>	<b>608</b>
EPA ID: NYR000038307				
<b>PETERS &amp; SONS TAILOR</b>	<b>835 PARK ST</b>	<b>SW &gt;2 (2.188 mi.)</b>	<b>MJ2567</b>	<b>609</b>
EPA ID: NYD013271549				
<b>A T &amp; T</b>	<b>641 THOMSON RD</b>	<b>SE &gt;2 (2.197 mi.)</b>	<b>MY2580</b>	<b>612</b>

## EXECUTIVE SUMMARY

Limit Set Status Flag: A  
Permit Number: NY0233005

NY VAPOR REOPENED: A review of the NY VAPOR REOPENED list, as provided by EDR, and dated 01/01/2018 has revealed that there are 5 NY VAPOR REOPENED sites within approximately 3 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
<b>SYRACUSE CHINA</b> Facility Status: Complete (No Further Action) Site Code: 734053	<b>2801 COURT ST</b>	<b>W 1/2 - 1 (0.775 mi.)</b>	<b>BM498</b>	<b>124</b>
CARRIER-CARLYLE COMP Facility Status: Complete (Mitigate) Site Code: 734068	6500 NEW VENTURE GEA	E >2 (2.120 mi.)	LX2376	563
<b>MCKESSON ENVIROSYSTE</b> Facility Status: Complete (No Further Action) Site Code: 734020	<b>400 BEAR ST</b>	<b>WSW &gt;2 (2.585 mi.)</b>	<b>SS4003</b>	<b>914</b>
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
<b>GENERAL MOTORS - FIS</b> Facility Status: Complete (Mitigate) Site Code: 734057	<b>1000 TOWN LINE ROAD</b>	<b>NW 1/4 - 1/2 (0.280 mi.)</b>	<b>E41</b>	<b>17</b>
<b>FORMER G.E. COURT ST</b> Facility Status: Complete Site Code: 734070	<b>6437 DEERE ROAD</b>	<b>ENE 1/2 - 1 (0.596 mi.)</b>	<b>AO268</b>	<b>70</b>

NY COOLING TOWERS: A review of the NY COOLING TOWERS list, as provided by EDR, and dated 01/08/2019 has revealed that there are 121 NY COOLING TOWERS sites within approximately 3 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
Not reported	6040 TARBELL RD	ENE 1/2 - 1 (0.785 mi.)	BL514	128
Not reported	113 FALSO DR	NNE 1/2 - 1 (0.862 mi.)	BX588	145
Not reported	113 FALSO DR	NNE 1/2 - 1 (0.862 mi.)	BX589	145
Not reported	113 FALSO DR	NNE 1/2 - 1 (0.862 mi.)	BX590	145
Not reported	6712 BROOKLAWN PARKW	NE 1 - 2 (1.085 mi.)	CZ778	189
Not reported	6001 MOLLOY RD	NNE 1 - 2 (1.123 mi.)	DF805	195
Not reported	6001 MOLLOY RD	NNE 1 - 2 (1.123 mi.)	DF819	199
Not reported	6360 THOMPSON RD	ESE 1 - 2 (1.379 mi.)	FA1159	278
Not reported	6360 THOMPSON RD	ESE 1 - 2 (1.379 mi.)	FA1162	278
Not reported	6360 THOMPSON RD	ESE 1 - 2 (1.379 mi.)	FA1163	278
Not reported	6360 THOMPSON RD	ESE 1 - 2 (1.379 mi.)	FA1164	279
Not reported	6360 THOMPSON RD	ESE 1 - 2 (1.379 mi.)	FA1167	279
Not reported	6360 THOMPSON RD	ESE 1 - 2 (1.379 mi.)	FA1168	279
Not reported	6360 THOMPSON RD	ESE 1 - 2 (1.379 mi.)	FA1169	280
Not reported	6360 THOMPSON RD	ESE 1 - 2 (1.379 mi.)	FA1170	280
Not reported	1613 JAMES STREET	SSW 1 - 2 (1.579 mi.)	GK1498	357
Not reported	1613 JAMES STREET	SSW 1 - 2 (1.579 mi.)	GK1501	358
Not reported	400 SUNNYCREST RD	S 1 - 2 (1.652 mi.)	HA1602	384

## EXECUTIVE SUMMARY

Equal/Higher Elevation	Address	Direction / Distance	Map ID	Page
SPEEDY TRANSMISSION	6222 THOMPSON RD	SE 1 - 2 (1.568 mi.)	GE1463	348
DE FIO TONY	1500 BUTTERNUT ST	WSW 1 - 2 (1.653 mi.)	GU1605	384
TWO GUYS AUTO SERVIC	1601 LEMOYNE AVE	W 1 - 2 (1.693 mi.)	HC1643	394
COLAB ENTERPRISES IN	1916 BREWERTON RD	WNW 1 - 2 (1.745 mi.)	1716	410
HENDRELL HENRY G	2212 BREWERTON RD	WNW 1 - 2 (1.768 mi.)	HV1731	414
GRECO ANNUNZIO	W MANLIUS & E JAMES	SE 1 - 2 (1.791 mi.)	ID1764	421
SERVICE STATION & RE	2300 BREWERTON RD ST	WNW 1 - 2 (1.813 mi.)	IG1787	427
TRAUX PAUL	4405 JAMES ST	SE 1 - 2 (1.820 mi.)	ID1796	429
YOUNG TERRY TEXACO S	2301 BREWERTON RD	WNW 1 - 2 (1.827 mi.)	IG1820	435
FOOD BAG CITGO	750 W MANLIUS ST	SE 1 - 2 (1.837 mi.)	ID1838	440
SONBYRNE SALES 8 MAT	2307 BREWERTON RD	WNW 1 - 2 (1.848 mi.)	IG1856	444
OAK PARK SERVICE	809 OAK ST	SW 1 - 2 (1.861 mi.)	IQ1880	449
MATTYDALE SERVICE CE	2349 BREWERTON RD	WNW 1 - 2 (1.867 mi.)	IG1910	456
SERVICE STATION & RE	10 ADLER DR STE 112	ENE 1 - 2 (1.892 mi.)	JF1953	466
BRAKE PAD ADVANCED T	2500 BREWERTON RD	NW 1 - 2 (1.908 mi.)	JD1976	471
SERVICE STN REPR SP	1801 BURNET AVE	S 1 - 2 (1.957 mi.)	KA2043	488
ADVANCED AUTOMOTIVE	2616 BREWERTON RD	NW 1 - 2 (1.973 mi.)	KI2067	493
CHOPPERS CAR CARE CE	3207 BURNET AVE	SSE 1 - 2 (1.997 mi.)	KP2148	511
MOBILE CLIMATE CONTR	27 CORPORATE CIR STE	NE >2 (2.007 mi.)	KM2154	512
FEATHERLY ROBERT I	701 W MANLIUS ST	SE >2 (2.026 mi.)	KF2192	521
RUSYN WILLIAM	1224 WOLF ST	W >2 (2.029 mi.)	KN2204	524
BURGWIN GERALD E	BUTTERNUT & CARBON	SW >2 (2.061 mi.)	LL2281	542
NORTHERN LIGHTS MOBI	2723 BREWERTON RD	NW >2 (2.086 mi.)	LF2314	548
COCHRANS MAJOR GAS	6410 COLLAMER RD	ENE >2 (2.086 mi.)	LO2322	550
GERACE GULF SERVICE	422 KINNE ST	ESE >2 (2.115 mi.)	LZ2353	557
NUT SHELL	303 W MOLLOY RD	WNW >2 (2.120 mi.)	2358	559
FASTRAC MARKETS LLC	6500 NEW VENTURE GEA	E >2 (2.120 mi.)	LX2371	562
FASTRAC PROPERTIES I	6500 NEW VNTR GR DR	E >2 (2.120 mi.)	LX2377	563
MOBIL MECHANIC	69 FREDERICK ST	ESE >2 (2.128 mi.)	2422	574
SPEEDY TRANSMISSION	2804 BREWERTON	NW >2 (2.141 mi.)	LY2435	577
GOODYEAR TIRE & RUBB	2801 BREWERTON RD	NW >2 (2.153 mi.)	LY2515	597
GAUVIN WALLACE	2807 BREWERTON RD	NW >2 (2.155 mi.)	LY2522	598
HYS SUPER SERVICE	1302 BURNET AVE	S >2 (2.172 mi.)	MQ2544	603
VILLAGE AUTO SERVICE	611 W MANLIUS ST	SE >2 (2.205 mi.)	MO2584	613
DAVES NORTHSIDE AUTO	900 HAWLEY AVE	SSW >2 (2.214 mi.)	2601	617
MAGARIS PHIL SERVICE	2445 ERIE BLVD E	SSE >2 (2.227 mi.)	NH2629	623
MASELLO ENTPS OF SYR	801 BUTTERNUT ST	SW >2 (2.232 mi.)	NK2639	626
GERRYS GULF SERVICE	2501 ERIE BLVD E	SSE >2 (2.234 mi.)	NB2644	627
GAS N GROCERIES INC	2509 ERIE BLVD EAST	SSE >2 (2.235 mi.)	NB2649	628
DEES RENTAL SERVICE	RT 690 & TEALL AVE	S >2 (2.236 mi.)	MQ2650	628
SERVICE STATION & RE	6437 COLLAMER RD STE	ENE >2 (2.247 mi.)	2683	636
LEES SAM ARCO SERVIC	2500 ERIE BLVD E	SSE >2 (2.261 mi.)	NB2711	643
ZIP TRANS INC	2564 ERIE BLVD E	SSE >2 (2.273 mi.)	NU2733	648
ORSOS SERVICE	505 POND ST	SW >2 (2.288 mi.)	OF2782	659
ORSOS GULF SERVICE	1200 PARK ST	SW >2 (2.291 mi.)	OF2794	662
JERVIDIN SERVICE COR	901 BURNET AVE	SSW >2 (2.334 mi.)	PA2916	691
STERLING TRUCK STOP	1977 ERIE BLVD E	S >2 (2.335 mi.)	OT2919	692
GOLY MOTORS INC	800 WOLF ST	WSW >2 (2.356 mi.)	PB2961	702
UNITED REFINING COMP	450 W MANLIUS ST	SE >2 (2.359 mi.)	PI2966	703
PHIL MAGARIS SERVICE	204 SEELEY RD	SSE >2 (2.361 mi.)	OX2969	703
HI FY SERVICE STATIO	2901 ERIE BLVD E	SSE >2 (2.393 mi.)	PW3056	723
DE FIO TONY	716 CATHERINE ST	SW >2 (2.401 mi.)	QA3068	727
ZERRILLO CHESTER	726 WOLF ST	WSW >2 (2.404 mi.)	PY3076	728
G T AUTOMOTIVE INC	6481 COLLAMER RD	ENE >2 (2.406 mi.)	PS3080	729
GUYS SERVICE STATION	725 WOLF ST	WSW >2 (2.411 mi.)	PY3097	733
GUYS SERVICE STATION	700 HIAWATHA BLVD E	WSW >2 (2.420 mi.)	QF3113	736

## EXECUTIVE SUMMARY

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
PATS MENS SHOP & DRY	248 WOLF ST	WSW >2 (2.731 mi.)	UV4534	1040
ONEIDA LAKE MOTEL	1135 SALT SPRINGS RD	SSE >2 (2.784 mi.)	WX4714	1082
ARID CLEANERS	436 JAMES ST	SW >2 (2.785 mi.)	WJ4716	1083
CASTLES FAST DRY CLE	1210 SALT SPRINGS	SSE >2 (2.818 mi.)	4868	1119
D & L ULTRASHINE	6763 BUCKLEY RD	WNW >2 (2.823 mi.)	XR4898	1126
CRYSTAL CLEANERS	113 E 2ND ST	SE >2 (2.824 mi.)	YB4899	1127
PATRICKS TWO HOUR CL	1100 MADISON ST	SSW >2 (2.877 mi.)	ZH5140	1182
BILTWELL DRY CLEANIN	936 E GENESEE ST	SSW >2 (2.888 mi.)	YZ5168	1188
WESTCOTT ALTERATIONS	214 BASSETT ST	S >2 (2.900 mi.)	ZW5235	1203
K & R CLASSIC CLEANE	628 S MAIN ST	NNW >2 (2.977 mi.)	E5506	1266
K9 CLEANERS	626 S MAIN ST	NNW >2 (2.981 mi.)	E5518	1269
SCHIEDEL CLEANERS	624 S MAIN ST	NNW >2 (2.984 mi.)	E5538	1275
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
BEL AIRE LAUNDROMAT	TAFT & KREISCHER RD	N >2 (2.760 mi.)	WB4625	1061
NORTH STAR CLEANERS	6041 TAFT RD	NNE >2 (2.812 mi.)	XL4853	1115

### EDR RECOVERED GOVERNMENT ARCHIVES

#### *Exclusive Recovered Govt. Archives*

NY RGA HWS: A review of the NY RGA HWS list, as provided by EDR, has revealed that there are 13 NY RGA HWS sites within approximately 3 miles of the target property.

<u>Equal/Higher Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
SYRACUSE CHINA Facility ID: 734053	2900 COURT STREET	W 1/2 - 1 (0.775 mi.)	BM495	123
PRESTOLITE COMPANY	219 LAMSON STREET	SE 1 - 2 (1.112 mi.)	DE797	193
NY AIR NATIONAL GUAR	6001 EAST MALLOY ROA	NNE 1 - 2 (1.123 mi.)	DF803	195
UTC - CARRIER Facility ID: 734043	6350 THOMPSON ROAD (	ESE 1 - 2 (1.392 mi.)	FA1178	281
CARRIER-CARLYLE COMP	6500 NEW VENTURE GEA	E >2 (2.120 mi.)	LX2370	562
BRISTOL LABS Facility ID: 734001	6000 THOMPSON ROAD (	SE >2 (2.124 mi.)	MD2405	570
PETER WINKELMAN COMP Facility ID: 734047	101 GREENWAY AVENUE	S >2 (2.355 mi.)	OV2951	699
PETER WINKELMAN COMP Facility ID: 734047	101 GREENWAY AVENUE	S >2 (2.355 mi.)	OV2953	700
MCKESSON ENVIROSYSTE Facility ID: 734020	400 BEAR STREET WEST	WSW >2 (2.585 mi.)	SS4002	914
QUANTA RESOURCES Facility ID: 734013	2802-2810 LODI STREE	WSW >2 (2.852 mi.)	XU5038	1158
<u>Lower Elevation</u>	<u>Address</u>	<u>Direction / Distance</u>	<u>Map ID</u>	<u>Page</u>
FORMER GE COURT STRE	6417 & 6437 DEERE RO	E 1/2 - 1 (0.569 mi.)	AO234	62

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

LX2367  
East  
> 1  
2.120 mi.  
11195 ft.

CARRIER CORP.-CARLYLE  
CARLYLE-COMPRESSOR  
DEWITT, NY

NY Spills

S102123722  
N/A

Relative:  
Higher

[Click here for full text details](#)

NY Spills

Site ID: 155748

Spill Number/Closed Date: 8703556 / 1987-12-22

LX2368  
East  
> 1  
2.120 mi.  
11195 ft.

APEX STRIPING INC  
NEW VENTURE GEAR DR  
EAST SYRACUSE, NY 13057

NY SHWS

1004761198

NY SWF/LF

NYR000080622

NY ENG CONTROLS

NY INST CONTROL

NY SWTIRE

RCRA NonGen / NLR

NY Financial Assurance

NY MANIFEST

Relative:  
Higher

[Click here for full text details](#)

NY SHWS

Site Code: 56358

Class Code: Site is properly closed - requires continued management.

NY ENG CONTROLS

Site Code: 56358

NY INST CONTROL

Site Code: 56358

RCRA NonGen / NLR

EPA Id: NYR000080622

NY Financial Assurance

Activity Number: 34K03

NY MANIFEST

EPA ID: NYR000080622

LX2369  
East  
> 1  
2.120 mi.  
11195 ft.

UNITED TECHNOLOGIES CARLYLE COMPRESSOR  
6500 CHRYSLER DRIVE  
SYRACUSE, NY 13221

NY MANIFEST

S122482286  
N/A

Relative:  
Higher

[Click here for full text details](#)

NY MANIFEST

EPA ID: NYD000688796

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**LX2370**  
East  
> 1  
2.120 mi.  
11195 ft.

**CARRIER-CARLYLE COMPRESSORS**  
6500 NEW VENTURE GEAR DRIVE  
DEWITT, NY

NY RGA HWS

S114963511  
N/A

Relative:  
Higher

[Click here for full text details](#)

**LX2371**  
East  
> 1  
2.120 mi.  
11195 ft.

**FASTRAC MARKETS LLC**  
6500 NEW VENTURE GEAR DR  
EAST SYRACUSE, NY 13057

EDR Hist Auto

1020199349  
N/A

Relative:  
Higher

[Click here for full text details](#)

**LX2372**  
East  
> 1  
2.120 mi.  
11195 ft.

**CARLYLE COMPRESSOR CO DIV CARRIER CORP**  
6500 CHRYSLER DR  
DEWITT, NY 13214

RCRA NonGen / NLR  
FTTS  
HIST FTTS

1000293635  
NYD000688796

Relative:  
Higher

[Click here for full text details](#)

RCRA NonGen / NLR  
EPA Id: NYD000688796

**LX2373**  
East  
> 1  
2.120 mi.  
11195 ft.

**CARRIER CIRCLE BUSINESS COMPLEX**  
6500 NEW VENTURE GEAR DR  
EAST SYRACUSE, NY 13057

NY UST

U004082186  
N/A

Relative:  
Higher

[Click here for full text details](#)

**LX2374**  
East  
> 1  
2.120 mi.  
11195 ft.

**CARRIER CORP**  
6500 CHRYSLER DR  
SYRACUSE, NY

NY LTANKS  
NY Spills

S102666543  
N/A

Relative:  
Higher

[Click here for full text details](#)

**NY LTANKS**  
Site ID: 211667  
Spill Number/Closed Date: 9700279 / 1997-06-30

**NY Spills**  
Site ID: 331247  
Spill Number/Closed Date: 9902482 / 1999-07-02

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

LX2375 CARRIER CORP. CARLYLE COMPRESSOR DIV.  
East 6500 CHRYSLER DR  
> 1 SYRACUSE, NY 13221  
2.120 mi.  
11195 ft.

FINDS 1016297704  
N/A

Relative:  
Higher

[Click here for full text details](#)

FINDS

Registry ID:: 110011779156

LX2376 CARRIER-CARLYLE COMPRESSORS  
East 6500 NEW VENTURE GEAR DRIVE  
> 1 DEWITT, NY  
2.120 mi.  
11195 ft.

NY VAPOR REOPENED S106780982  
N/A

Relative:  
Higher

[Click here for full text details](#)

NY VAPOR REOPENED

Site Code: 734068

Facility Status: Complete (Mitigate)

LX2377 FASTRAC PROPERTIES II LLC  
East 6500 NEW VNTR GR DR 100  
> 1 EAST SYRACUSE, NY 13057  
2.120 mi.  
11195 ft.

EDR Hist Auto 1020897278  
N/A

Relative:  
Higher

[Click here for full text details](#)

LX2378 CARLYLE COMPRESSOR CO DIV CARRIER CORP  
East 6500 CHRYSLER DR  
> 1 DEWITT, NY 13214  
2.120 mi.  
11195 ft.

NY AIRS S121491804  
N/A

Relative:  
Higher

[Click here for full text details](#)

NY AIRS

DEC Id: 7312600017

LX2379 CARRIER CORP  
East 6500 NEW VENTURE GEAR DR  
> 1 SYRACUSE, NY  
2.120 mi.  
11195 ft.

NY Spills S104284857  
N/A

Relative:  
Higher

[Click here for full text details](#)

NY Spills

Site ID: 129847

Spill Number/Closed Date: 9911037 / 1999-12-20

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**LX2380**  
East  
> 1  
2.120 mi.  
11195 ft.

**CARRIER CIRCLE BUSINESS COMPLEX**  
6500 NEW VENTURE GEAR DR  
EAST SYRACUSE, NY 13057

**NY AST**

**U003077837**  
N/A

Relative:  
Higher

[Click here for full text details](#)

**NY AST**

Facility Id: 7-123927

**LX2381**  
East  
> 1  
2.120 mi.  
11195 ft.

**CARRIER CORP CARLYLE COMPRESSOR DIV**  
6500 CHRYSLER DR  
DE WITT, NY 13214

**FINDS**  
**ECHO**

**1007780207**  
N/A

Relative:  
Higher

[Click here for full text details](#)

**FINDS**

Registry ID:: 110064315030

Registry ID:: 110019426691

**ECHO**

Registry ID: 110019426691

Registry ID: 110064315030

**LX2382**  
East  
> 1  
2.120 mi.  
11195 ft.

**ADVANCED MOTORS & DRIVES**  
6500 NEW VENTURE DEAR DR  
EAST SYRACUSE, NY 13057

**FINDS**  
**ECHO**

**1016008578**  
N/A

Relative:  
Higher

[Click here for full text details](#)

**FINDS**

Registry ID:: 110055010232

**ECHO**

Registry ID: 110055010232

**LX2383**  
East  
> 1  
2.120 mi.  
11195 ft.

**SULLIVAN, BAZINET, BONGIO INC.**  
6500 NEW VENTURE GEAR DRIVE  
EAST SYRACUSE, NY 13057

**FINDS**

**1024382331**  
N/A

Relative:  
Higher

[Click here for full text details](#)

**FINDS**

Registry ID:: 110070286668



Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

	Site	Database(s)	EDR ID Number EPA ID Number
<b>ML2476</b> East > 1 2.148 mi. 11340 ft.  Relative: Higher	<b>OUTSIDE CARRIER PLANT</b> <b>CARRIER PARKWAY</b> <b>SYRACUSE, NY</b>  <a href="#">Click here for full text details</a>  <b>NY Spills</b> Site ID: 103299 Spill Number/Closed Date: 0007365 / 2000-09-29	<b>NY Spills</b>	<b>S104789856</b> <b>N/A</b>
<b>ML2477</b> East > 1 2.148 mi. 11340 ft.  Relative: Higher	<b>CARRIER CORP</b> <b>CARRIER PARKWAY</b> <b>SYRACUSE, NY</b>  <a href="#">Click here for full text details</a>  <b>NY Spills</b> Site ID: 103309 Spill Number/Closed Date: 0204895 / 2002-08-09	<b>NY Spills</b>	<b>1006891252</b> <b>N/A</b>
<b>ML2478</b> East > 1 2.148 mi. 11340 ft.  Relative: Higher	<b>CARLYLE COMP PLANT</b> <b>6500 NEW PROCESS GEAR DR</b> <b>SYRACUSE, NY</b>  <a href="#">Click here for full text details</a>  <b>NY Spills</b> Site ID: 265489 Spill Number/Closed Date: 9911092 / 1999-12-20	<b>NY Spills</b>	<b>S104284901</b> <b>N/A</b>
<b>ML2479</b> East > 1 2.148 mi. 11340 ft.  Relative: Higher	<b>CARRIER CORP</b> <b>CARRIER PARKWAY</b> <b>SYRACUSE, NY</b>  <a href="#">Click here for full text details</a>  <b>NY Spills</b> Site ID: 103294 Site ID: 103295 Site ID: 103304 Site ID: 103314 Site ID: 103323 Spill Number/Closed Date: 0000424 / 2000-04-11 Spill Number/Closed Date: 0002752 / 2000-06-06 Spill Number/Closed Date: 0103595 / 2001-10-09 Spill Number/Closed Date: 8911626 / 1990-03-13 Spill Number/Closed Date: 9909816 / 1999-11-13	<b>NY Spills</b>	<b>S103567227</b> <b>N/A</b>

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

	Site	Database(s)	EDR ID Number EPA ID Number
<b>ML2472</b> East > 1 2.148 mi. 11340 ft.  Relative: Higher	<b>CARRIER CIRCLE SUNOCO THOMPSON ROAD/CARRIER CIR SYRACUSE, NY</b>  <a href="#">Click here for full text details</a>  <b>NY Spills</b> Site ID: 98385 Site ID: 112423 Spill Number/Closed Date: 8709937 / 1988-02-29 Spill Number/Closed Date: 9813806 / 1999-02-12	<b>NY Spills</b>	<b>S102165943 N/A</b>
<b>ML2473</b> East > 1 2.148 mi. 11340 ft.  Relative: Higher	<b>CARLISLE COMPRESSOR CO CHRYSLER DRIVE EAST SYRACUSE, NY</b>  <a href="#">Click here for full text details</a>  <b>NY Spills</b> Site ID: 273888 Spill Number/Closed Date: 8804337 / 1988-08-17	<b>NY Spills</b>	<b>S103567164 N/A</b>
<b>ML2474</b> East > 1 2.148 mi. 11340 ft.  Relative: Higher	<b>TR2 PLANT CARRIER THOMPSON ROAD SYRACUSE, NY</b>  <a href="#">Click here for full text details</a>  <b>NY Spills</b> Site ID: 327880 Spill Number/Closed Date: 9906843 / 2000-02-16	<b>NY Spills</b>	<b>S104508042 N/A</b>
<b>ML2475</b> East > 1 2.148 mi. 11340 ft.  Relative: Higher	<b>CARRIER CORPORATION THOMPSON ROAD DEWITT, NY</b>  <a href="#">Click here for full text details</a>  <b>NY Spills</b> Site ID: 112411 Site ID: 112420 Spill Number/Closed Date: 0110720 / 2002-02-20 Spill Number/Closed Date: 9612775 / 1997-01-28	<b>NY Spills</b>	<b>S103570268 N/A</b>

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

LX2367  
East  
> 1  
2.120 mi.  
11195 ft.

CARRIER CORP.-CARLYLE  
CARLYLE-COMPRESSOR  
DEWITT, NY

Site 3 of 19 in cluster LX

NY Spills

S102123722  
N/A

Relative:  
Higher

Actual:  
400 ft.

SPILLS:

Spill Number/Closed Date: 8703556 / 1987-12-22  
Facility ID: 8703556  
Facility Type: ER  
DER Facility ID: 131863  
Site ID: 155748  
DEC Region: 7  
Spill Cause: Unknown  
Spill Class: Not reported  
SWIS: 3400  
Spill Date: 1987-07-31  
Investigator: AJMARSCH  
Referred To: Not reported  
Reported to Dept: 1987-07-31  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Unknown  
Spill Notifier: Responsible Party  
Cleanup Ceased: 1987-12-22  
Cleanup Meets Std: True  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 1987-07-31  
Spill Record Last Update: 1994-03-28

Spiller Name: Not reported  
Spiller Company: CARRIER CORPORATION  
Spiller Address: 6500 CHRYSLER DRIVE  
Spiller Company: 001  
Contact Name: Not reported  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was

Remarks:

JM / / : CONTAMINATED SOIL WAS REMOVED. MONITORING WELL WAS CLEAN.  
SPILL CLEANED UP. "  
"EXCAVATION CAME ACROSS CONTAMINATED SOIL AND OILY SUBSTANCE. UNDER-  
GROUND TANKS IN AREA. RECOVERY STARTED. ROLL OFF FOR CONTAMINATED  
SOIL"

All Materials:

Site ID: 155748  
Operable Unit ID: 907440  
Operable Unit: 01  
Material ID: 469787  
Material Code: 0066A  
Material Name: unknown petroleum  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: .00  
Units: Not reported  
Recovered: .00  
Oxygenate: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

LX2368  
East  
> 1  
2.120 mi.  
11195 ft.

APEX STRIPING INC  
NEW VENTURE GEAR DR  
EAST SYRACUSE, NY 13057

Site 4 of 19 in cluster LX

Relative:  
Higher

Actual:  
400 ft.

NY SHWS  
NY SWF/LF  
NY ENG CONTROLS  
NY INST CONTROL  
NY SWTIRE  
RCRA NonGen / NLR  
NY Financial Assurance  
NY MANIFEST

1004761198  
NYR000080622

SHWS:

Program: HW  
Site Code: 56358  
Classification: Site is properly closed - requires continued management.  
Region: 7  
Acres: 32.85  
HW Code: 734068  
Record Add: 11/18/1999  
Record Upd: 11/05/2018  
Updated By: DJHESLER

Site Description: Location: Carrier Carlyle Compressors is located in the northern part of the Town of Dewitt. Historical Use: The facility produced reciprocating compressors as components for air conditioners. The 225,000 square foot manufacturing building was constructed in the late 1960s. Manufacturing processes involved the use of chlorinated organic solvents including trichloroethylene and 1,1,1-trichloroethane. Spills or leaks from the various drums stored in an unpaved area of the back lot resulted in the release of contaminants into the shallow groundwater aquifer. Groundwater contaminants included chloroethane at 7,600 ppb (parts per billion); 1,1-dichloroethane at 8,100 ppb; vinyl chloride at 3,500 ppb; and 1,1,1-trichloroethane at 84,000 ppb. The volume of materials released over time produced a contaminant plume, which covered an area of approximately 260,000 square feet in the southwest corner of the property. Carrier built and began operating a combined pump and treat system and a soil vapor extraction (SVE) system, under an Interim Remedial Measure (IRM), to remediate the identified groundwater contamination. A Remedial Investigation/Feasibility Study (RI/FS) was completed in February of 1999 and a Record of Decision (ROD) was signed on March 30, 1999. The SVE system has since been shut down and an operation, maintenance, and monitoring program continues at this site. A deed restriction for the property restricting groundwater use is in place. A soil vapor mitigation system was installed to mitigate potential soil vapor impacts to the building.

Env Problem: Past spills and/or leakage of contaminants on an unpaved portion of the property contaminated the shallow groundwater at levels in excess of Part 703 groundwater standards. Impacts to nearby Sanders Creek were minimal. A groundwater pump and treat system in conjunction with soil vapor extraction was installed at this site. The system was operated and has since been shut down. Groundwater monitoring continues with sampling every 5 quarters. The site was investigated for soil vapor impacts. A soil vapor mitigation system was installed to mitigate potential soil vapor impacts to the building.

Health Problem: Since some contaminated soils remain at the site below asphalt or clean gravel, people will not come into contact with contaminated soils unless they dig below the surface materials. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process,

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system was installed in the western portion of the site building to prevent vapors beneath the slab from entering that portion of the building. Sampling indicates that soil vapor intrusion is not a concern for the remaining areas of the on-site building or for any off-site buildings.

Dump: False  
Structure: True  
Lagoon: False  
Landfill: False  
Pond: False  
Disp Start: 1970  
Disp Term: Jan. 1991  
Lat/Long: 43:05:20:0 / 76:04:30:0  
Dell: False  
Record Add: 1999-11-18 12:00:00  
Record Upd: 2009-07-02 09:30:00  
Updated By: txsmith  
Own Op: Owner  
Sub Type: NNN  
Owner Name: Not reported  
Owner Company: Carrier Circle Business Complex LLC  
Owner Address: 535 East County Line Road  
Owner Addr2: Suite 15  
Owner City,St,Zip: Lakewood, NJ 08701  
Owner Country: United States of America  
HW Code: 734068  
  
Waste Type: 1,1,1-TRICHLOROETHANE  
Waste Quantity: UNKNOWN  
Waste Code: Not reported  
HW Code: 734068  
Waste Type: TRICHLOROETHYLENE  
Waste Quantity: UNKNOWN  
Waste Code: Not reported  
HW Code: 734068  
Waste Type: TOLUENE  
Waste Quantity: UNKNOWN  
Waste Code: Not reported  
Crossref ID: Not reported  
Cross Ref Type Code: Not reported  
Cross Ref Type: Not reported  
Record Added Date: Not reported  
Record Updated: Not reported  
Updated By: Not reported

SWF/LF:

Flag: ACTIVE  
Region Code: 7  
Phone Number: 3153995335  
Owner Name: Dennis Beaudette  
Owner Type: Private  
Owner Address: 1015 Hiawatha Blvd East  
Owner Addr2: Not reported  
Owner City,St,Zip: Syracuse, NY 13208  
Owner Email: Not reported  
Owner Phone: 3153995335  
Contact Name: Not reported  
Contact Address: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Contact Addr2: Not reported  
Contact City,St,Zip: Not reported  
Contact Email: Not reported  
Contact Phone: Not reported  
Activity Desc: z Retired - Waste tire storage - Retreader  
Activity Number: [34K03]  
Active: Yes  
East Coordinate: 412702  
North Coordinate: 4771256  
Accuracy Code: Not reported  
Regulatory Status: Registration  
Waste Type: Tire  
Authorization #: 34K03  
Authorization Date: 11/10/2015  
Expiration Date: Not reported  
Operator Name: Not reported  
Operator Type: Not reported  
Last Date: 2016-10-07 00:00:00

ENG CONTROLS:

Site Code: 56358  
HW Code: 734068  
Control Code: 13  
Control Type: ENG  
Date Record Added: 06/04/2007

Date Rec Updated: 12/22/2014  
Updated By: txsmith

Site Description: Location: Carrier Carlyle Compressors is located in the northern part of the Town of Dewitt. Historical Use: The facility produced reciprocating compressors as components for air conditioners. The 225,000 square foot manufacturing building was constructed in the late 1960s. Manufacturing processes involved the use of chlorinated organic solvents including trichloroethylene and 1,1,1-trichloroethane. Spills or leaks from the various drums stored in an unpaved area of the back lot resulted in the release of contaminants into the shallow groundwater aquifer. Groundwater contaminants included chloroethane at 7,600 ppb (parts per billion); 1,1-dichloroethane at 8,100 ppb; vinyl chloride at 3,500 ppb; and 1,1,1-trichloroethane at 84,000 ppb. The volume of materials released over time produced a contaminant plume, which covered an area of approximately 260,000 square feet in the southwest corner of the property. Carrier built and began operating a combined pump and treat system and a soil vapor extraction (SVE) system, under an Interim Remedial Measure (IRM), to remediate the identified groundwater contamination. A Remedial Investigation/Feasibility Study (RI/FS) was completed in February of 1999 and a Record of Decision (ROD) was signed on March 30, 1999. The SVE system has since been shut down and an operation, maintenance, and monitoring program continues at this site. A deed restriction for the property restricting groundwater use is in place. A soil vapor mitigation system was installed to mitigate potential soil vapor impacts to the building.

Env Problem: Past spills and/or leakage of contaminants on an unpaved portion of the property contaminated the shallow groundwater at levels in excess of Part 703 groundwater standards. Impacts to nearby Sanders Creek were minimal. A groundwater pump and treat system in conjunction with soil vapor extraction was installed at this site. The system was operated and has since been shut down. Groundwater monitoring continues with sampling every 5 quarters. The site was investigated for soil vapor impacts. A soil vapor mitigation system was installed

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Health Problem: to mitigate potential soil vapor impacts to the building.  
Since some contaminated soils remain at the site below asphalt or clean gravel, people will not come into contact with contaminated soils unless they dig below the surface materials. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system was installed in the western portion of the site building to prevent vapors beneath the slab from entering that portion of the building. Sampling indicates that soil vapor intrusion is not a concern for the remaining areas of the on-site building or for any off-site buildings.

Dump: False  
Structure: True  
Lagoon: False  
Landfill: False  
Pond: False  
Disp Start: 1970  
Disp Term: Jan. 1991  
  
Lat/Long: 43:05:20:0 / 76:04:30:0  
Dell: False  
Record Add: 1999-11-18 12:00:00  
Record Upd: 2009-07-02 09:30:00  
Updated By: txsmith  
Own Op: Owner  
Sub Type: NNN  
Owner Name: Not reported  
Owner Company: Carrier Circle Business Complex LLC  
Owner Address: 535 East County Line Road  
Owner Addr2: Suite 15  
Owner City,St,Zip: Lakewood, NJ 08701  
Owner Country: United States of America  
HW Code: 734068  
Waste Type: 1,1,1-TRICHLOROETHANE  
Waste Quantity: UNKNOWN  
Waste Code: Not reported  
HW Code: 734068  
Waste Type: TRICHLOROETHYLENE  
Waste Quantity: UNKNOWN  
Waste Code: Not reported  
HW Code: 734068  
Waste Type: TOLUENE  
Waste Quantity: UNKNOWN  
Waste Code: Not reported  
Crossref ID: Not reported  
Cross Ref Type Code: Not reported  
Cross Ref Type: Not reported  
Record Added Date: Not reported  
Record Updated: Not reported  
Updated By: Not reported

INST CONTROL:

Site Code: 56358  
Control Name: Deed Restriction  
HW Code: 734068

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Control Code: A  
Control Type: INST  
Dt record added: 06/04/2007  
Dt rec updated: 12/22/2014  
Updated By: txsmith  
Site Code: 56358  
Site Description: Location: Carrier Carlyle Compressors is located in the northern part of the Town of Dewitt. Historical Use: The facility produced reciprocating compressors as components for air conditioners. The 225,000 square foot manufacturing building was constructed in the late 1960s. Manufacturing processes involved the use of chlorinated organic solvents including trichloroethylene and 1,1,1-trichloroethane. Spills or leaks from the various drums stored in an unpaved area of the back lot resulted in the release of contaminants into the shallow groundwater aquifer. Groundwater contaminants included chloroethane at 7,600 ppb (parts per billion); 1,1-dichloroethane at 8,100 ppb; vinyl chloride at 3,500 ppb; and 1,1,1-trichloroethane at 84,000 ppb. The volume of materials released over time produced a contaminant plume, which covered an area of approximately 260,000 square feet in the southwest corner of the property. Carrier built and began operating a combined pump and treat system and a soil vapor extraction (SVE) system, under an Interim Remedial Measure (IRM), to remediate the identified groundwater contamination. A Remedial Investigation/Feasibility Study (RI/FS) was completed in February of 1999 and a Record of Decision (ROD) was signed on March 30, 1999. The SVE system has since been shut down and an operation, maintenance, and monitoring program continues at this site. A deed restriction for the property restricting groundwater use is in place. A soil vapor mitigation system was installed to mitigate potential soil vapor impacts to the building.

Env Problem: Past spills and/or leakage of contaminants on an unpaved portion of the property contaminated the shallow groundwater at levels in excess of Part 703 groundwater standards. Impacts to nearby Sanders Creek were minimal. A groundwater pump and treat system in conjunction with soil vapor extraction was installed at this site. The system was operated and has since been shut down. Groundwater monitoring continues with sampling every 5 quarters. The site was investigated for soil vapor impacts. A soil vapor mitigation system was installed to mitigate potential soil vapor impacts to the building.

Health Problem: Since some contaminated soils remain at the site below asphalt or clean gravel, people will not come into contact with contaminated soils unless they dig below the surface materials. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system was installed in the western portion of the site building to prevent vapors beneath the slab from entering that portion of the building. Sampling indicates that soil vapor intrusion is not a concern for the remaining areas of the on-site building or for any off-site buildings.

Dump: False  
Structure: True  
Lagoon: False  
Landfill: False  
Pond: False



Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Disp Start: 1970  
Disp Term: Jan. 1991  
Lat/Long: 43:05:20:0 / 76:04:30:0  
Dell: False  
Record Add: 1999-11-18 12:00:00  
Record Upd: 2009-07-02 09:30:00  
Updated By: txsmith  
Own Op: Owner  
Sub Type: NNN  
Owner Name: Not reported  
Owner Company: Carrier Circle Business Complex LLC  
Owner Address: 535 East County Line Road  
Owner Addr2: Suite 15  
Owner City,St,Zip:Lakewood, NJ 08701  
Owner Country: United States of America  
HW Code: 734068  
Waste Type: 1,1,1-TRICHLOROETHANE  
Waste Quantity: UNKNOWN  
Waste Code: Not reported  
  
HW Code: 734068  
Waste Type: TRICHLOROETHYLENE  
Waste Quantity: UNKNOWN  
Waste Code: Not reported  
HW Code: 734068  
Waste Type: TOLUENE  
Waste Quantity: UNKNOWN  
Waste Code: Not reported  
Crossref ID: Not reported  
Cross Ref Type Code: Not reported  
Cross Ref Type: Not reported  
Record Added Date: Not reported  
Record Updated: Not reported  
Updated By: Not reported  
  
Site Code: 56358  
Control Name: Monitoring Plan  
HW Code: 734068  
Control Code: 31  
Control Type: INST  
Dt record added: 06/04/2007  
Dt rec updated: 12/22/2014  
Updated By: txsmith  
Site Code: 56358  
Site Description: Location: Carrier Carlyle Compressors is located in the northern part of the Town of Dewitt. Historical Use: The facility produced reciprocating compressors as components for air conditioners. The 225,000 square foot manufacturing building was constructed in the late 1960s. Manufacturing processes involved the use of chlorinated organic solvents including trichloroethylene and 1,1,1-trichloroethane. Spills or leaks from the various drums stored in an unpaved area of the back lot resulted in the release of contaminants into the shallow groundwater aquifer. Groundwater contaminants included chloroethane at 7,600 ppb (parts per billion); 1,1-dichloroethane at 8,100 ppb; vinyl chloride at 3,500 ppb; and 1,1,1-trichloroethane at 84,000 ppb. The volume of materials released over time produced a contaminant plume, which covered an area of approximately 260,000 square feet in the southwest corner of the property. Carrier built and began operating a combined pump and treat system and a soil vapor extraction (SVE) system, under an Interim

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Remedial Measure (IRM), to remediate the identified groundwater contamination. A Remedial Investigation/Feasibility Study (RI/FS) was completed in February of 1999 and a Record of Decision (ROD) was signed on March 30, 1999. The SVE system has since been shut down and an operation, maintenance, and monitoring program continues at this site. A deed restriction for the property restricting groundwater use is in place. A soil vapor mitigation system was installed to mitigate potential soil vapor impacts to the building.

Env Problem: Past spills and/or leakage of contaminants on an unpaved portion of the property contaminated the shallow groundwater at levels in excess of Part 703 groundwater standards. Impacts to nearby Sanders Creek were minimal. A groundwater pump and treat system in conjunction with soil vapor extraction was installed at this site. The system was operated and has since been shut down. Groundwater monitoring continues with sampling every 5 quarters. The site was investigated for soil vapor impacts. A soil vapor mitigation system was installed to mitigate potential soil vapor impacts to the building.

Health Problem: Since some contaminated soils remain at the site below asphalt or clean gravel, people will not come into contact with contaminated soils unless they dig below the surface materials. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination. Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system was installed in the western portion of the site building to prevent vapors beneath the slab from entering that portion of the building. Sampling indicates that soil vapor intrusion is not a concern for the remaining areas of the on-site building or for any off-site buildings.

Dump: False  
Structure: True  
Lagoon: False  
Landfill: False  
Pond: False  
Disp Start: 1970  
Disp Term: Jan. 1991  
Lat/Long: 43:05:20:0 / 76:04:30:0  
Dell: False  
Record Add: 1999-11-18 12:00:00  
Record Upd: 2009-07-02 09:30:00  
Updated By: txsmith  
Own Op: Owner  
Sub Type: NNN  
Owner Name: Not reported  
Owner Company: Carrier Circle Business Complex LLC  
Owner Address: 535 East County Line Road  
Owner Addr2: Suite 15  
Owner City,St,Zip: Lakewood, NJ 08701  
Owner Country: United States of America  
HW Code: 734068  
Waste Type: 1,1,1-TRICHLOROETHANE  
Waste Quantity: UNKNOWN  
Waste Code: Not reported  
HW Code: 734068  
Waste Type: TRICHLOROETHYLENE  
Waste Quantity: UNKNOWN

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Waste Code: Not reported  
HW Code: 734068  
Waste Type: TOLUENE  
Waste Quantity: UNKNOWN  
Waste Code: Not reported  
Crossref ID: Not reported  
Cross Ref Type Code: Not reported  
Cross Ref Type: Not reported  
Record Added Date: Not reported  
Record Updated: Not reported  
Updated By: Not reported

Site Code: 56358  
Control Name: Ground Water Use Restriction  
HW Code: 734068

Control Code: 08  
Control Type: INST  
Dt record added: 06/04/2007  
Dt rec updated: 12/22/2014  
Updated By: txsmith  
Site Code: 56358

Site Description: Location: Carrier Carlyle Compressors is located in the northern part of the Town of Dewitt. Historical Use: The facility produced reciprocating compressors as components for air conditioners. The 225,000 square foot manufacturing building was constructed in the late 1960s. Manufacturing processes involved the use of chlorinated organic solvents including trichloroethylene and 1,1,1-trichloroethane. Spills or leaks from the various drums stored in an unpaved area of the back lot resulted in the release of contaminants into the shallow groundwater aquifer. Groundwater contaminants included chloroethane at 7,600 ppb (parts per billion); 1,1-dichloroethane at 8,100 ppb; vinyl chloride at 3,500 ppb; and 1,1,1-trichloroethane at 84,000 ppb. The volume of materials released over time produced a contaminant plume, which covered an area of approximately 260,000 square feet in the southwest corner of the property. Carrier built and began operating a combined pump and treat system and a soil vapor extraction (SVE) system, under an Interim Remedial Measure (IRM), to remediate the identified groundwater contamination. A Remedial Investigation/Feasibility Study (RI/FS) was completed in February of 1999 and a Record of Decision (ROD) was signed on March 30, 1999. The SVE system has since been shut down and an operation, maintenance, and monitoring program continues at this site. A deed restriction for the property restricting groundwater use is in place. A soil vapor mitigation system was installed to mitigate potential soil vapor impacts to the building.

Env Problem: Past spills and/or leakage of contaminants on an unpaved portion of the property contaminated the shallow groundwater at levels in excess of Part 703 groundwater standards. Impacts to nearby Sanders Creek were minimal. A groundwater pump and treat system in conjunction with soil vapor extraction was installed at this site. The system was operated and has since been shut down. Groundwater monitoring continues with sampling every 5 quarters. The site was investigated for soil vapor impacts. A soil vapor mitigation system was installed to mitigate potential soil vapor impacts to the building.

Health Problem: Since some contaminated soils remain at the site below asphalt or clean gravel, people will not come into contact with contaminated soils unless they dig below the surface materials. People are not drinking the contaminated groundwater because the area is served by a public water supply that is not affected by this contamination.

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Volatile organic compounds in the groundwater may move into the soil vapor (air spaces within the soil), which in turn may move into overlying buildings and affect the indoor air quality. This process, which is similar to the movement of radon gas from the subsurface into the indoor air of buildings, is referred to as soil vapor intrusion. A sub-slab depressurization system was installed in the western portion of the site building to prevent vapors beneath the slab from entering that portion of the building. Sampling indicates that soil vapor intrusion is not a concern for the remaining areas of the on-site building or for any off-site buildings.

Dump: False  
Structure: True  
Lagoon: False  
  
Landfill: False  
Pond: False  
Disp Start: 1970  
Disp Term: Jan. 1991  
Lat/Long: 43:05:20:0 / 76:04:30:0  
Dell: False  
Record Add: 1999-11-18 12:00:00  
Record Upd: 2009-07-02 09:30:00  
Updated By: txsmith  
Own Op: Owner  
Sub Type: NNN  
Owner Name: Not reported  
Owner Company: Carrier Circle Business Complex LLC  
Owner Address: 535 East County Line Road  
Owner Addr2: Suite 15  
Owner City,St,Zip:Lakewood, NJ 08701  
Owner Country: United States of America  
HW Code: 734068  
Waste Type: 1,1,1-TRICHLOROETHANE  
Waste Quantity: UNKNOWN  
Waste Code: Not reported  
HW Code: 734068  
Waste Type: TRICHLOROETHYLENE  
Waste Quantity: UNKNOWN  
Waste Code: Not reported  
HW Code: 734068  
Waste Type: TOLUENE  
Waste Quantity: UNKNOWN  
Waste Code: Not reported  
Crossref ID: Not reported  
Cross Ref Type Code: Not reported  
Cross Ref Type: Not reported  
Record Added Date: Not reported  
Record Updated: Not reported  
Updated By: Not reported

SWTIRE:

Contact Name: Not reported  
No of Tire: 400  
Concerns: Not reported  
Compliance Status: Not reported  
Facility Status: Not reported  
Region: 7  
East Coordinate: 412702  
North Coordinate: 4771256  
Contact Address: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Contact Address2: Not reported  
Contact City: Not reported  
Contact State: Not reported  
Contact Zip: Not reported  
Contact Email: Not reported  
Owner Name: Dennis Beaudette  
Owner Address: 1015 Hiawatha Blvd East  
Owner Address2: Not reported  
Owner City: Syracuse  
Owner State: NY  
Owner Zip: 13208  
  
Owner Email: Not reported  
Owner Phone: 3153995335  
Owner Type: Private  
Operator Name: Not reported  
Operator Type: Not reported  
Activity Desc: Waste tire storage - Retreader  
Activity Number: [34K03]  
Active: Yes  
Accuracy Code: Not reported  
Waste Types: Tire  
Regulatory Status: Registration  
Authorization Number: 34K03  
Authorization Issue Date: 2015-11-10 00:00:00  
Expiration Date: Not reported  
Date of Last Inspection: 2016-10-07 00:00:00

RCRA NonGen / NLR:

Date form received by agency: 01/01/2007  
Facility name: APEX STRIPING INC  
Facility address: NEW VENTURE GEAR DR  
EAST SYRACUSE, NY 13057  
  
EPA ID: NYR000080622  
Contact: JOSEPH M MCDONALD  
Contact address: NEW VENTURE GEAR DR  
EAST SYRACUSE, NY 13057  
  
Contact country: US  
Contact telephone: 315-432-0714  
Contact email: Not reported  
EPA Region: 02  
Land type: Private  
Classification: Non-Generator  
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: COOLIDGE VENTURES LLC  
Owner/operator address: W RED OAK LN  
WHITE PLAINS, NY 10604  
  
Owner/operator country: US  
Owner/operator telephone: Not reported  
Owner/operator email: Not reported  
Owner/operator fax: Not reported  
Owner/operator extension: Not reported  
Legal status: Private  
Owner/Operator Type: Operator  
Owner/Op start date: 12/31/1979  
Owner/Op end date: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Owner/operator name: COOLIDGE VENTURES LLC  
Owner/operator address: W RED OAK LN  
WHITE PLAINS, NY 10604  
Owner/operator country: US  
Owner/operator telephone: Not reported  
Owner/operator email: Not reported  
Owner/operator fax: Not reported  
Owner/operator extension: Not reported  
Legal status: Private  
  
Owner/Operator Type: Owner  
Owner/Op start date: 12/31/1979  
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No  
Mixed waste (haz. and radioactive): No  
Recycler of hazardous waste: No  
Transporter of hazardous waste: No  
Treater, storer or disposer of HW: No  
Underground injection activity: No  
On-site burner exemption: No  
Furnace exemption: No  
Used oil fuel burner: No  
Used oil processor: No  
User oil refiner: No  
Used oil fuel marketer to burner: No  
Used oil Specification marketer: No  
Used oil transfer facility: No  
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006  
Site name: APEX STRIPING INC  
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 02/24/2004  
Site name: APEX STRIPING INC  
Classification: Large Quantity Generator

. Waste code: D001  
. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSLEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D018  
. Waste name: BENZENE

. Waste code: D035  
. Waste name: METHYL ETHYL KETONE

Date form received by agency: 03/29/2000  
Site name: APEX STRIPING INC  
Classification: Conditionally Exempt Small Quantity Generator

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Waste code: D001  
Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 10/08/2004  
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
Area of violation: Not reported  
Date achieved compliance: Not reported  
Evaluation lead agency: State

NY Financial Assurance 1:

Owner Name: Dennis Beaudette  
Region: 7  
Estimate Type: Closure Estimate  
Estimate Amount: 1500  
Estimate Date: 12/12/2016  
Mechanism: Letter of credit  
Mechanism Amount: 1500  
Issue Date: 12/12/2016  
Expiration Date: 11/01/2017  
Activity Number: 34K03  
Activity Description: Waste tire storage - Retreader

NY MANIFEST:

Country: USA  
EPA ID: NYR000080622  
Facility Status: Not reported  
Location Address 1: 6500 NEW VENTURE GEAR  
Code: BP  
Location Address 2: Not reported  
Total Tanks: Not reported  
Location City: EAST SYRACUSE  
Location State: NY  
Location Zip: 13057  
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYR000080622  
Mailing Name: APEX STRIPPING INC  
Mailing Contact: JOSEPH MCDONALD  
Mailing Address 1: 6500 NEW VENTURE GEAR  
Mailing Address 2: Not reported  
Mailing City: EAST SYRACUSE  
Mailing State: NY  
Mailing Zip: 13057  
Mailing Zip 4: Not reported  
Mailing Country: USA  
Mailing Phone: 3154320714

NY MANIFEST:

Document ID: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Manifest Status:	Not reported
seq:	Not reported
Year:	2012
Trans1 State ID:	TXR000050930
Trans2 State ID:	NJD071629976
Generator Ship Date:	05/04/2012
Trans1 Recv Date:	05/04/2012
Trans2 Recv Date:	05/14/2012
TSD Site Recv Date:	05/17/2012
Part A Recv Date:	Not reported
Part B Recv Date:	Not reported
Generator EPA ID:	NYR000080622
Trans1 EPA ID:	Not reported
Trans2 EPA ID:	Not reported
TSD ID 1:	KYD053348108
TSD ID 2:	Not reported
Manifest Tracking Number:	002931824SKS
Import Indicator:	N
Export Indicator:	N
Discr Quantity Indicator:	N
Discr Type Indicator:	N
Discr Residue Indicator:	N
Discr Partial Reject Indicator:	N
Discr Full Reject Indicator:	N
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H061
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	1550.0
Units:	P - Pounds
Number of Containers:	3.0
Container Type:	DM - Metal drums, barrels
Handling Method:	B Incineration, heat recovery, burning.
Specific Gravity:	1.0
Waste Code:	D001
Waste Code 1_2:	D005
Waste Code 1_3:	D006
Waste Code 1_4:	D007
Waste Code 1_5:	D008
Waste Code 1_6:	Not reported

[Click this hyperlink](#) while viewing on your computer to access  
-1 additional NY MANIFEST: record(s) in the EDR Site Report.



Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**LX2369**  
**East**  
**> 1**  
**2.120 mi.**  
**11195 ft.**

**UNITED TECHNOLOGIES CARLYLE COMPRESSOR**  
**6500 CHRYSLER DRIVE**  
**SYRACUSE, NY 13221**

**NY MANIFEST**

**S122482286**  
**N/A**

**Relative:**  
**Higher**

**Actual:**  
**400 ft.**

NY MANIFEST:

Country: USA  
EPA ID: NYD000688796  
Facility Status: Not reported  
Location Address 1: 6500 CHRYSLER DR  
Code: BP  
  
Location Address 2: Not reported  
Total Tanks: Not reported  
Location City: TOWN OF DEWITT  
Location State: NY  
Location Zip: 13221  
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYD000688796  
Mailing Name: UNITED TECHNOLOGIES CARLYLE COMPRESSOR  
Mailing Contact: BETH HUBBEN  
Mailing Address 1: 6500 CHRYSLER DR-BLDG TR4  
Mailing Address 2: Not reported  
Mailing City: DEWITT  
Mailing State: NY  
Mailing Zip: 13221  
Mailing Zip 4: Not reported  
Mailing Country: USA  
Mailing Phone: 3154326776

NY MANIFEST:

Document ID: Not reported  
Manifest Status: Not reported  
seq: Not reported  
Year: 2012  
Trans1 State ID: TXR000050930  
Trans2 State ID: Not reported  
Generator Ship Date: 05/23/2012  
Trans1 Recv Date: 05/23/2012  
Trans2 Recv Date: Not reported  
TSD Site Recv Date: 06/04/2012  
Part A Recv Date: Not reported  
Part B Recv Date: Not reported  
Generator EPA ID: NYD000688796  
Trans1 EPA ID: Not reported  
Trans2 EPA ID: Not reported  
TSD ID 1: NJD002182897  
TSD ID 2: Not reported  
Manifest Tracking Number: 002931852SKS  
Import Indicator: N  
Export Indicator: N  
Discr Quantity Indicator: N  
Discr Type Indicator: N  
Discr Residue Indicator: N  
Discr Partial Reject Indicator: N  
Discr Full Reject Indicator: N  
Manifest Ref Number: Not reported  
Alt Facility RCRA ID: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	30.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Waste Code:	D002
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

[Click this hyperlink](#) while viewing on your computer to access  
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

	Site	Database(s)	
<b>LX2370</b>	<b>CARRIER-CARLYLE COMPRESSORS</b>	<b>NY RGA HWS</b>	<b>S114963511</b>
<b>East</b>	<b>6500 NEW VENTURE GEAR DRIVE</b>		<b>N/A</b>
<b>&gt; 1</b>	<b>DEWITT, NY</b>		
<b>2.120 mi.</b>	<b>Site 6 of 19 in cluster LX</b>		
<b>11195 ft.</b>			
<b>Relative:</b>	RGA HWS:		
<b>Higher</b>	2012 CARRIER-CARLYLE COMPRESSORS	6500 NEW VENTURE GEAR DRIVE	
<b>Actual:</b>	2011 CARRIER-CARLYLE COMPRESSORS	6500 NEW VENTURE GEAR DRIVE	
<b>400 ft.</b>	2010 CARRIER-CARLYLE COMPRESSORS	6500 NEW VENTURE GEAR DRIVE	

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

LX2371  
East  
> 1  
2.120 mi.  
11195 ft.

**FASTRAC MARKETS LLC**  
**6500 NEW VENTURE GEAR DR**  
**EAST SYRACUSE, NY 13057**

**Site 7 of 19 in cluster LX**

**EDR Hist Auto**

**1020199349**  
**N/A**

**Relative:**  
**Higher**

EDR Hist Auto

**Actual:**  
**400 ft.**

Year:

Name:

Type:

2008 FASTRAC MARKET LLC  
2009 FASTRAC MARKET LLC  
2010 FASTRAC MARKETS LLC  
2010 FASTRAC PROPERTIES II LLC  
2011 FASTRAC PROPERTIES II LLC  
2011 FASTRAC MARKETS LLC  
2012 FASTRAC PROPERTIES II LLC  
2012 FASTRAC MARKETS LLC  
2013 FASTRAC PROPERTIES II LLC  
2013 FASTRAC MARKETS LLC  
2014 FASTRAC MARKETS LLC  
2014 FASTRAC PROPERTIES II LLC

Gasoline Service Stations  
Gasoline Service Stations  
Convenience Stores  
Convenience Stores  
Convenience Stores  
Convenience Stores  
Convenience Stores  
Convenience Stores  
Convenience Stores  
Convenience Stores  
Convenience Stores  
Convenience Stores

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

	Site	Database(s)	
<b>LX2372</b>	<b>CARLYLE COMPRESSOR CO DIV CARRIER CORP</b>	<b>RCRA NonGen / NLR</b>	<b>1000293635</b>
<b>East</b>	<b>6500 CHRYSLER DR</b>	<b>FTTS</b>	<b>NYD000688796</b>
<b>&gt; 1</b>	<b>DEWITT, NY 13214</b>	<b>HIST FTTS</b>	
<b>2.120 mi.</b>			
<b>11195 ft.</b>	<b>Site 8 of 19 in cluster LX</b>		

**Relative:**  
**Higher**

RCRA NonGen / NLR:

**Actual:**  
**400 ft.**

Date form received by agency: 01/01/2007  
Facility name: CARLYLE COMPRESSOR CO DIV CARRIER CORP  
Facility address: 6500 CHRYSLER DR  
DEWITT, NY 13214  
EPA ID: NYD000688796  
Mailing address: PO BOX 4808 TR 4  
SYRACUSE, NY 13221  
Contact: Not reported  
Contact address: PO BOX 4808 TR 4  
SYRACUSE, NY 13221  
Contact country: US  
Contact telephone: Not reported  
Contact email: Not reported  
EPA Region: 02  
Land type: Facility is not located on Indian land. Additional information is not known.  
Classification: Non-Generator  
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name: CARRIER CORP  
Owner/operator address: NOT REQUIRED  
NOT REQUIRED, WY 99999  
Owner/operator country: US  
Owner/operator telephone: 212-555-1212  
Owner/operator email: Not reported  
Owner/operator fax: Not reported  
Owner/operator extension: Not reported  
Legal status: Private  
Owner/Operator Type: Owner  
Owner/Op start date: Not reported  
Owner/Op end date: Not reported

Owner/operator name: CARRIER CORP  
Owner/operator address: NOT REQUIRED  
NOT REQUIRED, WY 99999  
Owner/operator country: US  
Owner/operator telephone: 212-555-1212  
Owner/operator email: Not reported  
Owner/operator fax: Not reported  
Owner/operator extension: Not reported  
Legal status: Private  
Owner/Operator Type: Operator  
Owner/Op start date: Not reported  
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No  
Mixed waste (haz. and radioactive): No  
Recycler of hazardous waste: No  
Transporter of hazardous waste: No  
Treater, storer or disposer of HW: No  
Underground injection activity: No

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

On-site burner exemption: No  
Furnace exemption: No  
Used oil fuel burner: No  
Used oil processor: No  
Used oil refiner: No  
Used oil fuel marketer to burner: No  
Used oil Specification marketer: No  
Used oil transfer facility: No  
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006

Site name: CARLYLE COMPRESSOR CO DIV CARRIER CORP

Classification: Not a generator, verified

Date form received by agency: 07/08/1999

Site name: CARLYLE COMPRESSOR CO DIV CARRIER CORP

Classification: Not a generator, verified

Date form received by agency: 03/30/1994

Site name: UTC - CARLYLE COMPRESSOR

Classification: Large Quantity Generator

Date form received by agency: 02/27/1992

Site name: CARLYLE COMPRESSOR

Classification: Large Quantity Generator

Date form received by agency: 03/01/1990

Site name: UNITED TECHNOLOGIES CARLYLE COMPRESSOR

Classification: Large Quantity Generator

Date form received by agency: 08/18/1980

Site name: CARLYLE COMPRESSOR CO DIV CARRIER CORP

Classification: Large Quantity Generator

. Waste code: D000

. Waste name: Not Defined

. Waste code: D001

. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002

. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: F001

. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE,

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002  
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F017  
. Waste name: Not Defined

. Waste code: U226  
. Waste name: ETHANE, 1,1,1-TRICHLORO-

. Waste code: U228  
. Waste name: ETHENE, TRICHLORO-

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 06/22/1999  
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
Area of violation: Not reported  
Date achieved compliance: Not reported  
Evaluation lead agency: State

Evaluation date: 12/21/1988  
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
Area of violation: Not reported  
Date achieved compliance: Not reported  
Evaluation lead agency: State

Evaluation date: 09/03/1986  
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
Area of violation: Not reported  
Date achieved compliance: Not reported  
Evaluation lead agency: State

FTTS INSP:

Inspection Number: 198808223136 2  
Region: 02  
Inspection Date: 08/22/88  
Inspector: F. FREIHERR, LP  
Violation occurred: No

Investigation Type: Section 6 PCB Federal Conducted  
Investigation Reason: Neutral Scheme, Region  
Legislation Code: TSCA  
Facility Function: User

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

HIST FTTS INSP:

Inspection Number: 198808223136 2  
Region: 02  
Inspection Date: Not reported  
Inspector: F. FREIHERR, LP  
Violation occurred: No  
Investigation Type: Section 6 PCB Federal Conducted  
Investigation Reason: Neutral Scheme, Region  
Legislation Code: TSCA  
Facility Function: User



Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

LX2373  
East  
> 1  
2.120 mi.  
11195 ft.

**CARRIER CIRCLE BUSINESS COMPLEX**  
**6500 NEW VENTURE GEAR DR**  
**EAST SYRACUSE, NY 13057**

NY UST

U004082186  
N/A

Relative:  
Higher

Actual:  
400 ft.

UST:

Id/Status: 7-123927 / Active  
Program Type: PBS  
Region: STATE  
DEC Region: 7  
Expiration Date: 01/14/2023  
UTM X: 412701.74027  
UTM Y: 4771255.02759  
Site Type: Manufacturing (Other than Chemical)/Processing

Affiliation Records:

Site Id: 44599  
Affiliation Type: Mail Contact  
Company Name: CARRIER CIRCLE BUSINESS COMPLEX LLC  
Contact Type: Not reported  
Contact Name: ABE WILHELM  
Address1: 475 OBERLIN AVE SOUTH - SUITE 206  
Address2: Not reported  
City: LAKEWOOD  
State: NJ  
Zip Code: 08701  
Country Code: 001  
Phone: (732) 461-4305  
EMail: ABE@VINTAGEMGT.COM  
Fax Number: Not reported  
Modified By: KCKEMP  
Date Last Modified: 2017-11-15

Site Id: 44599  
Affiliation Type: Facility Operator  
Company Name: CARRIER CIRCLE BUSINESS COMPLEX  
Contact Type: Not reported  
Contact Name: CARRIER CIRCLE BUSINESS COMPLEX LLC  
Address1: Not reported  
Address2: Not reported  
City: Not reported  
State: NN  
Zip Code: Not reported  
Country Code: 001  
Phone: (315) 432-5451  
EMail: Not reported  
Fax Number: Not reported  
Modified By: KCKEMP  
Date Last Modified: 2015-05-08

Site Id: 44599  
Affiliation Type: Emergency Contact  
Company Name: CARRIER CIRCLE BUSINESS COMPLEX LLC  
Contact Type: Not reported  
Contact Name: CHRISTOPHER MURGIA  
Address1: Not reported  
Address2: Not reported  
City: Not reported  
State: NN

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Zip Code: Not reported  
Country Code: 999  
Phone: (315) 481-7096  
EMail: Not reported  
Fax Number: Not reported  
Modified By: KCKEMP  
Date Last Modified: 2015-05-08

Site Id: 44599  
Affiliation Type: Facility Owner  
Company Name: CARRIER CIRCLE BUSINESS COMPLEX LLC  
Contact Type: REGIONAL MANAGER  
Contact Name: CHRISTOPHER MURGIA  
Address1: 475 OBERLIN AVE SOUTH - SUITE 206  
Address2: Not reported  
City: LAKEWOOD  
State: NJ  
Zip Code: 08701  
Country Code: 001  
Phone: (732) 461-4305  
EMail: Not reported  
Fax Number: Not reported  
Modified By: KCKEMP  
Date Last Modified: 2017-11-15

Tank Info:

Tank Number: 001  
Tank ID: 128001  
Tank Status: Closed Prior to Micro Conversion, 03/91  
Material Name: Closed Prior to Micro Conversion, 03/91  
Capacity Gallons: 8000  
Install Date: 08/01/1984  
Date Tank Closed: Not reported  
Registered: True  
Tank Location: Underground  
Tank Type: Steel/carbon steel  
Material Code: 9999  
Common Name of Substance: Other

Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: TRANSLAT  
Last Modified: 04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)  
H00 - Tank Leak Detection - None  
B00 - Tank External Protection - None  
C00 - Pipe Location - No Piping  
D02 - Pipe Type - Galvanized Steel  
F00 - Pipe External Protection - None  
G00 - Tank Secondary Containment - None  
J02 - Dispenser - Suction Dispenser  
A00 - Tank Internal Protection - None

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Tank Number: 002  
Tank ID: 128002  
Tank Status: Closed Prior to Micro Conversion, 03/91  
Material Name: Closed Prior to Micro Conversion, 03/91  
Capacity Gallons: 8000  
Install Date: 08/01/1984  
Date Tank Closed: Not reported  
Registered: True  
Tank Location: Underground  
Tank Type: Steel/carbon steel  
Material Code: 9999  
Common Name of Substance: Other

Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: TRANSLAT  
Last Modified: 04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)  
H00 - Tank Leak Detection - None  
G00 - Tank Secondary Containment - None  
J02 - Dispenser - Suction Dispenser  
A00 - Tank Internal Protection - None  
F00 - Pipe External Protection - None  
B00 - Tank External Protection - None  
C00 - Pipe Location - No Piping  
D02 - Pipe Type - Galvanized Steel

Tank Number: 003  
Tank ID: 128003  
Tank Status: Closed Prior to Micro Conversion, 03/91  
Material Name: Closed Prior to Micro Conversion, 03/91  
Capacity Gallons: 8000  
Install Date: Not reported  
Date Tank Closed: Not reported  
Registered: True  
Tank Location: Underground  
Tank Type: Steel/carbon steel  
Material Code: 9999  
Common Name of Substance: Other

Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: TRANSLAT  
Last Modified: 04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)  
B00 - Tank External Protection - None  
C00 - Pipe Location - No Piping  
D02 - Pipe Type - Galvanized Steel  
F00 - Pipe External Protection - None  
H00 - Tank Leak Detection - None  
G00 - Tank Secondary Containment - None

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

J02 - Dispenser - Suction Dispenser  
A00 - Tank Internal Protection - None

Tank Number: 004  
Tank ID: 128004  
Tank Status: Closed Prior to Micro Conversion, 03/91  
Material Name: Closed Prior to Micro Conversion, 03/91  
Capacity Gallons: 8000  
Install Date: Not reported  
Date Tank Closed: Not reported  
Registered: True  
Tank Location: Underground  
Tank Type: Steel/carbon steel  
Material Code: 9999  
Common Name of Substance: Other

Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: TRANSLAT  
Last Modified: 04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)  
H00 - Tank Leak Detection - None  
B00 - Tank External Protection - None  
C00 - Pipe Location - No Piping  
D02 - Pipe Type - Galvanized Steel  
F00 - Pipe External Protection - None  
G00 - Tank Secondary Containment - None  
J02 - Dispenser - Suction Dispenser  
A00 - Tank Internal Protection - None

Tank Number: 005  
Tank ID: 128005  
Tank Status: Closed Prior to Micro Conversion, 03/91  
Material Name: Closed Prior to Micro Conversion, 03/91  
Capacity Gallons: 10000  
Install Date: Not reported  
Date Tank Closed: Not reported  
Registered: True  
Tank Location: Underground  
Tank Type: Steel/carbon steel  
Material Code: 0001  
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: TRANSLAT  
Last Modified: 04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)  
H00 - Tank Leak Detection - None  
G00 - Tank Secondary Containment - None

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

J02 - Dispenser - Suction Dispenser  
A00 - Tank Internal Protection - None  
D02 - Pipe Type - Galvanized Steel  
F00 - Pipe External Protection - None  
B00 - Tank External Protection - None  
C00 - Pipe Location - No Piping

Tank Number: 006  
Tank ID: 128006  
Tank Status: Closed Prior to Micro Conversion, 03/91  
Material Name: Closed Prior to Micro Conversion, 03/91  
Capacity Gallons: 10000  
Install Date: Not reported  
Date Tank Closed: Not reported  
Registered: True  
Tank Location: Underground  
Tank Type: Steel/carbon steel  
Material Code: 0001  
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: TRANSLAT  
Last Modified: 04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)  
H00 - Tank Leak Detection - None  
J02 - Dispenser - Suction Dispenser  
G00 - Tank Secondary Containment - None  
A00 - Tank Internal Protection - None  
C00 - Pipe Location - No Piping  
D02 - Pipe Type - Galvanized Steel  
F00 - Pipe External Protection - None  
B00 - Tank External Protection - None

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

LX2374  
East  
> 1  
2.120 mi.  
11195 ft.

CARRIER CORP  
6500 CHRYSLER DR  
SYRACUSE, NY  
  
Site 10 of 19 in cluster LX

NY LTANKS  
NY Spills

S102666543  
N/A

Relative:  
Higher  
  
Actual:  
400 ft.

LTANKS:

Spill Number/Closed Date: 9700279 / 1997-06-30  
Facility ID: 9700279  
Site ID: 211667  
Spill Date: 1997-04-05  
Spill Cause: Tank Overfill  
Spill Source: Major Facility (MOSF) > 400,000 gal  
Spill Class: C3  
Cleanup Ceased: Not reported  
SWIS: 3415  
Investigator: CFMANNES  
Referred To: Not reported  
Reported to Dept: 1997-04-05  
CID: 370  
Water Affected: Not reported  
Spill Notifier: Responsible Party  
Last Inspection: Not reported  
Recommended Penalty: False  
Meets Standard: False  
UST Involvement: False  
Remediation Phase: 0  
Date Entered In Computer: 1997-04-05  
Spill Record Last Update: 1997-04-05  
Spiller Name: ABOVE  
Spiller Company: CARRIER  
Spiller Address: 6500 CHRYSLER  
Spiller County: 001  
Spiller Contact: ABOVE  
Spiller Phone: Not reported  
Spiller Extension: Not reported  
DEC Region: 7  
DER Facility ID: 266413  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was CM "  
  
Remarks: "OVERFILL OF TEST UNIT SPILL CONTAINED TO CONCRETE PAD SPILL CLEANED"

SPILLS:

Spill Number/Closed Date: 9902482 / 1999-07-02  
Facility ID: 9902482  
Facility Type: ER  
DER Facility ID: 266413  
Site ID: 331247  
DEC Region: 7  
Spill Cause: Equipment Failure  
Spill Class: D5  
SWIS: 3415  
  
Spill Date: 1999-06-03  
Investigator: CFMANNES  
Referred To: Not reported  
Reported to Dept: 1999-06-03  
CID: 388  
Water Affected: Not reported  
Spill Source: Commercial/Industrial

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-06-03
Spill Record Last Update:	1999-07-02
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was CM REFER TO DIV. AIR"
Remarks:	"caller reports fatigue failure on one of the copper tubes."
All Materials:	
Site ID:	331247
Operable Unit ID:	1081413
Operable Unit:	01
Material ID:	305988
Material Code:	1350A
Material Name:	chlorodifluoromethane
Case No.:	00075456
Material FA:	Hazardous Material
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**LX2375**     **CARRIER CORP. CARLYLE COMPRESSOR DIV.**  
**East**       **6500 CHRYSLER DR**  
**> 1**         **SYRACUSE, NY 13221**  
**2.120 mi.**  
**11195 ft.**     **Site 11 of 19 in cluster LX**

**FINDS**     **1016297704**  
                 **N/A**

**Relative:**  
**Higher**

FINDS:

**Actual:**  
**400 ft.**

Registry ID:

110011779156

Environmental Interest/Information System

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.



Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**LX2376**  
**East**  
**> 1**  
**2.120 mi.**  
**11195 ft.**  
**Relative:**  
**Higher**  
**Actual:**  
**400 ft.**

**CARRIER-CARLYLE COMPRESSORS**  
**6500 NEW VENTURE GEAR DRIVE**  
**DEWITT, NY**  
**Site 12 of 19 in cluster LX**  
**VAPOR REOPENED:**  
Site Code: 734068  
Facility Status: Complete (Mitigate)

**NY VAPOR REOPENED**

**S106780982**  
**N/A**

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**LX2377**  
**East**  
**> 1**  
**2.120 mi.**  
**11195 ft.**  
**Site 13 of 19 in cluster LX**

**Relative:**  
**Higher**

EDR Hist Auto

**Actual:**  
**400 ft.**

Year: Name:  
2009 FASTRAC PROPERTIES II LLC

Type:  
Convenience Stores

**EDR Hist Auto** **1020897278**  
**N/A**

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**LX2378**      **CARLYLE COMPRESSOR CO DIV CARRIER CORP**  
**East**        **6500 CHRYSLER DR**  
**> 1**          **DEWITT, NY 13214**  
**2.120 mi.**  
**11195 ft.**    **Site 14 of 19 in cluster LX**

**NY AIRS**    **S121491804**  
                 **N/A**

**Relative:**  
**Higher**

AIRS:

**Actual:**  
**400 ft.**

Permit Type:	AFR
Permit Status:	Expired
Issue Date:	12/30/1998
Expiration Date:	12/31/2000
County Fips:	Not reported
DEC Id:	7312600017
Emission Unit Id:	Not reported
Process Id:	Not reported
Contaminant Name/cas:	Not reported
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	Not reported
Unit:	Not reported
Auth Type Code:	7
Latitude:	Not reported
Longitude:	Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

**LX2379**  
**East**  
**> 1**  
**2.120 mi.**  
**11195 ft.**

**CARRIER CORP**  
**6500 NEW VENTURE GEAR DR**  
**SYRACUSE, NY**

**NY Spills** **S104284857**  
**N/A**

**Site 15 of 19 in cluster LX**

**Relative:**  
**Higher**

**Actual:**  
**400 ft.**

**SPILLS:**

Spill Number/Closed Date: 9911037 / 1999-12-20  
Facility ID: 9911037  
Facility Type: ER  
DER Facility ID: 111912  
Site ID: 129847  
DEC Region: 7  
Spill Cause: Equipment Failure  
Spill Class: C4  
SWIS: 3415  
Spill Date: 1999-12-17  
Investigator: HDWARNER  
Referred To: Not reported  
Reported to Dept: 1999-12-17  
CID: 257  
Water Affected: Not reported  
Spill Source: Commercial/Industrial  
Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 1999-12-17  
Spill Record Last Update: 1999-12-20  
Spiller Name: CALLER  
Spiller Company: CARRIER CORP  
Spiller Address: 6500 NEW VENTURE GEAR DR  
Spiller Company: 001  
Contact Name: CARLA DESILVIO  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was  
HW COPY OF REPORT SENT TO AIR PROGRAM."  
Remarks: "mechanical failure"

**All Materials:**

Site ID: 129847  
Operable Unit ID: 1089726  
Operable Unit: 01  
Material ID: 296508  
Material Code: 0050A  
Material Name: freon  
Case No.: Not reported  
Material FA: Other  
Quantity: 50.00  
Units: L  
Recovered: .00  
Oxygenate: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**LX2380**  
**East**  
**> 1**  
**2.120 mi.**  
**11195 ft.**

**CARRIER CIRCLE BUSINESS COMPLEX**  
**6500 NEW VENTURE GEAR DR**  
**EAST SYRACUSE, NY 13057**

**NY AST**

**U003077837**  
**N/A**

**Site 16 of 19 in cluster LX**

**Relative:**  
**Higher**

**AST:**

**Actual:**  
**400 ft.**

Region: STATE  
DEC Region: 7  
Site Status: Active  
Facility Id: 7-123927  
Program Type: PBS  
UTM X: 412701.74027  
UTM Y: 4771255.02759  
Expiration Date: 01/14/2023  
Site Type: Manufacturing (Other than Chemical)/Processing

**Affiliation Records:**

Site Id: 44599  
Affiliation Type: Mail Contact  
Company Name: CARRIER CIRCLE BUSINESS COMPLEX LLC  
Contact Type: Not reported  
Contact Name: ABE WILHELM  
Address1: 475 OBERLIN AVE SOUTH - SUITE 206  
Address2: Not reported  
City: LAKEWOOD  
State: NJ  
Zip Code: 08701  
Country Code: 001  
Phone: (732) 461-4305  
EMail: ABE@VINTAGEMGT.COM  
Fax Number: Not reported  
Modified By: KCKEMP  
Date Last Modified: 2017-11-15

Site Id: 44599  
Affiliation Type: Facility Operator  
Company Name: CARRIER CIRCLE BUSINESS COMPLEX  
Contact Type: Not reported  
Contact Name: CARRIER CIRCLE BUSINESS COMPLEX LLC  
Address1: Not reported  
Address2: Not reported  
City: Not reported  
State: NN  
Zip Code: Not reported  
Country Code: 001  
Phone: (315) 432-5451  
EMail: Not reported  
Fax Number: Not reported  
Modified By: KCKEMP  
Date Last Modified: 2015-05-08

Site Id: 44599  
Affiliation Type: Emergency Contact  
Company Name: CARRIER CIRCLE BUSINESS COMPLEX LLC  
Contact Type: Not reported  
Contact Name: CHRISTOPHER MURGIA  
Address1: Not reported  
Address2: Not reported  
City: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

State: NN  
Zip Code: Not reported  
Country Code: 999  
Phone: (315) 481-7096  
EMail: Not reported  
Fax Number: Not reported  
Modified By: KCKEMP  
Date Last Modified: 2015-05-08

Site Id: 44599  
Affiliation Type: Facility Owner  
Company Name: CARRIER CIRCLE BUSINESS COMPLEX LLC  
Contact Type: REGIONAL MANAGER  
Contact Name: CHRISTOPHER MURGIA  
Address1: 475 OBERLIN AVE SOUTH - SUITE 206  
Address2: Not reported  
City: LAKEWOOD  
State: NJ  
Zip Code: 08701  
Country Code: 001  
Phone: (732) 461-4305  
EMail: Not reported  
Fax Number: Not reported  
Modified By: KCKEMP  
Date Last Modified: 2017-11-15

Tank Info:

Tank Number: 007  
Tank Id: 128007  
Material Code: 9999  
Common Name of Substance: Other

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)  
B00 - Tank External Protection - None  
C00 - Pipe Location - No Piping  
F00 - Pipe External Protection - None  
G00 - Tank Secondary Containment - None  
J02 - Dispenser - Suction Dispenser  
A00 - Tank Internal Protection - None  
D01 - Pipe Type - Steel/Carbon Steel/Iron  
H99 - Tank Leak Detection - Other

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.

Tank Type: Steel/Carbon Steel/Iron  
Tank Status: Closed - Removed  
Pipe Model: Not reported  
Install Date: 07/01/1987  
Capacity Gallons: 8000  
Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Date Tank Closed: Not reported  
Register: True  
Modified By: TRANSLAT

Last Modified: 04/14/2017  
Material Name: other

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Tank Number: 008  
Tank Id: 128008  
Material Code: 9999  
Common Name of Substance: Other

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)  
J02 - Dispenser - Suction Dispenser  
G00 - Tank Secondary Containment - None  
D01 - Pipe Type - Steel/Carbon Steel/Iron  
A00 - Tank Internal Protection - None  
C00 - Pipe Location - No Piping  
F00 - Pipe External Protection - None  
B00 - Tank External Protection - None  
H99 - Tank Leak Detection - Other

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.

Tank Type: Steel/Carbon Steel/Iron  
Tank Status: Closed - Removed  
Pipe Model: Not reported  
Install Date: 07/01/1987  
Capacity Gallons: 8000  
Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Date Tank Closed: Not reported  
Register: True  
Modified By: TRANSLAT  
Last Modified: 04/14/2017  
Material Name: other

Tank Number: 009  
Tank Id: 128009  
Material Code: 0001  
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

H00 - Tank Leak Detection - None  
I02 - Overfill - High Level Alarm  
L09 - Piping Leak Detection - Exempt Suction Piping  
G01 - Tank Secondary Containment - Diking (Aboveground)  
C01 - Pipe Location - Aboveground  
I04 - Overfill - Product Level Gauge (A/G)  
J02 - Dispenser - Suction Dispenser  
A00 - Tank Internal Protection - None  
B01 - Tank External Protection - Painted/Asphalt Coating  
D01 - Pipe Type - Steel/Carbon Steel/Iron  
F01 - Pipe External Protection - Painted/Asphalt Coating

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.

Tank Type: Steel/Carbon Steel/Iron  
Tank Status: In Service  
Pipe Model: Not reported  
Install Date: 07/01/1987  
Capacity Gallons: 10000  
Tightness Test Method: NN  
Date Test: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Next Test Date: Not reported  
Date Tank Closed: Not reported  
Register: True  
Modified By: KCKEMP  
Last Modified: 04/14/2017  
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 010  
Tank Id: 128010  
Material Code: 0001  
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground  
I04 - Overfill - Product Level Gauge (A/G)  
G01 - Tank Secondary Containment - Diking (Aboveground)  
H00 - Tank Leak Detection - None  
I02 - Overfill - High Level Alarm  
L09 - Piping Leak Detection - Exempt Suction Piping  
J02 - Dispenser - Suction Dispenser  
A00 - Tank Internal Protection - None  
B01 - Tank External Protection - Painted/Asphalt Coating  
D01 - Pipe Type - Steel/Carbon Steel/Iron  
F01 - Pipe External Protection - Painted/Asphalt Coating

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.

Tank Type: Steel/Carbon Steel/Iron  
Tank Status: In Service  
Pipe Model: Not reported  
Install Date: 07/01/1987  
Capacity Gallons: 10000  
Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Date Tank Closed: Not reported  
Register: True  
Modified By: KCKEMP  
Last Modified: 04/14/2017  
Material Name: #2 fuel oil (on-site consumption)



Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

LX2381  
East  
> 1  
2.120 mi.  
11195 ft.

CARRIER CORP CARLYLE COMPRESSOR DIV  
6500 CHRYSLER DR  
DE WITT, NY 13214

Site 17 of 19 in cluster LX

Relative:  
Higher

FINDS:

Actual:  
400 ft.

Registry ID: 110064315030

Environmental Interest/Information System

US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

Registry ID: 110019426691

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1007780207  
Registry ID: 110019426691  
DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110019426691>

Envid: 1007780207  
Registry ID: 110064315030  
DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110064315030>

FINDS  
ECHO 1007780207  
N/A

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**LX2382**  
**East**  
**> 1**  
**2.120 mi.**  
**11195 ft.**

**ADVANCED MOTORS & DRIVES**  
**6500 NEW VENTURE DEAR DR**  
**EAST SYRACUSE, NY 13057**

**FINDS**  
**ECHO**

**1016008578**  
**N/A**

**Relative:**  
**Higher**

FINDS:

**Actual:**  
**400 ft.**

Registry ID:

110055010232

Environmental Interest/Information System

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:

1016008578

Registry ID:

110055010232

DFR URL:

<http://echo.epa.gov/detailed-facility-report?fid=110055010232>

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**LX2383**  
**East**  
**> 1**  
**2.120 mi.**  
**11195 ft.**

**SULLIVAN, BAZINET, BONGIO INC.**  
**6500 NEW VENTURE GEAR DRIVE**  
**EAST SYRACUSE, NY 13057**

**FINDS** **1024382331**  
**N/A**

**11195 ft.** **Site 19 of 19 in cluster LX**

**Relative:**  
**Higher**

FINDS:

**Actual:**  
**400 ft.**

Registry ID: 110070286668

Environmental Interest/Information System  
OSHA ESTABLISHMENT

[Click this hyperlink](#) while viewing on your computer to access  
additional FINDS: detail in the EDR Site Report.

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**ML2469**  
**East**  
**> 1**  
**2.148 mi.**  
**11340 ft.**

**CARRIER CORPORATION**  
**CHRYSLER DRIVE LAB**  
**SYRACUSE, NY**

**NY Spills** **S104283288**  
**N/A**

**Site 8 of 40 in cluster ML**

**Relative:**  
**Higher**

**Actual:**  
**404 ft.**

**SPILLS:**

Spill Number/Closed Date: 9908891 / 1999-10-25  
Facility ID: 9908891  
Facility Type: ER  
DER Facility ID: 258174  
Site ID: 320440  
DEC Region: 7  
Spill Cause: Equipment Failure  
Spill Class: C4  
SWIS: 3415  
Spill Date: 1999-10-21  
Investigator: MENASH  
Referred To: Not reported  
Reported to Dept: 1999-10-21  
CID: 281  
Water Affected: Not reported  
Spill Source: Commercial/Industrial  
Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 1999-10-21  
Spill Record Last Update: 1999-10-25  
Spiller Name: BETH HUBBEN  
Spiller Company: CARRIER CORPORATION  
Spiller Address: CARRIER PARKWAY PO BX4808  
Spiller Company: 001  
Contact Name: BETH HUBBEN  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was  
MN "  
Remarks: "VALVE FAILURE AT ABOVE LOCATION CAUSED RELEASE OF PRODUCT. SPILL  
ESTIMATED BETWEEN 1-15 LBS. NO RECOVERY EXPECTED AND REPAIRS ARE TO  
BE MADE. NO CALL BACK REQUESTED."

**All Materials:**

Site ID: 320440  
Operable Unit ID: 1083164  
Operable Unit: 01  
Material ID: 297990  
Material Code: 1350A  
Material Name: chlorodifluoromethane  
Case No.: 00075456  
Material FA: Hazardous Material  
Quantity: .00  
Units: G  
Recovered: .00  
Oxygenate: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

**ML2478**  
**East**  
**> 1**  
**2.148 mi.**  
**11340 ft.**

**CARLYLE COMP PLANT**  
**6500 NEW PROCESS GEAR DR**  
**SYRACUSE, NY**

**NY Spills** **S104284901**  
**N/A**

**Site 17 of 40 in cluster ML**

**Relative:**  
**Higher**

**Actual:**  
**404 ft.**

**SPILLS:**

Spill Number/Closed Date: 9911092 / 1999-12-20  
Facility ID: 9911092  
Facility Type: ER  
DER Facility ID: 216326  
Site ID: 265489  
DEC Region: 7  
Spill Cause: Equipment Failure  
Spill Class: D5  
SWIS: 3415  
Spill Date: 1999-12-17  
Investigator: CFMANNES  
Referred To: Not reported  
Reported to Dept: 1999-12-20  
CID: 388  
Water Affected: Not reported  
Spill Source: Commercial/Industrial  
  
Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 1999-12-20  
Spill Record Last Update: 1999-12-20  
Spiller Name: CALLER  
Spiller Company: CARRIER CORP  
Spiller Address: 6500 NEW VENTURE GEAR DR  
Spiller Company: 001  
Contact Name: CALLER  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was  
CM REFERRED TO DIV. OF AIR."  
  
Remarks: "caller reports release to air due to ruptured pipe. pipe has been  
fixed."

**All Materials:**

Site ID: 265489  
Operable Unit ID: 1089795  
Operable Unit: 01  
Material ID: 296561  
Material Code: 0050A  
Material Name: freon  
Case No.: Not reported  
Material FA: Other  
Quantity: 200.00  
Units: L  
Recovered: .00  
Oxygenate: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**ML2484**  
**East**  
**> 1**  
**2.148 mi.**  
**11340 ft.**

**CARRIER CORP**  
**NEW VENTURE GEAR DR**  
**EAST SYRACUSE, NY**

**NY Spills** **S104651948**  
**N/A**

**Site 23 of 40 in cluster ML**

**Relative:**  
**Higher**

**Actual:**  
**404 ft.**

**SPILLS:**

Spill Number/Closed Date: 0000749 / 2000-05-18  
Facility ID: 0000749  
Facility Type: ER  
DER Facility ID: 80724  
Site ID: 88219  
DEC Region: 7  
Spill Cause: Human Error  
Spill Class: C4  
SWIS: 3400  
Spill Date: 2000-04-19  
Investigator: HDWARNER  
Referred To: Not reported  
Reported to Dept: 2000-04-19  
CID: 390  
Water Affected: Not reported  
Spill Source: Major Facility (MOSF) > 400,000 gal  
Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2000-04-19  
Spill Record Last Update: 2000-05-18  
Spiller Name: CALLER  
Spiller Company: CARRIER CORP  
Spiller Address: CARRIER CORP PARK  
Spiller Company: 001  
Contact Name: PHILLIP TALUCCI  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was  
HW "  
Remarks: "TECHNICIAN FORGOT TO TIGHTEN A FITTING TO THE RECOVERY TANK AND WHEN  
THE VALVE WAS OPENED, THERE WAS A RELEASE OF PRODUCT"

**All Materials:**

Site ID: 88219  
Operable Unit ID: 822476  
Operable Unit: 01  
Material ID: 288988  
Material Code: 0777A  
Material Name: chlorofluoromethane  
Case No.: Not reported  
Material FA: Other  
Quantity: 20.00  
Units: L  
Recovered: .00  
Oxygenate: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**ML2485**  
**East**  
**> 1**  
**2.148 mi.**  
**11340 ft.**

**SAUNDERS CREEK**  
**CHRYSLER DR - CARLISLE CMP**  
**SYRACUSE, NY**

**NY Spills** **S102166240**  
**N/A**

**Site 24 of 40 in cluster ML**

**Relative:**  
**Higher**

**Actual:**  
**404 ft.**

**SPILLS:**

Spill Number/Closed Date: 8805672 / 1988-10-06  
Facility ID: 8805672  
Facility Type: ER  
DER Facility ID: 70565  
Site ID: 75389  
DEC Region: 7  
Spill Cause: Unknown  
Spill Class: Not reported  
SWIS: 3415  
Spill Date: 1988-09-30  
Investigator: AJMARSCH  
Referred To: Not reported  
Reported to Dept: 1988-10-04  
CID: Not reported  
Water Affected: SAUNDERS CREEK  
Spill Source: Unknown  
Spill Notifier: Local Agency  
Cleanup Ceased: 1988-10-06  
Cleanup Meets Std: True  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 1988-10-05  
Spill Record Last Update: 1988-10-14  
Spiller Name: Not reported  
Spiller Company: UNKNOWN  
Spiller Address: Not reported  
Spiller Company: 999  
Contact Name: Not reported  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was  
JM 10/06/88: NO OIL WAS FOUND IN STREAM. "  
Remarks: "OIL IN CREEK."

**All Materials:**

Site ID: 75389  
Operable Unit ID: 922636  
Operable Unit: 01  
Material ID: 457579  
Material Code: 0066A  
Material Name: unknown petroleum  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: .00  
Units: Not reported  
Recovered: .00  
Oxygenate: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**LX2369**  
**East**  
**> 1**  
**2.120 mi.**  
**11195 ft.**

**UNITED TECHNOLOGIES CARLYLE COMPRESSOR**  
**6500 CHRYSLER DRIVE**  
**SYRACUSE, NY 13221**

**NY MANIFEST**

**S122482286**  
**N/A**

**Relative:**  
**Higher**

**Actual:**  
**400 ft.**

NY MANIFEST:

Country: USA  
EPA ID: NYD000688796  
Facility Status: Not reported  
Location Address 1: 6500 CHRYSLER DR  
Code: BP  
  
Location Address 2: Not reported  
Total Tanks: Not reported  
Location City: TOWN OF DEWITT  
Location State: NY  
Location Zip: 13221  
Location Zip 4: Not reported

NY MANIFEST:

EPAID: NYD000688796  
Mailing Name: UNITED TECHNOLOGIES CARLYLE COMPRESSOR  
Mailing Contact: BETH HUBBEN  
Mailing Address 1: 6500 CHRYSLER DR-BLDG TR4  
Mailing Address 2: Not reported  
Mailing City: DEWITT  
Mailing State: NY  
Mailing Zip: 13221  
Mailing Zip 4: Not reported  
Mailing Country: USA  
Mailing Phone: 3154326776

NY MANIFEST:

Document ID: Not reported  
Manifest Status: Not reported  
seq: Not reported  
Year: 2012  
Trans1 State ID: TXR000050930  
Trans2 State ID: Not reported  
Generator Ship Date: 05/23/2012  
Trans1 Recv Date: 05/23/2012  
Trans2 Recv Date: Not reported  
TSD Site Recv Date: 06/04/2012  
Part A Recv Date: Not reported  
Part B Recv Date: Not reported  
Generator EPA ID: NYD000688796  
Trans1 EPA ID: Not reported  
Trans2 EPA ID: Not reported  
TSD ID 1: NJD002182897  
TSD ID 2: Not reported  
Manifest Tracking Number: 002931852SKS  
Import Indicator: N  
Export Indicator: N  
Discr Quantity Indicator: N  
Discr Type Indicator: N  
Discr Residue Indicator: N  
Discr Partial Reject Indicator: N  
Discr Full Reject Indicator: N  
Manifest Ref Number: Not reported  
Alt Facility RCRA ID: Not reported



Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Alt Facility Sign Date:	Not reported
MGMT Method Type Code:	H141
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	30.0
Units:	P - Pounds
Number of Containers:	1.0
Container Type:	DM - Metal drums, barrels
Handling Method:	L Landfill.
Specific Gravity:	1.0
Waste Code:	D002
Waste Code 1_2:	Not reported
Waste Code 1_3:	Not reported
Waste Code 1_4:	Not reported
Waste Code 1_5:	Not reported
Waste Code 1_6:	Not reported

[Click this hyperlink](#) while viewing on your computer to access  
-1 additional NY MANIFEST: record(s) in the EDR Site Report.

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

	Site	Database(s)	
<b>LX2370</b>	<b>CARRIER-CARLYLE COMPRESSORS</b>	<b>NY RGA HWS</b>	<b>S114963511</b>
<b>East</b>	<b>6500 NEW VENTURE GEAR DRIVE</b>		<b>N/A</b>
<b>&gt; 1</b>	<b>DEWITT, NY</b>		
<b>2.120 mi.</b>	<b>Site 6 of 19 in cluster LX</b>		
<b>11195 ft.</b>			
<b>Relative:</b>	RGA HWS:		
<b>Higher</b>	2012 CARRIER-CARLYLE COMPRESSORS	6500 NEW VENTURE GEAR DRIVE	
<b>Actual:</b>	2011 CARRIER-CARLYLE COMPRESSORS	6500 NEW VENTURE GEAR DRIVE	
<b>400 ft.</b>	2010 CARRIER-CARLYLE COMPRESSORS	6500 NEW VENTURE GEAR DRIVE	

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

LX2371  
East  
> 1  
2.120 mi.  
11195 ft.

**FASTRAC MARKETS LLC**  
**6500 NEW VENTURE GEAR DR**  
**EAST SYRACUSE, NY 13057**

**Site 7 of 19 in cluster LX**

**EDR Hist Auto**

**1020199349**  
**N/A**

**Relative:**  
**Higher**

EDR Hist Auto

**Actual:**  
**400 ft.**

Year:

Name:

Type:

2008 FASTRAC MARKET LLC  
2009 FASTRAC MARKET LLC  
2010 FASTRAC MARKETS LLC  
2010 FASTRAC PROPERTIES II LLC  
2011 FASTRAC PROPERTIES II LLC  
2011 FASTRAC MARKETS LLC  
2012 FASTRAC PROPERTIES II LLC  
2012 FASTRAC MARKETS LLC  
2013 FASTRAC PROPERTIES II LLC  
2013 FASTRAC MARKETS LLC  
2014 FASTRAC MARKETS LLC  
2014 FASTRAC PROPERTIES II LLC

Gasoline Service Stations  
Gasoline Service Stations  
Convenience Stores  
Convenience Stores  
Convenience Stores  
Convenience Stores  
Convenience Stores  
Convenience Stores  
Convenience Stores  
Convenience Stores  
Convenience Stores  
Convenience Stores

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

LX2372  
East  
> 1  
2.120 mi.  
11195 ft.

**CARLYLE COMPRESSOR CO DIV CARRIER CORP**  
**6500 CHRYSLER DR**  
**DEWITT, NY 13214**

**RCRA NonGen / NLR**  
**FTTS**  
**HIST FTTS**

**1000293635**  
**NYD000688796**

**Site 8 of 19 in cluster LX**

**Relative:**  
**Higher**

RCRA NonGen / NLR:

**Actual:**  
**400 ft.**

Date form received by agency: 01/01/2007  
Facility name: CARLYLE COMPRESSOR CO DIV CARRIER CORP  
Facility address: 6500 CHRYSLER DR  
DEWITT, NY 13214  
EPA ID: NYD000688796  
Mailing address: PO BOX 4808 TR 4  
SYRACUSE, NY 13221  
Contact: Not reported  
Contact address: PO BOX 4808 TR 4  
SYRACUSE, NY 13221  
Contact country: US  
Contact telephone: Not reported  
Contact email: Not reported  
EPA Region: 02  
Land type: Facility is not located on Indian land. Additional information is not known.  
Classification: Non-Generator  
Description: Handler: Non-Generators do not presently generate hazardous waste

**Owner/Operator Summary:**

Owner/operator name: CARRIER CORP  
Owner/operator address: NOT REQUIRED  
NOT REQUIRED, WY 99999  
Owner/operator country: US  
Owner/operator telephone: 212-555-1212  
Owner/operator email: Not reported  
Owner/operator fax: Not reported  
Owner/operator extension: Not reported  
Legal status: Private  
Owner/Operator Type: Owner  
Owner/Op start date: Not reported  
Owner/Op end date: Not reported

Owner/operator name: CARRIER CORP  
Owner/operator address: NOT REQUIRED  
NOT REQUIRED, WY 99999  
Owner/operator country: US  
Owner/operator telephone: 212-555-1212  
Owner/operator email: Not reported  
Owner/operator fax: Not reported  
Owner/operator extension: Not reported  
Legal status: Private  
Owner/Operator Type: Operator  
Owner/Op start date: Not reported  
Owner/Op end date: Not reported

**Handler Activities Summary:**

U.S. importer of hazardous waste: No  
Mixed waste (haz. and radioactive): No  
Recycler of hazardous waste: No  
Transporter of hazardous waste: No  
Treater, storer or disposer of HW: No  
Underground injection activity: No

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

On-site burner exemption: No  
Furnace exemption: No  
Used oil fuel burner: No  
Used oil processor: No  
Used oil refiner: No  
Used oil fuel marketer to burner: No  
Used oil Specification marketer: No  
Used oil transfer facility: No  
Used oil transporter: No

Historical Generators:

Date form received by agency: 01/01/2006

Site name: CARLYLE COMPRESSOR CO DIV CARRIER CORP

Classification: Not a generator, verified

Date form received by agency: 07/08/1999

Site name: CARLYLE COMPRESSOR CO DIV CARRIER CORP

Classification: Not a generator, verified

Date form received by agency: 03/30/1994

Site name: UTC - CARLYLE COMPRESSOR

Classification: Large Quantity Generator

Date form received by agency: 02/27/1992

Site name: CARLYLE COMPRESSOR

Classification: Large Quantity Generator

Date form received by agency: 03/01/1990

Site name: UNITED TECHNOLOGIES CARLYLE COMPRESSOR

Classification: Large Quantity Generator

Date form received by agency: 08/18/1980

Site name: CARLYLE COMPRESSOR CO DIV CARRIER CORP

Classification: Large Quantity Generator

. Waste code: D000

. Waste name: Not Defined

. Waste code: D001

. Waste name: IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.

. Waste code: D002

. Waste name: A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.

. Waste code: F001

. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE,

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002  
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F017  
. Waste name: Not Defined

. Waste code: U226  
. Waste name: ETHANE, 1,1,1-TRICHLORO-

. Waste code: U228  
. Waste name: ETHENE, TRICHLORO-

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date: 06/22/1999  
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
Area of violation: Not reported  
Date achieved compliance: Not reported  
Evaluation lead agency: State

Evaluation date: 12/21/1988  
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
Area of violation: Not reported  
Date achieved compliance: Not reported  
Evaluation lead agency: State

Evaluation date: 09/03/1986  
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE  
Area of violation: Not reported  
Date achieved compliance: Not reported  
Evaluation lead agency: State

FTTS INSP:

Inspection Number: 198808223136 2  
Region: 02  
Inspection Date: 08/22/88  
Inspector: F. FREIHERR, LP  
Violation occurred: No

Investigation Type: Section 6 PCB Federal Conducted  
Investigation Reason: Neutral Scheme, Region  
Legislation Code: TSCA  
Facility Function: User

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

HIST FTTS INSP:

Inspection Number: 198808223136 2  
Region: 02  
Inspection Date: Not reported  
Inspector: F. FREIHERR, LP  
Violation occurred: No  
Investigation Type: Section 6 PCB Federal Conducted  
Investigation Reason: Neutral Scheme, Region  
Legislation Code: TSCA  
Facility Function: User

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

LX2373  
East  
> 1  
2.120 mi.  
11195 ft.

**CARRIER CIRCLE BUSINESS COMPLEX**  
**6500 NEW VENTURE GEAR DR**  
**EAST SYRACUSE, NY 13057**

NY UST

U004082186  
N/A

Relative:  
Higher

Actual:  
400 ft.

UST:

Id/Status: 7-123927 / Active  
Program Type: PBS  
Region: STATE  
DEC Region: 7  
Expiration Date: 01/14/2023  
UTM X: 412701.74027  
UTM Y: 4771255.02759  
Site Type: Manufacturing (Other than Chemical)/Processing

Affiliation Records:

Site Id: 44599  
Affiliation Type: Mail Contact  
Company Name: CARRIER CIRCLE BUSINESS COMPLEX LLC  
Contact Type: Not reported  
Contact Name: ABE WILHELM  
Address1: 475 OBERLIN AVE SOUTH - SUITE 206  
Address2: Not reported  
City: LAKEWOOD  
State: NJ  
Zip Code: 08701  
Country Code: 001  
Phone: (732) 461-4305  
EMail: ABE@VINTAGEMGT.COM  
Fax Number: Not reported  
Modified By: KCKEMP  
Date Last Modified: 2017-11-15

Site Id: 44599  
Affiliation Type: Facility Operator  
Company Name: CARRIER CIRCLE BUSINESS COMPLEX  
Contact Type: Not reported  
Contact Name: CARRIER CIRCLE BUSINESS COMPLEX LLC  
Address1: Not reported  
Address2: Not reported  
City: Not reported  
State: NN  
Zip Code: Not reported  
Country Code: 001  
Phone: (315) 432-5451  
EMail: Not reported  
Fax Number: Not reported  
Modified By: KCKEMP  
Date Last Modified: 2015-05-08

Site Id: 44599  
Affiliation Type: Emergency Contact  
Company Name: CARRIER CIRCLE BUSINESS COMPLEX LLC  
Contact Type: Not reported  
Contact Name: CHRISTOPHER MURGIA  
Address1: Not reported  
Address2: Not reported  
City: Not reported  
State: NN



Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Zip Code: Not reported  
Country Code: 999  
Phone: (315) 481-7096  
EMail: Not reported  
Fax Number: Not reported  
Modified By: KCKEMP  
Date Last Modified: 2015-05-08

Site Id: 44599  
Affiliation Type: Facility Owner  
Company Name: CARRIER CIRCLE BUSINESS COMPLEX LLC  
Contact Type: REGIONAL MANAGER  
Contact Name: CHRISTOPHER MURGIA  
Address1: 475 OBERLIN AVE SOUTH - SUITE 206  
Address2: Not reported  
City: LAKEWOOD  
State: NJ  
Zip Code: 08701  
Country Code: 001  
Phone: (732) 461-4305  
EMail: Not reported  
Fax Number: Not reported  
Modified By: KCKEMP  
Date Last Modified: 2017-11-15

Tank Info:

Tank Number: 001  
Tank ID: 128001  
Tank Status: Closed Prior to Micro Conversion, 03/91  
Material Name: Closed Prior to Micro Conversion, 03/91  
Capacity Gallons: 8000  
Install Date: 08/01/1984  
Date Tank Closed: Not reported  
Registered: True  
Tank Location: Underground  
Tank Type: Steel/carbon steel

Material Code: 9999  
Common Name of Substance: Other

Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: TRANSLAT  
Last Modified: 04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)  
H00 - Tank Leak Detection - None  
B00 - Tank External Protection - None  
C00 - Pipe Location - No Piping  
D02 - Pipe Type - Galvanized Steel  
F00 - Pipe External Protection - None  
G00 - Tank Secondary Containment - None  
J02 - Dispenser - Suction Dispenser  
A00 - Tank Internal Protection - None

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Tank Number: 002  
Tank ID: 128002  
Tank Status: Closed Prior to Micro Conversion, 03/91  
Material Name: Closed Prior to Micro Conversion, 03/91  
Capacity Gallons: 8000  
Install Date: 08/01/1984  
Date Tank Closed: Not reported  
Registered: True  
Tank Location: Underground  
Tank Type: Steel/carbon steel  
Material Code: 9999  
Common Name of Substance: Other

Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: TRANSLAT  
Last Modified: 04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)  
H00 - Tank Leak Detection - None  
G00 - Tank Secondary Containment - None  
J02 - Dispenser - Suction Dispenser  
A00 - Tank Internal Protection - None  
F00 - Pipe External Protection - None  
B00 - Tank External Protection - None  
C00 - Pipe Location - No Piping  
D02 - Pipe Type - Galvanized Steel

Tank Number: 003  
Tank ID: 128003  
Tank Status: Closed Prior to Micro Conversion, 03/91  
Material Name: Closed Prior to Micro Conversion, 03/91  
Capacity Gallons: 8000  
Install Date: Not reported  
Date Tank Closed: Not reported  
Registered: True  
Tank Location: Underground  
Tank Type: Steel/carbon steel  
Material Code: 9999  
Common Name of Substance: Other

Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: TRANSLAT  
Last Modified: 04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)  
B00 - Tank External Protection - None  
C00 - Pipe Location - No Piping  
D02 - Pipe Type - Galvanized Steel  
F00 - Pipe External Protection - None  
H00 - Tank Leak Detection - None  
G00 - Tank Secondary Containment - None

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

J02 - Dispenser - Suction Dispenser  
A00 - Tank Internal Protection - None

Tank Number: 004  
Tank ID: 128004  
Tank Status: Closed Prior to Micro Conversion, 03/91  
Material Name: Closed Prior to Micro Conversion, 03/91  
Capacity Gallons: 8000  
Install Date: Not reported  
Date Tank Closed: Not reported  
Registered: True  
Tank Location: Underground  
Tank Type: Steel/carbon steel  
Material Code: 9999  
Common Name of Substance: Other

Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: TRANSLAT  
Last Modified: 04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)  
H00 - Tank Leak Detection - None  
B00 - Tank External Protection - None  
C00 - Pipe Location - No Piping  
D02 - Pipe Type - Galvanized Steel  
F00 - Pipe External Protection - None  
G00 - Tank Secondary Containment - None  
J02 - Dispenser - Suction Dispenser  
A00 - Tank Internal Protection - None

Tank Number: 005  
Tank ID: 128005  
Tank Status: Closed Prior to Micro Conversion, 03/91  
Material Name: Closed Prior to Micro Conversion, 03/91  
Capacity Gallons: 10000  
Install Date: Not reported  
Date Tank Closed: Not reported  
Registered: True  
Tank Location: Underground  
Tank Type: Steel/carbon steel  
Material Code: 0001  
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: TRANSLAT  
Last Modified: 04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)  
H00 - Tank Leak Detection - None  
G00 - Tank Secondary Containment - None

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

J02 - Dispenser - Suction Dispenser  
A00 - Tank Internal Protection - None  
D02 - Pipe Type - Galvanized Steel  
F00 - Pipe External Protection - None  
B00 - Tank External Protection - None  
C00 - Pipe Location - No Piping

Tank Number: 006  
Tank ID: 128006  
Tank Status: Closed Prior to Micro Conversion, 03/91  
Material Name: Closed Prior to Micro Conversion, 03/91  
Capacity Gallons: 10000  
Install Date: Not reported  
Date Tank Closed: Not reported  
Registered: True  
Tank Location: Underground  
Tank Type: Steel/carbon steel  
Material Code: 0001  
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Pipe Model: Not reported  
Modified By: TRANSLAT  
Last Modified: 04/14/2017

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)  
H00 - Tank Leak Detection - None  
J02 - Dispenser - Suction Dispenser  
G00 - Tank Secondary Containment - None  
A00 - Tank Internal Protection - None  
C00 - Pipe Location - No Piping  
D02 - Pipe Type - Galvanized Steel  
F00 - Pipe External Protection - None  
B00 - Tank External Protection - None

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

LX2374  
East  
> 1  
2.120 mi.  
11195 ft.

CARRIER CORP  
6500 CHRYSLER DR  
SYRACUSE, NY  
  
Site 10 of 19 in cluster LX

NY LTANKS  
NY Spills

S102666543  
N/A

Relative:  
Higher  
  
Actual:  
400 ft.

LTANKS:

Spill Number/Closed Date: 9700279 / 1997-06-30  
Facility ID: 9700279  
Site ID: 211667  
Spill Date: 1997-04-05  
Spill Cause: Tank Overfill  
Spill Source: Major Facility (MOSF) > 400,000 gal  
Spill Class: C3  
Cleanup Ceased: Not reported  
SWIS: 3415  
Investigator: CFMANNES  
Referred To: Not reported  
Reported to Dept: 1997-04-05  
CID: 370  
Water Affected: Not reported  
Spill Notifier: Responsible Party  
Last Inspection: Not reported  
Recommended Penalty: False  
Meets Standard: False  
UST Involvement: False  
Remediation Phase: 0  
Date Entered In Computer: 1997-04-05  
Spill Record Last Update: 1997-04-05  
Spiller Name: ABOVE  
Spiller Company: CARRIER  
Spiller Address: 6500 CHRYSLER  
Spiller County: 001  
Spiller Contact: ABOVE  
Spiller Phone: Not reported  
Spiller Extension: Not reported  
DEC Region: 7  
DER Facility ID: 266413  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was CM "  
  
Remarks: "OVERFILL OF TEST UNIT SPILL CONTAINED TO CONCRETE PAD SPILL CLEANED"

SPILLS:

Spill Number/Closed Date: 9902482 / 1999-07-02  
Facility ID: 9902482  
Facility Type: ER  
DER Facility ID: 266413  
Site ID: 331247  
DEC Region: 7  
Spill Cause: Equipment Failure  
Spill Class: D5  
SWIS: 3415  
  
Spill Date: 1999-06-03  
Investigator: CFMANNES  
Referred To: Not reported  
Reported to Dept: 1999-06-03  
CID: 388  
Water Affected: Not reported  
Spill Source: Commercial/Industrial

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Spill Notifier:	Responsible Party
Cleanup Ceased:	Not reported
Cleanup Meets Std:	False
Last Inspection:	Not reported
Recommended Penalty:	False
UST Trust:	False
Remediation Phase:	0
Date Entered In Computer:	1999-06-03
Spill Record Last Update:	1999-07-02
Spiller Name:	Not reported
Spiller Company:	Not reported
Spiller Address:	Not reported
Spiller Company:	001
Contact Name:	CALLER
DEC Memo:	"Prior to Sept, 2004 data translation this spill Lead_DEC Field was CM REFER TO DIV. AIR"
Remarks:	"caller reports fatigue failure on one of the copper tubes."
All Materials:	
Site ID:	331247
Operable Unit ID:	1081413
Operable Unit:	01
Material ID:	305988
Material Code:	1350A
Material Name:	chlorodifluoromethane
Case No.:	00075456
Material FA:	Hazardous Material
Quantity:	.00
Units:	G
Recovered:	.00
Oxygenate:	Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**LX2375**     **CARRIER CORP. CARLYLE COMPRESSOR DIV.**  
**East**        **6500 CHRYSLER DR**  
**> 1**           **SYRACUSE, NY 13221**  
**2.120 mi.**  
**11195 ft.**     **Site 11 of 19 in cluster LX**

**FINDS**     **1016297704**  
                 **N/A**

**Relative:**  
**Higher**

FINDS:

**Actual:**  
**400 ft.**

Registry ID:

110011779156

Environmental Interest/Information System

NCDB (National Compliance Data Base) supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**LX2376**  
**East**  
**> 1**  
**2.120 mi.**  
**11195 ft.**  
**Relative:**  
**Higher**  
**Actual:**  
**400 ft.**

**CARRIER-CARLYLE COMPRESSORS**  
**6500 NEW VENTURE GEAR DRIVE**  
**DEWITT, NY**  
**Site 12 of 19 in cluster LX**  
VAPOR REOPENED:  
Site Code: 734068  
Facility Status: Complete (Mitigate)

**NY VAPOR REOPENED**

**S106780982**  
**N/A**



Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**LX2377**  
**East**  
**> 1**  
**2.120 mi.**  
**11195 ft.**  
**Site 13 of 19 in cluster LX**

**Relative:**  
**Higher**

EDR Hist Auto

**Actual:**  
**400 ft.**

Year: Name:  
2009 FASTRAC PROPERTIES II LLC

Type:  
Convenience Stores

**EDR Hist Auto** **1020897278**  
**N/A**

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**LX2378**      **CARLYLE COMPRESSOR CO DIV CARRIER CORP**  
**East**        **6500 CHRYSLER DR**  
**> 1**          **DEWITT, NY 13214**  
**2.120 mi.**  
**11195 ft.**    **Site 14 of 19 in cluster LX**

**NY AIRS**    **S121491804**  
                 **N/A**

**Relative:**  
**Higher**

AIRS:

**Actual:**  
**400 ft.**

Permit Type:	AFR
Permit Status:	Expired
Issue Date:	12/30/1998
Expiration Date:	12/31/2000
County Fips:	Not reported
DEC Id:	7312600017
Emission Unit Id:	Not reported
Process Id:	Not reported
Contaminant Name/cas:	Not reported
Epa Control Code:	Not reported
Contol Eff:	Not reported
Emissions:	Not reported
Unit:	Not reported
Auth Type Code:	7
Latitude:	Not reported
Longitude:	Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

**LX2379**  
**East**  
**> 1**  
**2.120 mi.**  
**11195 ft.**

**CARRIER CORP**  
**6500 NEW VENTURE GEAR DR**  
**SYRACUSE, NY**

**NY Spills** **S104284857**  
**N/A**

**Site 15 of 19 in cluster LX**

**Relative:**  
**Higher**

**Actual:**  
**400 ft.**

**SPILLS:**

Spill Number/Closed Date: 9911037 / 1999-12-20  
Facility ID: 9911037  
Facility Type: ER  
DER Facility ID: 111912  
Site ID: 129847  
DEC Region: 7  
Spill Cause: Equipment Failure  
Spill Class: C4  
SWIS: 3415  
Spill Date: 1999-12-17  
Investigator: HDWARNER  
Referred To: Not reported  
Reported to Dept: 1999-12-17  
CID: 257  
Water Affected: Not reported  
Spill Source: Commercial/Industrial  
Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 1999-12-17  
Spill Record Last Update: 1999-12-20  
Spiller Name: CALLER  
Spiller Company: CARRIER CORP  
Spiller Address: 6500 NEW VENTURE GEAR DR  
Spiller Company: 001  
Contact Name: CARLA DESILVIO  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was  
HW COPY OF REPORT SENT TO AIR PROGRAM."  
Remarks: "mechanical failure"

**All Materials:**

Site ID: 129847  
Operable Unit ID: 1089726  
Operable Unit: 01  
Material ID: 296508  
Material Code: 0050A  
Material Name: freon  
Case No.: Not reported  
Material FA: Other  
Quantity: 50.00  
Units: L  
Recovered: .00  
Oxygenate: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**LX2380**  
**East**  
**> 1**  
**2.120 mi.**  
**11195 ft.**

**CARRIER CIRCLE BUSINESS COMPLEX**  
**6500 NEW VENTURE GEAR DR**  
**EAST SYRACUSE, NY 13057**

**NY AST**

**U003077837**  
**N/A**

**Site 16 of 19 in cluster LX**

**Relative:**  
**Higher**

**AST:**

**Actual:**  
**400 ft.**

Region: STATE  
DEC Region: 7  
Site Status: Active  
Facility Id: 7-123927  
Program Type: PBS  
UTM X: 412701.74027  
UTM Y: 4771255.02759  
Expiration Date: 01/14/2023  
Site Type: Manufacturing (Other than Chemical)/Processing

**Affiliation Records:**

Site Id: 44599  
Affiliation Type: Mail Contact  
Company Name: CARRIER CIRCLE BUSINESS COMPLEX LLC  
Contact Type: Not reported  
Contact Name: ABE WILHELM  
Address1: 475 OBERLIN AVE SOUTH - SUITE 206  
Address2: Not reported  
City: LAKEWOOD  
State: NJ  
Zip Code: 08701  
Country Code: 001  
Phone: (732) 461-4305  
EMail: ABE@VINTAGEMGT.COM  
Fax Number: Not reported  
Modified By: KCKEMP  
Date Last Modified: 2017-11-15

Site Id: 44599  
Affiliation Type: Facility Operator  
Company Name: CARRIER CIRCLE BUSINESS COMPLEX  
Contact Type: Not reported  
Contact Name: CARRIER CIRCLE BUSINESS COMPLEX LLC  
Address1: Not reported  
Address2: Not reported  
City: Not reported  
State: NN  
Zip Code: Not reported  
Country Code: 001  
Phone: (315) 432-5451  
EMail: Not reported  
Fax Number: Not reported  
Modified By: KCKEMP  
Date Last Modified: 2015-05-08

Site Id: 44599  
Affiliation Type: Emergency Contact  
Company Name: CARRIER CIRCLE BUSINESS COMPLEX LLC  
Contact Type: Not reported  
Contact Name: CHRISTOPHER MURGIA  
Address1: Not reported  
Address2: Not reported  
City: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

State: NN  
Zip Code: Not reported  
Country Code: 999  
Phone: (315) 481-7096  
EMail: Not reported  
Fax Number: Not reported  
Modified By: KCKEMP  
Date Last Modified: 2015-05-08

Site Id: 44599  
Affiliation Type: Facility Owner  
Company Name: CARRIER CIRCLE BUSINESS COMPLEX LLC  
Contact Type: REGIONAL MANAGER  
Contact Name: CHRISTOPHER MURGIA  
Address1: 475 OBERLIN AVE SOUTH - SUITE 206  
Address2: Not reported  
City: LAKEWOOD  
State: NJ  
Zip Code: 08701  
Country Code: 001  
Phone: (732) 461-4305  
EMail: Not reported  
Fax Number: Not reported  
Modified By: KCKEMP  
Date Last Modified: 2017-11-15

Tank Info:

Tank Number: 007  
Tank Id: 128007  
Material Code: 9999  
Common Name of Substance: Other

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)  
B00 - Tank External Protection - None  
C00 - Pipe Location - No Piping  
F00 - Pipe External Protection - None  
G00 - Tank Secondary Containment - None  
J02 - Dispenser - Suction Dispenser  
A00 - Tank Internal Protection - None  
D01 - Pipe Type - Steel/Carbon Steel/Iron  
H99 - Tank Leak Detection - Other

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.

Tank Type: Steel/Carbon Steel/Iron  
Tank Status: Closed - Removed  
Pipe Model: Not reported  
Install Date: 07/01/1987  
Capacity Gallons: 8000  
Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Date Tank Closed: Not reported  
Register: True  
Modified By: TRANSLAT

Last Modified: 04/14/2017  
Material Name: other

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Tank Number: 008  
Tank Id: 128008  
Material Code: 9999  
Common Name of Substance: Other

Equipment Records:

I04 - Overfill - Product Level Gauge (A/G)  
J02 - Dispenser - Suction Dispenser  
G00 - Tank Secondary Containment - None  
D01 - Pipe Type - Steel/Carbon Steel/Iron  
A00 - Tank Internal Protection - None  
C00 - Pipe Location - No Piping  
F00 - Pipe External Protection - None  
B00 - Tank External Protection - None  
H99 - Tank Leak Detection - Other

Tank Location: Aboveground - contact with soil.... Tank bottom rests on soil, allowing no visual inspection.

Tank Type: Steel/Carbon Steel/Iron  
Tank Status: Closed - Removed  
Pipe Model: Not reported  
Install Date: 07/01/1987  
Capacity Gallons: 8000  
Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Date Tank Closed: Not reported  
Register: True  
Modified By: TRANSLAT  
Last Modified: 04/14/2017  
Material Name: other

Tank Number: 009  
Tank Id: 128009  
Material Code: 0001  
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

H00 - Tank Leak Detection - None  
I02 - Overfill - High Level Alarm  
L09 - Piping Leak Detection - Exempt Suction Piping  
G01 - Tank Secondary Containment - Diking (Aboveground)  
C01 - Pipe Location - Aboveground  
I04 - Overfill - Product Level Gauge (A/G)  
J02 - Dispenser - Suction Dispenser  
A00 - Tank Internal Protection - None  
B01 - Tank External Protection - Painted/Asphalt Coating  
D01 - Pipe Type - Steel/Carbon Steel/Iron  
F01 - Pipe External Protection - Painted/Asphalt Coating

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.

Tank Type: Steel/Carbon Steel/Iron  
Tank Status: In Service  
Pipe Model: Not reported  
Install Date: 07/01/1987  
Capacity Gallons: 10000  
Tightness Test Method: NN  
Date Test: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Next Test Date: Not reported  
Date Tank Closed: Not reported  
Register: True  
Modified By: KCKEMP  
Last Modified: 04/14/2017  
Material Name: #2 fuel oil (on-site consumption)

Tank Number: 010  
Tank Id: 128010  
Material Code: 0001  
Common Name of Substance: #2 Fuel Oil (On-Site Consumption)

Equipment Records:

C01 - Pipe Location - Aboveground  
I04 - Overfill - Product Level Gauge (A/G)  
G01 - Tank Secondary Containment - Diking (Aboveground)  
H00 - Tank Leak Detection - None  
I02 - Overfill - High Level Alarm  
L09 - Piping Leak Detection - Exempt Suction Piping  
J02 - Dispenser - Suction Dispenser  
A00 - Tank Internal Protection - None  
B01 - Tank External Protection - Painted/Asphalt Coating  
D01 - Pipe Type - Steel/Carbon Steel/Iron  
F01 - Pipe External Protection - Painted/Asphalt Coating

Tank Location: Aboveground - on saddles, legs, racks, etc.... Tank bottom is elevated above grade or tank pad, allowing visual inspection.

Tank Type: Steel/Carbon Steel/Iron  
Tank Status: In Service  
Pipe Model: Not reported  
Install Date: 07/01/1987  
Capacity Gallons: 10000  
Tightness Test Method: NN  
Date Test: Not reported  
Next Test Date: Not reported  
Date Tank Closed: Not reported  
Register: True  
Modified By: KCKEMP  
Last Modified: 04/14/2017  
Material Name: #2 fuel oil (on-site consumption)

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

LX2381  
East  
> 1  
2.120 mi.  
11195 ft.

CARRIER CORP CARLYLE COMPRESSOR DIV  
6500 CHRYSLER DR  
DE WITT, NY 13214

Site 17 of 19 in cluster LX

FINDS  
ECHO 1007780207  
N/A

Relative:  
Higher

FINDS:

Actual:  
400 ft.

Registry ID: 110064315030

Environmental Interest/Information System

US EPA TRIS (Toxics Release Inventory System) contains information from facilities on the amounts of over 300 listed toxic chemicals that these facilities release directly to air, water, land, or that are transported off-site.

Registry ID: 110019426691

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

FIS (New York - Facility Information System) is New York's Department of Environmental Conservation (DEC) information system for tracking environmental facility information found across the State.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1007780207  
Registry ID: 110019426691  
DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110019426691>

Envid: 1007780207  
Registry ID: 110064315030  
DFR URL: <http://echo.epa.gov/detailed-facility-report?fid=110064315030>



Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**LX2382**  
**East**  
**> 1**  
**2.120 mi.**  
**11195 ft.**

**ADVANCED MOTORS & DRIVES**  
**6500 NEW VENTURE DEAR DR**  
**EAST SYRACUSE, NY 13057**

**FINDS**  
**ECHO**

**1016008578**  
**N/A**

**Site 18 of 19 in cluster LX**

**Relative:**  
**Higher**

FINDS:

**Actual:**  
**400 ft.**

Registry ID:

110055010232

Environmental Interest/Information System

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

[Click this hyperlink](#) while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:

1016008578

Registry ID:

110055010232

DFR URL:

<http://echo.epa.gov/detailed-facility-report?fid=110055010232>

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

**LX2383**  
**East**  
**> 1**  
**2.120 mi.**  
**11195 ft.**

**SULLIVAN, BAZINET, BONGIO INC.**  
**6500 NEW VENTURE GEAR DRIVE**  
**EAST SYRACUSE, NY 13057**

**FINDS** **1024382331**  
**N/A**

**11195 ft.** **Site 19 of 19 in cluster LX**

**Relative:**  
**Higher**

FINDS:

**Actual:**  
**400 ft.**

Registry ID: 110070286668

Environmental Interest/Information System  
OSHA ESTABLISHMENT

[Click this hyperlink](#) while viewing on your computer to access  
additional FINDS: detail in the EDR Site Report.

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

**ML2478**  
**East**  
**> 1**  
**2.148 mi.**  
**11340 ft.**

**CARLYLE COMP PLANT**  
**6500 NEW PROCESS GEAR DR**  
**SYRACUSE, NY**

**NY Spills** **S104284901**  
**N/A**

**Site 17 of 40 in cluster ML**

**Relative:**  
**Higher**

**Actual:**  
**404 ft.**

**SPILLS:**

Spill Number/Closed Date: 9911092 / 1999-12-20  
Facility ID: 9911092  
Facility Type: ER  
DER Facility ID: 216326  
Site ID: 265489  
DEC Region: 7  
Spill Cause: Equipment Failure  
Spill Class: D5  
SWIS: 3415  
Spill Date: 1999-12-17  
Investigator: CFMANNES  
Referred To: Not reported  
Reported to Dept: 1999-12-20  
CID: 388  
Water Affected: Not reported  
Spill Source: Commercial/Industrial  
  
Spill Notifier: Responsible Party  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 1999-12-20  
Spill Record Last Update: 1999-12-20  
Spiller Name: CALLER  
Spiller Company: CARRIER CORP  
Spiller Address: 6500 NEW VENTURE GEAR DR  
Spiller Company: 001  
Contact Name: CALLER  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was  
CM REFERRED TO DIV. OF AIR."  
  
Remarks: "caller reports release to air due to ruptured pipe. pipe has been  
fixed."

**All Materials:**

Site ID: 265489  
Operable Unit ID: 1089795  
Operable Unit: 01  
Material ID: 296561  
Material Code: 0050A  
Material Name: freon  
Case No.: Not reported  
Material FA: Other  
Quantity: 200.00  
Units: L  
Recovered: .00  
Oxygenate: Not reported

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

**ML2473**  
**East**  
**> 1**  
**2.148 mi.**  
**11340 ft.**

**CARLISLE COMPRESSOR CO**  
**CHRYSLER DRIVE**  
**EAST SYRACUSE, NY**

**NY Spills** **S103567164**  
**N/A**

**Site 12 of 40 in cluster ML**

**Relative:**  
**Higher**

**Actual:**  
**404 ft.**

**SPILLS:**

Spill Number/Closed Date: 8804337 / 1988-08-17  
Facility ID: 8804337  
Facility Type: ER  
DER Facility ID: 222780  
Site ID: 273888  
DEC Region: 7  
Spill Cause: Other  
Spill Class: Not reported  
SWIS: 3400  
Spill Date: 1988-08-17  
Investigator: HDWARNER  
Referred To: Not reported  
Reported to Dept: 1988-08-17  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Commercial/Industrial  
Spill Notifier: Responsible Party  
Cleanup Ceased: 1988-08-17  
Cleanup Meets Std: True  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 1988-09-19  
  
Spill Record Last Update: 1988-11-02  
Spiller Name: Not reported  
Spiller Company: NIAGARA MOHAWK  
Spiller Address: 300 ERIE BLVD E  
Spiller Company: 001  
Contact Name: Not reported  
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead\_DEC Field was  
HW 08/17/88: NIAGARA MOHAWK CLEANED UP THE 2-4 GALLONS OF TRANSFORMER  
FLUID WHICH WAS SPILLED. "  
  
Remarks: "RACCOON SHORTED OUT BUSHING CAUSING BUSHING TO BLOW OUT TOP. OIL IS  
CONTAINED AND NI-MO IS CLEANING UP."

**All Materials:**

Site ID: 273888  
Operable Unit ID: 921498  
Operable Unit: 01  
Material ID: 456282  
Material Code: 0017A  
Material Name: PCB oil  
Case No.: Not reported  
Material FA: Petroleum  
Quantity: 2.00  
Units: G  
Recovered: .00  
Oxygenate: Not reported